

	1		2		3	
LOCATION	Veldman 1		Veldman 2		Veldman 3	
LATTITUDE	40 29'12.3N		40 29'12.0N		40 29'30.2N	
LONGTITUDE	104 57'27.5W		104 57'06.3W		104 57'01.7W	
DESCRIPTION	East of entrance gate		Along cr32 on SW fenceline		Along NE fenceline	
USGS GAGE #						
ELE OF BM	4792		4802		4809	
BOTTOM DEPTH						
DATE	READING	WATER ELEV	READING	WATER ELEV	READING	WATER ELEV
11/01/17	13.3	4778.7	9.2	4792.8	7.2	4801.8
01/11/18	14	4778	10.6	4791.4	7.5	4801.5
02/12/18	14	4778	9.6	4792.4	10.8	4798.2
04/04/18	13.67	4778.33	10.2	4791.8	7.17	4801.83
05/12/18	13.7	4778.3	10	4792	7.18	4801.82
06/06/18	13.7	4778.3	10.1	4791.9	7.2	4801.8

Three Bells

	4		5		6	
LOCATION	Veldman 4		Ditullio 1		Ditullio 2	
LATTITUDE	40 29'31.6N		40 29'46.0N		40 29'39.2N	
LONGTITUDE	104 57'28.1W		104 57'35.2W		104 57'51.6W	
DESCRIPTION	Along sewer line east of scale		North of scale house		West of scale towards river	
USGS GAGE #						
ELE OF BM	4813		4818		4813	
BOTTOM DEPTH						
DATE	READING	WATER ELEV	READING	WATER ELEV	READING	WATER ELEV
11/01/17	10.8	4802.2	6.1	4811.9	nr	-
01/11/18	11.7	4801.3	8.4	4809.6	7.4	4805.6
02/12/18	11.3	4801.7	7.6	4810.4	7.2	4805.8
04/04/18	11.2	4801.8	6.8	4811.2	6.9	4806.1
05/12/18	11.2	4801.8	6.5	4811.5	6.7	4806.3
06/06/18	11.1	4801.9	7	4811	6.5	4806.5

	7		8		9	
LOCATION	Ditullio 3		Ditullio 4		Ditullio 5	
LATTITUDE	40 29'39.2N		40 29'54.4N		40 30'04.2N	
LONGTITUDE	104 58'19.6W		104 58'20.0W		104 58'18.6W	
DESCRIPTION	On west side of river along west fence					
USGS GAGE #						
ELE OF BM	4814		4819		4817	
BOTTOM DEPTH						
DATE	READING	WATER ELEV	READING	WATER ELEV	READING	WATER ELEV
11/01/17	6.8	4807.2	6.3	4812.7	nr	-
01/11/18	14.6	4799.4	14.6	4804.4	5.9	4811.1
02/12/18	14.4	4799.6	14.6	4804.4	5.9	4811.1
04/04/18	14.4	4799.6	14.24	4804.76	5.8	4811.2
05/12/18	14.36	4799.64	14.4	4804.6	5.9	4811.1
06/06/18	14.2	4799.8	14.6	4804.4	6	4811