

APPENDIX E – SOIL LINER FILL ACCEPTANCE FORMS



	Soil	Liner	Fill	Acceptance Form
--	------	-------	------	-----------------

Client: Cripple Creek			
Project: VLF2 Phase 2	Weather	Sunny	
Project No.: 475.0106.032	Date	: 06/15/2020	
	-		
Area/Location:	Panel (P- 3261 1	2-3277	1
(12.). Lacroscie restance (12. rocky extended annual operations for annual operations for annual operations for annual	Panels P- 3261 1 76856 FE2	anna an	
	and the second sec		11
Items Inspected:	Depth of SLF verified		
nems inspected.	Firm and unyielding Surface	······································	
	No visible low/ponding areas		1
	Free of deleterious materials		
	Free of deleterious materials		
		Construction of the second sec	
Testing Performed:		Survey Completed	
	Moisture/Density Lab Testing		
	Lab Testing - Natural Moisture, Particle		
	Atterberg Limits, Proctor, Specific Gra		
Deficient Items:	None		
	, -		
Remedial Actions:			
SIF Accepted:	YFS 🗸	ุ่งก	
	Harrison Antonio and An		
Comments			
		\$60 YE & THE REAL YEAR OF A CHARGE WITH THE TRANSPORTED AND THE THE TRANSPORT OF A CHARGE WITH THE THE THE THE	
Cimatura			
Signatures	12	W	
Alexa, Piela	the star	Date: ollidana	
NewFields	-pamy"	Date: 06/15/2120	
		Data // Ela	1 .
Tezak	K-V. Hand	Data: 6/15/20	20
	all a willet	Data (lista	nd
CC&V	Hour highers	Date: <u>6/15/20</u>	AU
-		Data / 15 2.	
Tetra Tech		Date: <u>6.15.2</u> c	
		20. 50. South	
Other		Date:	•
14			



Client: Cripple Creek	& Victor Mining Co. Contractor: Tezak	
Project: VLF2 Phase 2		
···	Weather: Sunny Date: 06/16/2020	
Project No.: 475.0106.032	Date. <u>0611612020</u>	
Area/Location:	Pa 14 P 2221 (P-3223	
Area/Location.	Panels P-3271 (P-3277 57,197 F12	
	2//·///	13
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	
Testing Performed:	Nuclear Density Survey Completed	14.10
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:	None	
2		
Remedial Actions:		
SIF Arcented:	VES NO	~
Comments		-
		-
		-
		-
Cignaturas	1	
Signatures		
NewFields	Date: G/16/	20
Newricius	and the second	
Tezak	Data: 6/16/2	20
, czan	- I MA	
CC&V	: Arta Auflell Date: 6/1/2/20	20
		7
Tetra Tech	Date: 6-16	$\overline{0}$
Other	: Date:	
Other		





Client: Cripple Creek	& Victor Mining Co. Contractor: Tezak	
Project: VLF2 Phase 2	Weather: Clear	
Project No.: 475.0106.032	Weather: <u>Clear</u> Date: <u>06/17/2020</u>	
Area/Location:	Panels P-3278/ P-3284	
	20588 FtZ	14
	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	-
Testing Deuteumodu	Nuclear Density Survey Completed	
Testing Performed:	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:	Λ/Λ	
	IVONE	
8		
1		
Remedial Actions:	2	
3		
	· · · · · · · · · · · · · · · · · · ·	
SIF Arrented:	VES NO	
Comments:		
Circulture et		
Signatures:		
NewFields:	Mameh Date: 06/17/2020	•
Newricius.	- Wamen	
Tezaki	K 4), 1000 Date: 6/17/200	20
CC&V	John Stouller Date: 6/17/2020	5
		~
Tetra Tech	Date: 6-17-14	\bigcirc
Other	Date:	
1 2		



Client: Cripple Creek	& Victor Mining Co. Contractor: Tezak	
Project: VLF2 Phase 2	Weather: Sunny	
A CONTRACTOR OF A CONTRACTOR O		Ī
Project No.: 475.0106.032	Date	
Area/Location:	Panels P-32851P-3293	
, a cay cocation.	Panels P-3285 1 P-3293	
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	l
		Ì
		1
Testing Performed:		
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:	None	
Remedial Actions:		
SIF Accepted:	VES V NO	
Comments		
1		
Signatures		
	NG 1	
NewFields	: Ammeh Date: 06/18/2020	
	Bate: 6/18/202	2.51
Tezak	- Lin N. Norky	
CC81	1: John Shiflet Date: 6/18/202	20
CC&V	r: Aufor hufler Date: 6/18/202	
Tetra Tee	Date: (-1820	
Tetra Tetra	"	
Othe	r: Date:	



Client: Cripple Creek	& Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2		Weather: Choudy	
Project No.: 475.0106.032		Date: 06/19/2020	
	-		
Area/Location:	Panels P-32	94/12-3296	
•	Panels P-32	351 F12	-
	······································	20117	
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface	3	
	No visible low/ponding area		
	Free of deleterious material		-
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Testir		
	Lab Testing - Natural Moistu		
	Atterberg Limits, Proctor, S	Specific Gravity, Permeability	
Deficient Items:	Nonp		
Remedial Actions:			
SLF Accepted:	VES X	NO	
Comments:			
			_
Signatures:	1 -		
	1		
NewFields:	"Itme"	Date: 06/19/20	220
	V III V		
Tezak:	ni U.Horst	Date: 6/19/2	2020
	1 cl 10 Al	Alul-	
CC&V:	John Juflell	Date: 6 / 19 / 20	
	VINA		2
Tetra Tech:	A AND	Date: (2
Other		Date:	



Climate Called C			
	k & Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2		Weather: Sunny	
Project No.: 475.0106.03	2	Weather: <u>Sunny</u> Date: 06/20/2020	
Area/Location:	Panels P-3297	IP-3309	and the second se
	46802 42		-
)0		
Items Inspected:	Depth of SLF verified		
125.	Firm and unyielding Surface	9	-
	No visible low/ponding area		-
	Free of deleterious materia		-
		15	-
			-
Testing Performed:	Nuclear Density	Summer Course has a	-
resting renormed.	Moisture/Density Lab Testi	Survey Completed	-
			-
	Lab Testing - Natural Moistu		-
		Specific Gravity, Permeability	
Deficient Items:	None		_
			_
			_
Remedial Actions:			
8			
8			-
SLF Accepted:	YES	NO	
Comments:			
			•
			·
Signatures:			
	An		
NewFields:	Ammahi .	Date: 06/20/2020	
	VIIII	Date. <u>00/2020</u>	
Tezak:	X. D. Heatt	Date: 6 20 2	0
-		Date	-
CC&V:	John Sullel	1/20/20	, I
	A	Date: 6/20/30	
Tetra Tech:	X/ U		20
-	VVC)	Date: <u>6 - 20 2</u>	0
Other:			
		Date:	



Client: Cripple Cree	k & Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2		Weather: Cloudy	
Project No.: 475.0106.03	2	Date: 06/22/2020	
	0		and the second second
Area/Location:	Panels P-33 50080 F	1010-3331	
	50080 F	42	-
		<i>i</i>	-
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface		-
	No visible low/ponding area		_
	Free of deleterious material	ls	
			_
Testing Performed:	and a state of the	Survey Completed	
	Moisture/Density Lab Testir		-
	Lab Testing - Natural Moistu	ure, Particle Size,	
Deficient Items:	A	pecific Gravity, Permeability	
Deficient items:	None		
1			
Remedial Actions:			
Reffection Actions.			
SLF Accepted:	VES 🗸	NO	
	- <u>A</u>		
Comments:			
Signatures:	10 -2		
			1
NewFields:	Manne li-	Date: 06/22/2021	1
Tezak:	7 Mart	Date: $\frac{\partial h/22}{202}$ Date: $\frac{\sqrt{22}}{2}$	0
0001	11.5110.H		
CC&V: 7	John Sheflet	Date: 6/22/202	0
Tetra Tech:	LA V		
retra recu:		Date: <u>(</u>	10
Other:			
		Date:	



.

	k & Victor Mining Co. Contractor: Tezak
Project: VLF2 Phase :	
Project No.: 475.0106.03	2 Date: 06/23/2020
Area/Location:	Panels P-3332/3357
	11-977 517
Items Inspected:	Depth of SLF verified
	Firm and unyielding Surface
	No visible low/ponding areas Free of deleterious materials
	Free of deleterious materials
T	
Testing Performed:	
	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size,
	Atterberg Limits, Proctor, Specific Gravity, Permeability
Deficient Items:	None
Remedial Actions:	
SLF Accepted:	YES V NO
Comments:	
-	
-	
Signatures:	
Signatures:	M /
Naur: 11	
NewFields:	Date: 06/23/2020
Tezak:	Am U. Notal Date: 6 23 2020
CC&V:	John Suflet Date: 6/23/2020
4	
Tetra Tech:	Date: 6.23.20
Other:	Date:

/



		ontractor: Tezak
Project: VLF2 Phase 2		Weather: Cartly cloudy
Project No.: 475.0106.03	2	Date: praling of
Area/Location:	Ponels F-3358	+ + ru P-3364
		22 ftz
	51,00	47 -
Items Inspected	Depth of SLF verified	
items inspected.		
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	
Testing Performed:		Survey Completed
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture,	, Particle Size,
	Atterberg Limits, Proctor, Spec	cific Gravity, Permeability
Deficient Items:	Naal	
Remedial Actions:		
nemedial netions.		
SLF Accepted:	YES	NO
Comments:		
-		
Signatures:	1	
NewFields:	Ame hi	Date: 06/2 9/2027
Tezak:	X William	Date: 3/29/20
-		<u>vjvvjrv</u>
CC&V:	John Shiflet	Date: <u>6/29/202</u> 0
Tetra Tech:	y ~ L	Date: 679-20
Other:		Date:



	k & Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2		Weather: Windy/ Cloudy	
Project No.: 475.0106.03	2	Date: 6/30/2020	
Area/Location	Panel P-3365)	
	5580 F+2		
Items Inspected:	: Depth of SLF verified		
	Firm and unyielding Surface		
	No visible low/ponding area		
	Free of deleterious materia		
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Testir		
	Lab Testing - Natural Moistu		
		pecific Gravity, Permeability	
Deficient Items:	. 10.08		1178-1179-1179-1179-1179-1179-1179-1179-
Remedial Actions:			
nemedial Actions.			
SLF Accepted:	NEC. 1		
oti Accepteu.	YES	NO	
Comments:			
connents.			
,			
6			
Signatures:	2		
	N-		
NewFields:	Ahm ohi	Date: <u>06/30/2020</u>	
-	1111	001301X0X0	
Tezak:	high hand	Date: $\left(\frac{1}{30} \right)_{20}$	
1	10 00 11		
CC&V:	John Shiflet	Date: 6/30/2028	
	VIANA	Statement of the second s	
Tetra Tech		Date: 6 30 -20	
Other:		Date:	
		1	



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak	1
Project: VLF2 Phase 2	***************************************		
Project No.: 475.0106.03	2	Date: 7/1/2020	
- //	0 12 0 30		
Area/Location:		66/p-3372	
	38,97	3 F4 2	
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface		
8	No visible low/ponding area		
	Free of deleterious materia	ls	
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Testi	ng	
	Lab Testing - Natural Moist	ure, Particle Size,	
	Atterberg Limits, Proctor, S	Specific Gravity, Permeability	
Deficient Items:	None		
	f States and a state of the sta		
Remedial Actions:			
	an a		
SLF Accepted:	YES	NO	
Ser Accepted.			
Comments:		na di che anno 19 a 19	
comments.			
Signatures:	N.		
	is i	/. /.	
NewFields:	Famer	Date: 7/1/2020	
	VILLE	-1.120	
Tezak:	K-W, Nosp	Date: 7/1/20	
	A STILL		
CC&V:	John hefun	Date: 7/// 2020	
	HTH		
Tetra Tech:	St CO	Date: 7.1.20	
Other:		Date:	



Client: Cripple Cree	k & Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2	2	Weather: Sunny	
Project No.: 475.0106.03	2	Date: 07/02/2020	
	<u>^</u>	- Charle & Color and Construction	
Area/Location:	Panels P-33	73 to P-3378	NEW HOLD CONTRACT OF CONTRACT OF CONTRACT
	33	460 F12	
	.,		
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surfac		
	No visible low/ponding are		
	Free of deleterious materia	als	
Testing Performed:		Survey Completed	
	Moisture/Density Lab Testi		
	Lab Testing - Natural Moist		
Deficient Items:		Specific Gravity, Permeability	
Dencient items:			
Remedial Actions:			
	/		
SLF Accepted:	YES V	NO	
Comments:			
C:			
Signatures:	M		
NewFields:	10 01-	Data walasia	
Newrields.	Akmin	Date: <u>07/02/20 20</u>	
Tezak:	KULSA	Date: 7/2/20	
	A 11		
CC&V:	John Stullet	Date: T/2/20	
	(1)A	<u> </u>	
Tetra Tech:	A Di	Date: 7 2 20	
Other:		Date:	



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak	ny na haran na hara na kata ya mana na banda na haran na kata na haran da mana da mana da mana da mana da mana	
Project: VLF2 Phase 2		Weather: Sun	ny	
Project No.: 475.0106.032 Date: 07/03/2020		3/2020		
			,	
Area/Location:	Panels P-3=	379 to P-3	384	
	33,6	184 F12 -		
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surfac	ce		
	No visible low/ponding are	A REAL PROPERTY AND A REAL PROPERTY A REAL PROPERTY A REAL PROPERTY AND A REAL PROPERTY A REAL		
	Free of deleterious materi	als		
Testing Performed:		***	ompleted	
	Moisture/Density Lab Test			
	Lab Testing - Natural Mois		1 122	
	Atterberg Limits, Proctor,			
Deficient Items:	None			
	an a			
Remedial Actions:				
Remedial Actions.				
SLF Accepted:	YES		NO	
l on Acception		-		2
Comments:	an a	899, 8 4 5 5 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	n an	
			40. Prod 1 i maren e al al antica de la calencia d	

Signatures:	1 7			
	P			
NewFields:	fameli	D	ate: 07/03/2020	
			-/-	
Tezak:	An W. Norg	<u>)</u> D	ate: 7/3/20	
	1. <1.10.1		10/0000	
CCRV:	John mylla	5	ate: 1/3/2020	
	$\left \right $	_	72.20	
Tetra Tech:	You	D	ate: 7.3.20	
			<u>ata</u> .	
Other:		D	ate:	
3				



Client: Cripple Creel	& Victor Mining Co	Contractor: Tezak	
Project: VLF2 Phase 2			
Project No.: 475.0106.033		Weather: Partly Cloudy Date: 07/07/2020	
Project No., 475.0100.05.		Date. 07/01/ X020	
Area/Location:	P. I. O. BRAST	0 7780	
Area/Location:	Yanels P-3385/ 29588	<u>r-3287</u>	.
	29588	Ft2	
là sur a lun qui a atta al s	Depth of SLF verified	an ng tang ang tang tang tang tang tang	
i items inspected:			. 1
	Firm and unyielding Surface		
	No visible low/ponding areas		
	Free of deleterious materials		
			-
Testing Performed:	######################################	Survey Completed	
	Moisture/Density Lab Testing		
	Lab Testing - Natural Moistur		
	Atterberg Limits, Proctor, Spo	ecific Gravity, Permeability	
Deficient Items:	None		
Remedial Actions:			5 m -
			-
SLF Accepted:	YES	NO	-
	n an	an a	
Comments:			
			-
			-
			-
Signatures	NO		
	AND I.		
NewFields:	Ammely	Date: <u>07/07/202</u>	D
	KILLET		
Tezak:	Juw. Nog	Date: <u>7/7/20</u>	2
CCRV	1625/ 11.1		16
CCAV	you myun	Uate: <u>7/1/20</u>	20
	M CH-		,
Tetra Tech:		Date: / 7. 7	U U
01		Deter	
Other:		Date:	-



Client: Cripple Cree	& Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2		Weather: Clear	
Project No.: 475.0106.032		Date: 07/08/2020	1

Area/Location:	Panels 17-3	339018-3396	
•	447	390/P-3396	
Items Inspected:	Depth of SLF verified	na kana kana kana kana kana kana kana k	
	Firm and unyielding Surfa	ce	
	No visible low/ponding ar		
	Free of deleterious mater		
	territation provide the annual of the second of the second second second second second second second second se		
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Tes		
	Lab Testing - Natural Mois	sture, Particle Size,	
	Atterberg Limits, Proctor	, Specific Gravity, Permeability	
Deficient Items:	None		
			1
Remedial Actions:			
SLF Accepted:	YES V	NO	
	all a succession of the		
Comments:	10 10 10 10 10 10 10 10 10 10 10 10 10 1		
Signatures:	\mathcal{D}		
	AS 1.		
NewFields:	Amen	Date: 07/08/2020	
· · · · ·		1	
Tezak:	15 m. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	Date: 782	0
CCR.V:	Jacos Ilit	Bate: 7/8/20	מרז
CORV.	Jour mon		id v
Tetra Tech:	V.	Datas 7 () as	
		Date: $7 \cdot 8 \cdot 7$	
Other:		Date:	
Utier.		<i>Date</i>	



Client: Cripple Crool	& Victor Mining Co. Contractor: Tezak	
Project: VLF2 Phase 2		
	CIEU	
Project No.: 475.0106.03	2 Date: 07/09/2020	
-		
Area/Location:	<u>Panels P-3397 P-3404</u> 22543 Ft ²	
	22543 Ft ²	
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	
		-
Testing Performed:	Nuclear Density Survey Completed	-
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:	Nane	
		•
Remedial Actions:		
		2
		-
SIF Accented:	VES 1/ NO	
Comments:		
Signatures:	ha	
NewFields:	Date: 07/09/202	
angeste operation of the second secon	Trancia 01104/202	ed of the second s
Tezak:	Jupping Date: 7/9	120
CC&.V+	- Ada Suflets Data 7/9/202	0
Tetra Tech:	Date: 7.9.20	
Other:	Date:	



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak	
Proiect: VLF2 Phase 2		Weather: Clear	
Project No.: 475.0106.03			
Area/Location:	Paneds P-34	051P-3424	
	69,92	9 612	
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface		
	No visible low/ponding area		
5	Free of deleterious material	ls	
Testing Derformed	Nuclear Density	Summer Consultated	
Testing Performed:	Moisture/Density Lab Testir	Survey Completed	
	Lab Testing - Natural Moistu		
		pecific Gravity, Permeability	
Deficient Items:	Nau		
Remedial Actions:			
SIF Accented	ALC N	NO	
Comments:			
comments.			

	ARMA MAALAANA YA MUTUMU II II WAARMA MAANA MA	NA MARANANA ANA MANANA MANA	
Signatures:	h í		
	AK		
NewFields:	Mamelia	Date: 07/10/2020	
	X.D.Mst	/	
Tezak:	1 A MA	Date: <u>7/10 20</u>	
CC8.V.	John She Lill	Date: 7/10/200	00
Tetra Tech.	K	Date: 7.10.20	,
C	0		
Other:		Date:	



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak	
Project: VLF2 Phase 2	and the second	Weather: <u>Clcar</u>	
Project No.: 475.0106.03		Date: 07/11/2	120
	9,99,99,99,99,99,99,99,99,99,99,99,99,9		<i>v</i> – <i>v</i>
Area/Location:	Panels P-34	2518-3427	alan Manaka ini kataka manaka man
	255	25/P-3427 29 FEZ	
	n in the second production of the second in the second second second second second second second second second	and on the second s	antine ef i nem en neu Neuer Bandenen de Your nyezh
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface	2	
	No visible low/ponding are		
	Free of deleterious materia	ls	
Testing Performed:		Survey Comple	ted
	Moisture/Density Lab Testi		
	Lab Testing - Natural Moist		
		Specific Gravity, Permeability	
Deficient Items:	None		The state of the state of the state
Remedial Actions:			
Refficulta Actions.			
SIF Accepted:	VES	NO	
		40000-0	and an in the state of the
Comments:			
			a Sana Sana an
		a an an a start water and the start water an	
an an Anna an Anna an Anna an Anna ann ann			
Signatures:	ha		
	1.		
NewFields:	Ammeli	Date: 07	1/11/2020
T l			-11
Tezak:	Am W MODE	Date:	7/11/20
CC8.V.	Aohn Shillet	Date	
			1 July
Tetra Tech:	Les DU	Date	7.11.20
Other:		Date:	
			l e



Client: Cripple Cree	& Victor Mining Co. Contractor: Tezak
Project: VLF2 Phase 2	
Project No.: 475.0106.03	
	Date. 0111312020
Area/Location:	Panels P-34281 P-3432
	Panels P-3428/P-3432 40 4209 F12
2	70 7509 FLE
items inspected:	Depth of SLF verified
	Firm and unyielding Surface
	No visible low/ponding areas
	Free of deleterious materials
Testing Performed:	Nuclear Density Survey Completed
	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size,
	Atterberg Limits, Proctor, Specific Gravity, Permeability
Deficient Items:	None
Remedial Actions:	
SIF Accepted:	VFS NO
Comments:	
Signatures:	
Nouthalder	No 1
NewFields:	Date: 07/13/2020
Taralu	K. IIII St
Tezak:	K W Date: 7/13/20
CCR.V.	John Shiffeld Date: 7/13/2620
	John Shiflell 12020
Tetra Tech:	X/2 Data: 7:12.7.
icua icou.	Date: 7.13.20
Other:	Date:



Client: Cripple Cree	& Victor Mining Co. Contractor: Tezak
Project: VLF2 Phase 2	
Project No.: 475.0106.03	
Project No 475.0100.05	2 Date: <u>07/14/2020</u>
Area/Location:	1
Area/Location.	Panels P-3433 to P-3441 47197 FZZ
	47197 FZC
items inspected:	Depth of SLF verified
	Firm and unyielding Surface
	No visible low/ponding areas
	Free of deleterious materials
Testing Performed:	
	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size,
	Atterberg Limits, Proctor, Specific Gravity, Permeability
Deficient Items:	None
Remedial Actions:	
SIF Accepted:	YESNO
Comments:	
Signatures:	
	V
NewFields	Date: 07/14/2020
	VIII III
Tezak:	Kik Hozar Date: 7/14/20
Huge - Huge excellence of	
CC&V.	John Shiflet Date: 7/14/2020
Tetra Tech:	Date: 71420
Other:	Date:



Client: Cripple Cree	k & Victor Mining Co. Co	ontractor: Tezak	
Project: VLF2 Phase	2	Weather: Partly Cloudy	
Project No.: 475.0106.03	2	Date: 07/15/2020	
		<u> </u>	
Area/Location	Panel 6 P- 2111	421 1-3447	Nan Anton o Makada da Balla Bang Bang Pad
	Panels 1- 340 10284	$\frac{7}{1642}$ $\frac{7}{7}$ $\frac{7}{7}$ $\frac{7}{7}$	
	10207		
Items Inspected	Depth of SLF verified		
	Firm and unyielding Surface		
	No visible low/ponding areas		
	Free of deleterious materials	an a	
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Testing		
	Lab Testing - Natural Moisture		
	Atterberg Limits, Proctor, Spe	ecific Gravity, Permeability	
Deficient Items:	$\Lambda (2)$		
Remedial Actions:			
			i
	/		
SIF Accepted:	YFS V	MO	i
Comments:			
			Í
			i
nan fan hen aleman a beren al bereken an de sekeren en er en stere keite beste bester er besternte besternte s			
Signatures:	h_{1}		
	1.		
NewFields:	4 Komen	Date: 07/15/2020	
	VIII		
Tezak:	Smil How	Date: 7/15/20	
	1 OKI MA	1 1	
CC 8.V.	John Xullell	Date _ 7/15/2020	
Taken Table		->	
Tetra Tech:	Xa	Date: 7.15-20	
Oth		Pagenti and	
Other:		Date:	



Soil Liner	· Fill	Acceptance	Form
------------	--------	------------	------

.

.

Client: Cripple Creek 8	& Victor Mining Co. Contractor: Tezak
Project: VLF2 Phase 2	Weather: Partly Cloudy Date: 67/1672020
Project No.: 475.0106.032	Date: 67/16/2020
Project No 475.0100.052	
Area/Location:	Panels P-3448 P-3455 20392 FLZ
	Depth of SLF verified
1	Firm and unyielding Surface
	No visible low/ponding areas
-	Free of deleterious materials
-	
Testing Performed:	Nuclear Density Survey Completed
	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size, Atterberg Limits, Proctor, Specific Gravity, Permeability
Deficient Items:	None
9	
Remedial Actions:	
Kemeulai Actions.	
	NO
SIF Accepted	AEC NUD
Comments	
Signatures	
	: Date: 07/16/2020
NewFields	- saturage
Tezak	: <u>Tu /hant</u> Date: <u>7/16/20</u>
CC&\	. John Shylett 12020
Tetra Jed	Date: 7.16.20
	Date:
Othe	r: Date



Soil Liner	Fill	Acceptance	Form
------------	------	------------	------

		Contractory Torok	1
Client: Cripple Creek	& Victor Mining Co.	Contractor: Tezak	1
Proiect: VLF2 Phase 2			udy
Project No.: 475.0106.032		Date: 67/17/2020	
Area/Location:	Day 11 0 71	UN 10 211/1	
Area/Location.	Panels P-34 2230	+56/P-3461	
	·2230	12 Pt-	
items inspected:	Depth of SLF verified		
	Firm and unyielding Surface		
-	No visible low/ponding area		
-	Free of deleterious materials		
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Testin		
	Lab Testing - Natural Moistu		
		pecific Gravity, Permeability	
Deficient Items:	NOhr		
Remedial Actions:			
,			
SIF Accepted:	YES 1	NO	
	Manual and the American Street and an and an and a set		
Comments:			
A COME 21/22/4845065 CLARKERSON TO A COLOR			
ĺ			
		· · · · · · · · · · · · · · · · · · ·	
			alan menang yang
Signatures	10 0		
	X . 1.	Data: a. //	2.42.4
NewFields	1 men	Date. <u>07/171</u>	1020
Tezak	THA	Date: <u>07/17/</u> Date: <u>7/1</u>	4/20
rezak	1 - 1 purch	/	1
CC&V	. John Shillet	Date: 7/11	2020
Tetra Tech		Date: 7-17	20
	Ve		
Other		Date:	

Soll Liner	Fill Acceptance Form
Client: Cripple Creek & Victor Mining Co.	Contractor: Tezak
Project: VLF2 Phase 2	Weather: Partly Cloudy
Project No.: 475.0106.032	Date: 07/18/2020
Area/Location: Papels P-2	3462 to P-3466 9589 Ft2
	9589 Ft2
Items Inspected: Depth of SLF verified	
Firm and unyielding Su	urface
No visible low/ponding	g areas
Free of deleterious ma	aterials
Testing Performed: Nuclear Density	Survey Completed
Moisture/Density Lab	Testing
Lab Testing - Natural I	Moisture, Particle Size,
Atterberg Limits, Proc	ctor, Specific Gravity, Permeability
Deficient Items: None	
f-t-Vint Comment	
Remedial Actions:	
SLE Accented: YES	NO
· · · · · · · · · · · · · · · · · · ·	
Comments:	
Signatures:	
NewFields: Abommely	Date: 07/18/2020
A Martine -	
Tezak:	Date: 7/18/20
MRN. John Shifle	Date 7/18/2020
Tetra Tech:	Date: 7-18-20
Other:	Date:

Soil Liner Fill Acceptance Form _____NewFields



			Tweetown water and the second s
Client: Cripple Creek		ctor: Tezak	
Project: VLF2 Phase 2	Wea	ther: <u>Clear</u>	
Project No.: 475.0106.032		Date: 07/20/2020	
		,	
Area/Location:	Panels P-13467 1	0-3476	
	48756 FI	2	
	1 - 1 - 0 - 77		
Items Inspected:	Depth of SLF verified		
	Firm and unyielding Surface		
	No visible low/ponding areas		
	Free of deleterious materials		
			Ĩ
Testing Performed:	Nuclear Density	Survey Completed	
0	Moisture/Density Lab Testing	energy in the second	
	Lab Testing - Natural Moisture, Pa	rticle Size.	
	Atterberg Limits, Proctor, Specific		
Deficient Items:	A.A.		
Dencient nems.	J.V.VIE.		
8			
Remedial Actions:			
Remedial Actions.			
e			
SLF Accepted:	YES V	NO	
Sur Accepteo:		NO	
Causuasta			
Comments:			
			() () () () () () () () () ()
8			
Signatures:	h /		
	A		
NewFields;	Hommeti	Date: <u>07/20/2020</u> Date: <u>7/20/20</u>	
Tezak:	1 punt.	Date:/2/2/2	0
	10 <1 11 H		
CCRV:	John Mixlell	Date: 7/20/20	20
	the free		
Tetra Tech:	All the	Date: 7/20/20	2
Other:		Date:	



Client: Cripple Creel	& Victor Mining Co. Contractor: Tezak			
Proiect: VLF2 Phase 2				
Project No.: 475.0106.032				
Area/Location:	Panels P-3477 to P-3483			
	27672 H2			
	•			
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surface			
	No visible low/ponding areas			
	Free of deleterious materials			
Testing Performed:	Nuclear Density Survey Completed			
resting renormed.	Moisture/Density Lab Testing			
	Lab Testing - Natural Moisture, Particle Size,			
	Atterberg Limits, Proctor, Specific Gravity, Permeability			
Deficient Items:				
Remedial Actions:				
SIF Accepted	VFS V			
Comments:				
comments.				
	The second s			
Signatures:	10			
NewFields:	Date: 07/21/2020			
Tezak:	Date: 7/21/20			
CC&V-	1 - 2 Sh. 1 2020			
	Adua Shifill Date 1/01/2000			
Tetra Tech:	Date: 7.21.20			
Other:	Date:			



Client: Cripple Creek	2 Victor Mining Co	Contractor: Tezak	
Project: VLF2 Phase 2			
		- diffe - due -	i
Project No.: 475.0106.032		Date: 07/22/2020	
	0 11 0 240	. 0.2002	
Area/Location:	Panels P-3484 49727	to 1-3492	
	49.727	7-FE	
items inspected:	Depth of SLF verified		
	Firm and unyielding Surface		
	No visible low/ponding areas		
	Free of deleterious materials	5	
			1
Testing Performed:		Survey Completed	
	Moisture/Density Lab Testin		
	Lab Testing - Natural Moistu		
	Atterberg Limits, Proctor, Sp	becific Gravity, Permeability	
Deficient Items:	None		
Remedial Actions:			
	sector 1	MO	
SIF Accepted:	ALC V		
Comments			
	a second and the second second states in the second states and the second states are a second se		
	an wara church na na mana an		
Cimatura			
Signatures	h a		
NewFields	the phi	Date: 07/22/20 20	
NewFields	John for	Bute. <u>0 // 24/ 24</u>	
Tezak	TU	Date: 7/12/20	
тезак	- / mint		
CCRV	John St. Llok	Date 7/22/2620	
	(The suggest		
Tetra Tech	HO V	Date: 7 72.20	
i cua i con			
Other		Date:	
Suici			



Client: Cripple Creek	& Victor Mining Co.	Contractor: Tezak		
Project: VLF2 Phase 2		Weather: Partly Cloudy		
		Date: 07/23/2020		
Area/Location:	Parale P 211	$n + 0 = r n \mu$	ĺ	
A cay Location.	Panels P-340 623	10 10 1- 3507		
	623	362 FE	1	
ltowno Imanootoolu	Depth of SLF verified			
items inspecteu:			1	
	Firm and unyielding Surface	-		
	No visible low/ponding areas			
	Free of deleterious materials	5		
Testing Performed:		Survey Completed		
	Moisture/Density Lab Testin			
	Lab Testing - Natural Moistu			
	Atterberg Limits, Proctor, Sp	pecific Gravity, Permeability		
Deficient Items:	None			
2	•			
Remedial Actions:				
	/			
SLF Accepted	YES V	MA		
Comments:				
			8	
i				
i i				

Signatures	ar o en esta a de la caladada de la calada de encolector de la calada da calada de la calada de la calada de c			
Signatures.	\mathcal{D}			
NewFields	and the	Date: 67/23/2620		
incurrents.	TRome			
Tezaka	T PALA	Date: 7/23/2/	1	
Tuzak.	1 port			
CCRV	Some & The fett	Date: 7/23/200	A()	
	1 THE AUGU		n	
Tetra Tech	WS DI	Date: 773-7	70	
ietta rech			, -	
Other		Date:		
otiler				



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak			
Project: VLF2 Phase 2		Weather: Partly Closudy			
Project No.: 475.0106.032		Date: 07/24/2020			
Area/Location:	Panels P	3505 [P-3514 B875 Ft2			
items inspected:	Depth of SLF verified				
	Firm and unyielding Surface	e			
	No visible low/ponding are	as			
	Free of deleterious materia	ree of deleterious materials			
Testing Performed:	Nuclear Density	Survey Completed			
	Moisture/Density Lab Testi	ing			
	Lab Testing - Natural Moist				
	Atterberg Limits, Proctor, S	Specific Gravity, Permeability			
Deficient Items:	None				
Remedial Actions:					
	/				
SIF Accented	VES 1	NO			
·	אייינא איז איין איין איין איין איין איין איין				
Comments					
	and a second	and the cost of the second test test to a second state of the second secon			
5 5 5 5					
Signatures					
	R/				
NewFields	Arameh.	Date: 67/24/202	20		
	19 IIII				
Tezak	Kin W. Wool	Date: 7/24/20			
CC&V	Som Shiklet	Date: 7/24/2020)		
	TR TI				
Tetra Tech	4.20	Date: 72420)		
0	10				
Other	V	Date:			



Client: Cripple Creel	& Victor Mining Co	Contractor: Tezak		
Project: VLF2 Phase 2		Weather: <u>Cloudy</u>		
Project No.: 475.0106.032		Date: 07/30/202	ח	
	-	011301 200	0	
Area/Location:	Panels P 55538	3515 to P-3524 Ft2		
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surface	е		
	No visible low/ponding are	as		
	Free of deleterious materia	ils		
Testing Performed:	Nuclear Density	Survey Completed		
	Moisture/Density Lab Testi	ng		
	Lab Testing - Natural Moist	ure, Particle Size,		
		Specific Gravity, Permeability		
Deficient Items:	None			
Remedial Actions:				
SIF Accepted:	VES	NO	NA OR DESIGNATION OF THE OWNER	
Comments:				
			(eserve)	
			215-14.55 (11)-14-15 (11)-14-14 (11)-14-14-14-14-14-14-14-14-14-14-14-14-14-	
2 	1999 1999 1999 1999 1999 1999 1999 199			
Signatures:	/	7		
	$\Delta I_{1} \Delta I_{1}$		20 2020	
NewFields:		Date: [30-2020 5-2020	
·			2	
Tezak:	201	Date:	<u>x-2020</u>	
3	1 SI Ilat		10000	
CC&V-	John Sufell	Date: 1/30	12000	
	JAS II		7.7	
Tetra Tech:	WACY_	Date: 7-3	0.10	
	-			
Other:		Date:	<i>c</i>	
2. 2.				



Client: Cripple Creel	& Victor Mining Co. Contractor: Tezak				
Project: VLF2 Phase 2		/			
Project No.: 475.0106.03	97709 C 200	dy			
110ject 10 475.0100.05.	- <u>011311'4620</u>				
Area/Location:	Panels P-3525/12-3528 22354FE2				
Items Inspected:	Depth of SLF verified				
	Firm and unyielding Surface	-			
	No visible low/ponding areas	-			
	Free of deleterious materials				
		-			
		er me			
Testing Performed:	Nuclear Density Survey Completed				
	Moisture/Density Lab Testing				
	Lab Testing - Natural Moisture, Particle Size,				
	Atterberg Limits, Proctor, Specific Gravity, Permeability	-			
Deficient Items:	None				
Remedial Actions:					
	1				
SIF Accepted	YFSNO				
Comments:					
nen kan kan kan manan kana kan ang kana kan kan kan kan kan kan kan kan ka					
Signatures:					
NewFields:	Date: 731/20 Date: 731/20	20			
Tezak:	Date: 73/20	20			
	- 1/10 St. Math	10			
ርር ጸ.ህ•	John Muflell Date: 7/31/202				
Tatas T		、 、			
Tetra Tech:	Date: 7·31·20				
Oth					
Other:	Date:	- 1			



Client: Cripple Creek	& Victor Mining Co. Con	itractor: Tezak		
Project: VLF2 Phase 2		leather: Faily Cloudy		
Project No.: 475.0106.032				
Area/Location:	Panels P-3529	1P-3536		
	<u>anels P-3529</u> 44460Ft	2		
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surface			
	No visible low/ponding areas			
	Free of deleterious materials			
			l l	
Testing Performed:		Survey Completed		
	Moisture/Density Lab Testing			
	Lab Testing - Natural Moisture,			
	Atterberg Limits, Proctor, Spec			
Deficient Items:	None			
Remedial Actions:				
Remedial Actions.				
SIF Accepted:	AEC N	MC		
Comments:				
Signatures:	co r			
Alternative Alternative Alternative	they I			
NewFields	yamen.	Date: 08/01/2023	9	
			1	
Tezak:	1 www. worst	Date: <u>8/1/20</u>		
CCR.V-	del Sh. Klik	Date: 8/1/202	א מ	
	(John Jory un of 1/0/000			
Tetra Tech:	Date: 8.1.20			
ieua rech				
Other		Date:		
	<u></u>			



Soil	Liner	Fill	Acceptance	Form
------	-------	------	------------	------

Cliente Criente Creat	
Project: VLF2 Phase 2	K & Victor Mining Co. Contractor: Tezak Weather: Poul In Claudy
Project No.: 475.0106.03	
Project No 475.0100.05	Date. 08105/2020
Area/Location:	Panels P-3537/ P-3553 75934Ft2 76541Ft2
Items Inspected:	Depth of SLF verified
	Firm and unyielding Surface
	No visible low/ponding areas
	Free of deleterious materials
Testing Performed:	
	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size,
Deficient Items:	Atterberg Limits, Proctor, Specific Gravity, Permeability
Dencient items:	Ivone
Remedial Actions:	
SIF Accented	VES NO
Comments	
Signatures	h
	AS 1
NewFields	Date: 03/05/2020
Tanala	Date: 8/5/20
Tezak	Am Norton Date. op/20
CC&V	And Suflet noto: 5/5/20
Tetra Tech	Date: 8.5.20
Other	: Date:



Client: Cripple Creel	& Victor Mining Co.	Contractor: Tezak			
Project: VLF2 Phase 2 Weather: Partly Cloud					
Project No.: 475.0106.03					
Area/Location:	Area/Location: <u>Panels P-3554/P-3567</u> 57763 Ft2				
	577	63 EHZ			
1		Se an Se an an Anna Canada an			
Items Inspected:	Depth of SLF verified		D CYCHANAL MED ER MANNA COMMUNA		
Firm and unyielding Surface					
	No visible low/ponding areas				
	Free of deleterious materia	als			
Testing Performed:		Survey Completed			
	Moisture/Density Lab Test				
	Lab Testing - Natural Moist				
	and the second secon	Specific Gravity, Permeability			
Deficient Items:	None				
Remedial Actions:					
			-		
SLF Accepted:	YES	NO			
		No. Here and the second s	Ĩ		
Comments					
i i			ĺ		
Ì					
Signatures	h.				
	AX				
NewFields	Ammeli	Date: 08/06/2020			
	9	Date: 08 06	2		
Tezak	$\Lambda \leq =$	Date: 05 06	4020		
	Ila se Ila	Date: 8/6/200	24		
CC&.V	gong myll		u)		
Tatus Tab	VXV	Date: 8 6-20			
Tetra Tech	-YO	Date: 0 6-00			
Other		Date:			
Other					



Client: Cripple Creek	& Victor Mining Co	ontractor: Tezak			
Project: VLF2 Phase 2					
Project: VLF2 Phase 2 Weather: Clear Project No.: 475.0106.032 Date: 08/07/2020					
Bate. <u>0810112020</u>					
Area/Location:	Area/Location: <u>Panels P-35681 P-3581</u> 49931 Ft2				
A cay cocation.	runels [- 2568]	F-2201	•		
	49931	FCE			
items inspected:	Depth of SLE verified				
i items inspecteu.	Items Inspected: Depth of SLF verified Firm and unyielding Surface				
0	No visible low/ponding areas				
	Free of deleterious materials				
9	Thee of deletenous materials		-		
Testing Performed:	Nuclear Density	Survey Completed	-		
resting renormed.	Moisture/Density Lab Testing	Survey completed	-		
	Lab Testing - Natural Moisture	Particle Size	-		
	Atterberg Limits, Proctor, Spe		•		
Deficient Items:	0/00-10				
Dentient tierns.	100010		-		
			-		
			-		
Remedial Actions:					
Remedial Actions.			•		
			-		
-	/		-		
SLF Accented:	YES 1	NO			
			**		
Comments:					
ĺ					
			-		
	ananing mendepantan inter a nan an				
Signatures:			anten kan takan Makemba Aran manu takan kan tu intera anta yana		
	n				
NewFields:	A am chi	Date: 08/07/2	20		
* a - into interest and interested all COMERCED OF a - into interest and a second COMERCED OF OF		Date: 08/07/20 Date: 08/07/20			
Tezak:		Date:08076 7	020		
	al al ATT	(_ /			
CCR.V.	John Shifter	Date: 8/7/20	<u>d</u> 6		
	1 R L				
Tetra Tech:	W DE	Date: 8-7-2	2		
Other:		Date:	-		





Client: Cripple Creek	& Victor Mining Co. Contractor: Tezak			
Project: VLF2 Phase 2	Weighter Read	1.0		
		y		
Project No.: 475.0106.032	Date: 08/08/2020			
nan na anna ann an ann an ann an ann an				
Area/Location:	Panels P-35821 P-3606 69027 Ft2			
	69027 Ft2	1		
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surface			
24	No visible low/ponding areas			
	Free of deleterious materials	I		
·				
		u H		
Testing Performed:	Nuclear Density Survey Completed	1		
	Moisture/Density Lab Testing			
	Lab Testing - Natural Moisture, Particle Size,			
	Atterberg Limits, Proctor, Specific Gravity, Permeability			
Deficient Items:	None			
		i		
Remedial Actions:				
		1		
		1		
SIF Accented:	VES 🗸 NO	li l		
Reporter Republication Constraints Reporter Reporter	NOTIONAL AND			
Comments:				
oomnencor				
		ĵ.		
Signatures:				
1 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100	A			
NewFields:	Date: 08/08/202	D		
	Date: 08/08/202 Date: 08/08/202	/		
Tezak:	Date: 08/08/2	2020		
	dona Suffit Date: 8/8/20	12.0		
CCR.V.	Arm Mifled Date: 0/8/20	00		
	IN IL			
Tetra Tech:	Date: 8.8.20			
	X			
Other:	Date:			

Soil	Liner	Fill	Acceptance	Form
------	-------	------	------------	------



Client: Cripple Creek	& Victor Mining Co	Contractor: Tezak	
Project: VLF2 Phase 2	۲٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰۰۰٬۰		1.,
Project No.: 475.0106.032		Weather: Partly Cloud Date: 08/12/2020	y
FIDJECT NO 475.0100.052		Date: 08/12/2020	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
Area/Location:	0. 1.0 2	$c = \pm D = 2/c =$	
Alea/Location.	anels - 20	607 to P-3616- 0 Ft2	
8	LTJ. J.e		
Itoms Inspected:	Depth of SLF verified		
items inspected.	Firm and unyielding Surfac	A	
8	No visible low/ponding are		
1	Free of deleterious materia		
	Thee of deleterious materia	115 	
	aya, anja ya fatan wapanya kupanya kupanya kutoka nga katoka nga mana kutoka pananaka katoka kutoka na katoka n		
Testing Performed:	Nuclear Density	Survey Completed	
resting renormed.	Moisture/Density Lab Test		
	Lab Testing - Natural Moist		
	المتكالة المحافظة المواجعة المتناطع والمعالمة والتكافية وتوقيه والمتكافية ومحافظ فيتجوج والمتكاف والمحافظ والمحافظ وال	Specific Gravity, Permeability	
Deficient Items:			
Dencient items.	<u></u>		

Remedial Actions:			
Remedial Actions.	pe processi yan a manana kana kana kana na yan kana kana ka		
	/		
SIF Accented	VEG	0173	
WE Arrenten	Ϋ́ () ² ² ²	B 2 B 6 2	
Comments:			
comments.			

Signatures:			19.19.19.19.19.19.19.19.19.19.19.19.19.1
Jighardies.	b		
NewFields:	Manna 1.	Date: 08/12/2020	
ivewrielus.	Herringen	0 <u>000000000000000000000000000000</u>	
Tezak:	T Ph P.	Date: <u>8/12/20</u>	
TGZGK.	14 Junit		
CCR.V-	Stall Shell I	Date: 8/12/202	0
	(THE THE		
Tetra Tech:	VA N	Date: & 12-20	S
Other:		Date:	



Exercise States and St	& Victor Mining Co. Contractor: Tezak			
Proiect: VLF2 Phase 2	Weather: Parlly Cloudy			
Project No.: 475.0106.032	Date: 08/13/2020			
Area/Location:	Area/Location: <u>Panels P-3617 to P-3629</u> 36025 Ft ²			
	26025512			
	and a second			
items inspected:	Depth of SLF verified			
	Firm and unyielding Surface			
	No visible low/ponding areas			
	Free of deleterious materials			
	Free of deletenous materials			
Testing Performed:				
	Moisture/Density Lab Testing			
	Lab Testing - Natural Moisture, Particle Size,			
	Atterberg Limits, Proctor, Specific Gravity, Permeability			
Deficient Items:	None			
Remedial Actions:				
SIF Accented:	YES NO			
6 192 8 - 2-95 1 6-4712 (-1851				
Comments:				
Signatures:				
	h			
NewFields:	Date: 08/13/2020			
	ANTHON ON DIGITORICA			
Tezak:	Kin Wittens Date: 8/13/20			
Tezdk.	Nun Vinteren Dave. 012/20			
	the Shilling still 2016			
er xev.	John Myllin Date: 8/10/2020			
	Date: 8.13.20			
Tetra Tech	Date: 8.13.20			
Other:	Date:			



Client: Cripple Creek	& Victor Mining Co. Contractor: Tezak	1		
		/		
Project: VLF2 Phase 2 Weather: Clear Project No.: 475.0106.032 Date: 08/14/2020		ear		
Project No., 475.0100.05.	bate. <u>8811412620</u>			
Area/Location: Panels P-36301 P-3646				
,	Panels P-36301 P-3 49035			
	and the second	and and a second s		
Items Inspected:	Depth of SLF verified			
	Firm and unyielding Surface			
	No visible low/ponding areas			
	ree of deleterious materials			
Testing Performed:	Nuclear Density Survey	Completed		
	Moisture/Density Lab Testing			
	Lab Testing - Natural Moisture, Particle Size,			
	Atterberg Limits, Proctor, Specific Gravity, Perr	neability		
Deficient Items:	Mne			
Remedial Actions:				
CLE Barrata Is	VES	6.17		
SLE Accepted:		M/)		
Comments:				
comments.				
		n sa ann an tha fha ann ann ann an san ann an san ann ann		
Signatures:				
	A i			
NewFields:	Aprimeli	Date: 08/14/2020		
T	-			
Tezak:	1 part	Date: <u>\$/14/20</u>		
CCR.V.	Solo Shillel	Date: 8/14/2016		
(* 1.00)	(10)			
Tetra Tech:	A det	Date: 8.14.20		
Other:		Date:		



Client: Cripple Creel	د & Victor Mining Co. Contractor: Tezak	
Project: VLF2 Phase 2		
Project No.: 475.0106.032	Weather: Sunny 2 Date: 08/15/2020	
Area/Location:	Panels P-3647 / P-3658	
	Panels P-3647 / P-3658 29246 Ft2	
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	
Testing Performed:		
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size, Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:		
Dentient items.	None	
Remedial Actions:		
SIF Accepted:	VES V MO	
Comments:		
		an transmission a long
Signatures:	n a	
NewFields:	AT al'	
Newrielus.	Date: 08/15/2	020
Tezak:	To Par A Date: C/	120
	1 million S/2	120
CCRN	John Sullet Date 8/15/	2020
	1/ 17	
Tetra Tech:	Date: 8-15	25
Other:	Date:	



Enne Constanting the Constanting Street Constanting Street Constanting Street Constanting Street Constanting St	د & Victor Mining Co. Contractor: Tezak
Proiect: VLF2 Phase 2	JAPENY LOUGH
Project No.: 475.0106.03	Date: 08/+7/2020
Area/Location:	Panels P-36591P-3664 14446F2
	14446642
	and a second
Items Inspected:	Depth of SLF verified
	Firm and unyielding Surface
	No visible low/ponding areas
	Free of deleterious materials
Testing Performed:	Nuclear Density Survey Completed
Amer 177-m20362 P 2000 12 - USUND - 2 × 2014 Con-2016 92 Autobald, 2 y 2014 Con-	Moisture/Density Lab Testing
	Lab Testing - Natural Moisture, Particle Size,
	Atterberg Limits, Proctor, Specific Gravity, Permeability
Deficient Items:	None
Remedial Actions:	
SLE Accented:	VES NO
Comments:	
Signatures:	10 -
sense Contraction (Codd)	ALL I
NewFields:	Date: 08/17/2020
	Profile in the second s
Tezak:	Kinh, Happing Date: 8/17/20
CCR.V.	Sold Juful Date: 8/17/26
(
Tetra Tech:	Date: 817.20
Other:	Date:



		1
Enter the second s	& Victor Mining Co. Contractor: Tezak	
Proiect: VLF2 Phase 2	<u>F-q/19</u> C 1	
Project No.: 475.0106.032 Date: 08/18/2020		1
Area/Location:	Panels P-36651P-3680 36415Ft2	
	36415 Ft 2	
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	
	No visible low/ponding areas	
	Free of deleterious materials	
		1
Testing Performed:	Nuclear Density Survey Completed	
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:		
	provide and a second se	
Remedial Actions:		
Tremedial / Colonsi		
		i
SLF Arrented:	YES V	
Comments:		
comments.		
· · · · · · · · · · · · · · · · · · ·		uter a construction and a construction of the construction of the construction of the construction of the const
Signatures:	1	
	100 1	
NewFields:	Date: 08/18/2020	
Tezak:	Kin W. 1000 Date: 8/18/20	
	il a suplit	
CCR.V-	Aoring Mylll Date 8/18/20	
Tetra Tech:	Date: 8.18.20	
Other:	Date:	



Client: Cripple Creek	& Victor Mining Co	Contractor: Tezak	
Client: Cripple Creek & Victor Mining Co. Project: VLF2 Phase 2			
Project No.: 475.0106.032		Date: 08/19/2020	
Project No 475.0100.052		Date. 08/19/2020	
	1- 1: 0 20	$\alpha_1 \neq 0$ 37 m	
Area/Location:	Panels P-36 33,11	81-10 1-3694	
	55,11	6 TFC	1
Items Inspected:	Depth of SLF verified		
8	Firm and unyielding Surfac		
	No visible low/ponding are		
	Free of deleterious materia	als	1
			1
Testing Performed:	Nuclear Density	Survey Completed	
	Moisture/Density Lab Test	ing	
	Lab Testing - Natural Mois	ture, Particle Size,	
		Specific Gravity, Permeability	Í
Deficient Items:	26		
	un and the head of the second s		
Remedial Actions:			
			Ì
SIF Arcented:	VEC V	NO	99 10
	Animal analysis of the AnimAnsian decouption of a second part of	15 No. 1997	
Comments:			and a free many second second second
commenta.	,		
			ĺ
1		the second s	i
	Ref Balanda (powerska), bola mana antan 1931 (Ref Viet Manara A Antalana, powerska B Balanda Antalana (Powerska) an		
C:			
Signatures	N/		
	06	Datas of 1	
NewFields:	Tamen	Date: <u>08/19/2020</u>	
	1.11	Date: 8 19 20	
Tezak	J- Windy	Date: 8 19 20	
	1 5 11.11	and mil	
CC&V	Join & m fun	Date: 5/19/00	
	21	C 16 20	
Tetra Tech		Date: $9.19.20$	
		D	
Other		Date:	

.



Exercised and the second se	& Victor Mining Co. Contractor: Tezak	
Proiect: VLF2 Phase 2		
Project No.: 475.0106.032	Date: 08/20/2020	
Area/Location:	Panels P-3695 P-3712 32815 Ft2	_
	32815 Ft2	
Items Inspected:	Depth of SLF verified	
	Firm and unyielding Surface	-
	No visible low/ponding areas	
	Free of deleterious materials	
		-
		nas i
Testing Performed:	Nuclear Density Survey Completed	-
	Moisture/Density Lab Testing	
	Lab Testing - Natural Moisture, Particle Size,	
	Atterberg Limits, Proctor, Specific Gravity, Permeability	
Deficient Items:		
		5 -4
		-
		-
Remedial Actions:		
		-
		-
		-
SIF Accented:	YES V	
Comments:	на стали и поста и пост На поста поста и	na hada da cabili da se da sendera cabada se da an
		-
Signatures:	10	
Signatures.	N/ ····································	
NewFields:	Monneli, Date: 08/20/2021	
ivewrields:	- 1 pumer - Date. 08/20/2021	2
Tezak:	Kin W. Doret Date: 8/20/2	020
iezak.	Date. 0 20/20	220
CCRV-	Some Shaller Date: 8/26/20	$\gamma \gamma \gamma$
	Total Mater 8/20/20	
Tetra Teç a:	Date: 8.20.20	
retra recer.		<u>.</u>
Other:	Date:	
ouler:	Date.	-