



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

PERMIT INFORMATION

Permit Number: C-2010-088 Mine Name: Fruita Loadout Operator: CAM-Colorado, LLC Operator Address: Ronald Hull 424 Lewis Hargett Circle Suite 250 Lexington, KY 40503	County: Mesa Operation Type: Loadout Permit Status: Temporary Cessation Ownership: Private
	Operator Representative Present: NA
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: October 13, 2020 Inspection Start Time: 10:35 Inspection End Date: October 13, 2020 Inspection End Time: 11:05		Inspection Type: Coal Complete Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None		Joint Inspection Contacts: None	
Post Inspection Agency: None		Post Inspection Contacts: None	
Inspector(s): Clayton Wein	Inspector's Signature: <i>Clayton Wein</i>		Signature Date: 10/16/2020

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

R - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

N - Explosives

Y - Fish & Wildlife

R - Hydrologic Balance

Y - Gen. Compliance With Mine Plan

N - Other

N - Processing Waste

N - Roads

N - Reclamation Success

N - Revegetation

N - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

R - Signs and Markers

N - Support Facilities Not On-site

N - Special Categories Of Mining

N - Topsoil

COMMENTS

This was a complete inspection of the Fruita Loadout conducted on October 13, 2020. The inspection was completed by Clayton Wein of the Division. The site is inactive; therefore, no company representative was present for the inspection. The weather was clear with a temperature of 70 degrees F. The ground conditions were dry.

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

The records are kept at the office of J. E. Stover and Associates in Grand Junction, CO. The records were well kept and up to date. Please see the Availability of Records Form attached to the end of this report for more details.

HYDROLOGIC BALANCE - Rule 4.05

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

No facilities have been constructed at the loadout and no disturbances have been made (Photo 1). The site was stable. Reed wash was flowing at the time of the inspection (Photo 2). There were no indications of new disturbances or erosional features. There were no off site impacts noted.

SIGNS AND MARKERS – Rule 4.02:

The mine identification sign is displayed to the left of the entrance to the site (Photo 3). The sign was in good condition and located in a visible spot. The sign displayed the required information about the Division, the permittee and the permit.

DOCUMENTS RECEIVED: None**OTHER (SPECIFY): None**Number of Partial Inspection this Fiscal Year: 0Number of Complete Inspections this Fiscal Year: 2

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2

PHOTOGRAPHS



Photo 1: The permitted site. The photo was taken looking to the north.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2



Photo 2: Reed wash. The photo was taken looking to the south.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2



Photo 3: The mine Identification Sign.

Number of Partial Inspection this Fiscal Year: 0

Number of Complete Inspections this Fiscal Year: 2

AVAILABILITY OF RECORDS**PERMIT RECORDS**

DRMS Permit	RN-1
Permit Application w/Revisions	OK
Findings Document	RN-1
Insurance Certificate	OK
Bond Document	OK
Phased Bond Release	NA
Documents/Findings	
Air Emission Permits	Exp.
County Special Use Permits	NA
UG Mining Landowner Notification	NA
Subsidence Monitoring Reports	NA
Subsidence Monitoring Data	NA
Rill & Gully Survey	NA

Vegetation Monitoring Data	Baseline
Specific Variance Approvals	NA
Annual Reclamation Reports	2019
Midterm Review Documents	MT-1
DRMS/OSM Inspection	Up to
Reports/Enforcement Actions (3 Years)	date/Laserfiche
Transfers/Succession of Operator	SO-2
Temporary Cessation Notification	2012
Reclamation Cost Estimate	RN-1

CERTIFICATIONS

Pond Certifications	NA
Annual Certifications for Impoundments	NA
Fill Certifications for Excess Spoil or Underground Development Waste	NA
• Quarterly Inspections	NA
• Compaction Testing	NA
• Final Certification	NA
Coal Processing Waste Banks	NA
Haul Road Certifications	NA
Access Road Certifications	NA

HYDROLOGIC RECORDS

NPDES Permit	COR-900152
NPDES Records	NA
Stormwater Management Plan	Req. Term.
SPCC Plan	NA
MSHA Pond Inspections	NA
	NA
State Engineer's Pond Inspection	
Quarterly Pond Inspections	NA
Annual Hydrology Reports	2019
• Ground Water Monitoring	NA
• Surface Water Monitoring	NA
• Spring & Seep Monitoring	NA
• Mine Water Discharge Monitoring	NA
• Mine Inflow Study	NA
• Water Consumption Records	NA
Well Permits	NA

BLASTING RECORDS

Blasting Publication	NA
Blasting Records (3 years)	NA
ATFE Explosives Permit	NA
Blasting Variances	NA
Pre-Blast Surveys	NA

ADDITIONAL RECORDS

(specify)	

COMMENTS:

Number of Partial Inspection this Fiscal Year: 0Number of Complete Inspections this Fiscal Year: 2