



Figure 2

Legend

- Affected Area Block
- Ground Disturbance
  - Pre 2011
  - 2011
  - 2012
- 2015 Reclamation Type
  - Weed Spray

FIGURE 2 - BULLDOG RECLAMATION  
SOUTHERN HOLDING POND

Bulldog Mine  
Creede, CO, USA

DRWN BY: RM 329400  
SCALE: 1:2,000  
PROJECTION: UTM NAD83, Z13  
DATE: 10/20/2020  
SIGNATURE: Randy McClure