

Unit	Description
4	Remaining portion of Lower Valley Access Road
5	Shop Area and Misc.
6	Mine Bench
6A	A-groove Road
7	Remaining Portion, Upper Middle Fork
8B	Summit Office Site
9	Davis Gulch Dam and Cofferdam Area
10A	Construction water pipeline, Davis portion
10B	Dam materials stockpile
10C	Road side slopes, other disturbances
10D	Topsoil Piles (Davis Gulch, small)
12	Ridgetop/Northdraw Topsoil Pile
14	Southdraw Topsoil Pile
15A	Topsoil haul road, South SS Draw
15B	Stockpile areas (stripped for mat'ls storage)
16A	LaSal Laydown Area
16B	Upper portion Constr. Water Pipeline, LaSal
17A	Coarse Ore Stockpile Area
17B	Guard Pond Disturbance
18A	Switchyard Fill
18C	Gondola Site (head of ESR Test Plots valley)
18D	North Valley Fill
18E	Level graded areas, EL 8000 to EL 8080
18F	Rock stockpiles
18G	Stripped, but not graded, areas
19A	Powerline Cooridor, near access road
19B	Mine Vent Portal along Access Rd
ESR	Spent Shale Research Site
AAR	Alternate Access Rd, South Property Line

Legend

- Colony Mining Permit boundary CDRMS Permit No. M-80-047
- 18G Site Disturbance Inventory designation from 1982 Interim Site Plan (ISP)
- Stripped and/or rough graded areas, stabilized and prepared for future construction
- Operations support areas and R & D areas
- Topsoil storage piles (temporary)
- Sediment ponds/Flood control structure

Filename:

Environmental Solutions, Inc
P. O. Box 2998
Cheyenne, Wy 82001

2020 Annual Report
Updated Map

Affected Area Remaining After 2007 Area Reduction and Permit Boundary After 2012 Acreage Reduction

Date	Revision	By	Check
9/15/16	Edits for Annual Report Map	ESI	TCP
9/27/17	Edits for Annual Report Map	ESI	TCP
10/03/18	Edits for Annual Report Map	ESI	TCP
10/04/19	Edits for Annual Report Map, update legend	ESI	TCP
10/15/20	Edits for Annual Report Map, update legend	ESI	TCP