



Login

General Information

Permit Number *

C1981019

Revision Application Form Selection *

MR (Minor Revision Application)

Select Revision *

If there are no options available it's because there are no open revisions of the selected type for the selected permit number

MR-225 Collom Diesel Tank

Revision Sequence *

If this does not populate, please contact your specialist to determine which sequence number to use.

225

Operation Name

Colowyo Coal Mine

The following pages will show the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

1. Upon submission of this form you will be presented with a link to the contact information update form.
2. There is a question asking about the accuracy of this information. Indicating that it is inaccurate will send an e-mail to notify your administrator to make the appropriate changes.

Contact Information

Permittee Contact Information

Permittee Name

Colowyo Coal Company L.P.

Permittee Contact

Barbara Waltz

Permittee Address 1

P.O. Box 33695

Permittee Address 2**Permittee City**

Denver

Permittee State

CO

Permittee Zip Code

802330695

Permittee Contact Email Address**Permittee Contact Phone Number**

Permitting Contact Info

Permitting Name

Tri-State Generation and Transmission Association

Permitting Contact

Chris Gilbreath

Permitting Address 1

1100 West 116th Avenue

Permitting Address 2**Permitting City**

Westminster

Permitting State

CO

Permitting Zip Code

802340000

Permitting Contact Email Address

cgilbreath@tristategt.org

Permitting Contact Phone Number

3032543291

Inspection Contact Info

Inspection Name

Colowyo Coal Company L.P.

Inspection Contact

Tony Tennyson

Inspection Address 1

5731 State Highway 13

Inspection Address 2

Inspection City

Meeker

Inspection State

CO

Inspection Zip Code

816410000

Inspection Contact Email Address

ttennyson@tristategt.org

Inspection Contact Phone Number

9708241210

Is the contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *

☒ Yes ☐ No

Once this form is submitted you will see a link to update contact information, which you may do if you're an admin.

Surface Area Changes

Revision

Revision Title * (?)

MR-225 Collom Diesel Tank

Short description

Narrative Description of Revision * (?)

MR-225 proposes a 2,000 gallon diesel tank to support mining operations at Collom.

Detailed description used for notifications

Bond Amount Change? *

☒ Yes ☐ No

Additional Surface Disturbance? *

☐ Yes ☒ No

Proposed Acreage Revisions

Permit Area

Current Value

26133.34

Proposed Change Value * (?)

0.00

Calculated Revised Total

26133.34

This value must equal the total of all Surface and Mineral Acreage changes

Affected Area

Current Value

6169.30

Proposed Change Value * (?)

0.00

Calculated Revised Total

6169.30

Disturbed Area

Current Value

5010.10

Proposed Change Value * (?)

0.00

Calculated Revised Total

5010.10

Attachments & Maps

Do you have attachments? *

☒ Yes ☐ No

Attachments

Standard Uploads

Document, NOT Confidential

201111 Colowyo MR-225 Adequacy
Response Casiraro to Trujillo.pdf 442.94KB

Map, NOT Confidential

Proof of Publication

Confidential Uploads

CONFIDENTIAL Document

CONFIDENTIAL Map

Document / Map List

New or Revised Documents / Pages *

If none exist, enter NONE in the comment box below.

Please see attached change sheet.

New or Revised Maps *

If none exist, enter NONE in the comment box below.

Please see attached change sheet.

Deleted Documents / Pages *

If none exist, enter NONE in the comment box below.

Please see attached change sheet.

Deleted Maps *

If none exist, enter NONE in the comment box below.

Please see attached change sheet.

Signature

Date

11/11/20

By checking this box you have thoroughly reviewed this Coal Revision form and are ready to submit this form to DRMS.

☒ I Agree