

COLORADO Division of Reclamation,

Mining and Safety

Department of Natural Resources .

Production Report General Information Permit Number * Select Report Date * C1981035 Site Name King Coal Mine Address 1 6473 County Road 120 Address 2 City State Zip Hesperus CO 81326 Site Information Mine Capacity in Tons * Mineral Resources Mined * Mining Method(s) * Mine Status 108,333.00 Underground Coal Producing Numbers Only Location of Processing Facility * Hesperus, Colorado **Production by County** Production All production fields only accept numbers **Total Production State Owned** % Out of County Federally Private Owned % In State * State * in Tons * Owned 40,993.00 0.00 40,993.00 0.00 0.00 La Plata 100.00

Site Statistics

Number of Employees at this Site

| Total Number of Employees * | Office | Surface | Underground |
|---|------------------------|-------------------|-------------------|
| 92 | 5 | 25 | 62 |
| Numbers Only | Numbers Only | Numbers Only | Numbers Only |
| Safety Statistics | | | |
| - ··· · · · · · · · · · · · · · · · · · | Hours Worked * | Injuries * | Fatalities * |
| Days Worked * | | | |
| Days Worked * 28 | 12,702 | 0 | 0 |
| | 12,702 Numbers Only | 0 Numbers Only | 0 Numbers Only |
| 28 | | - | - |