

	Pit 116 Piezometer					
	H-1	H-2	H-3	H-4	H-5	H-6
Bottom Depth of Well (ft)	50.22	43.18	70.00	59.00	47.00	49.00
	Measured Depth to Water (ft.)					
	H-1	H-2	H-3	H-4	H-5	H-6
8/26/2009	0.65	25.50	28.05			
9/23/2009	3.80	25.60	27.60			
10/30/2009	3.90	25.80	27.30			
11/26/2009	4.70	26.20	26.80			
12/31/2009	5.60	26.70	27.10			
1/19/2010	5.10	26.90	27.30			
2/16/2010	4.40	27.40	27.80			
3/12/2010	4.10	27.30	28.70			
4/9/2010	3.90	27.40	28.40			
5/4/2010	3.60	27.60	28.20	15.00	5.00	2.70
6/22/2010	2.52	26.88	29.48	17.40	3.72	1.74
7/24/2010	0.20	27.20	29.00	16.10	2.80	1.10
9/9/2010	4.66	27.37	30.47	18.08	5.39	3.94
10/21/2010	6.46	27.52	30.83	18.75	7.50	5.03
12/2/2010	7.15	27.76	30.14	19.07	8.15	5.18
1/7/2011	7.51	28.21	31.43	19.51	8.50	5.46
2/7/2011	7.63	28.58	30.81	19.79	8.59	5.51
3/10/2011	7.79	29.01	31.17	20.11	8.73	5.59
4/12/2011	7.07	29.27	32.23	20.04	7.85	5.13
5/10/2011	6.35	29.28	31.28	20.02	7.30	5.14
6/10/2011	6.21	29.00	31.01	19.74	6.93	5.21
7/11/2011	4.27	20.28	30.26	17.97	5.00	3.79
8/11/2011	4.30	27.65	29.77	17.88	5.33	3.96
9/9/2011	4.80	27.23	29.39	18.13	4.91	4.43
10/11/2011	6.32	27.46	30.61	18.94	7.10	5.07
11/10/2011	6.68	27.76	29.98	19.23	7.62	5.05
12/12/2011	7.33	28.14	30.36	19.58	8.23	5.45
1/9/2012		28.49	30.68	19.87	8.52	5.61
2/10/2012		28.49	31.06	20.21	8.78	5.96
3/6/2012		29.23	31.32	20.43	8.90	6.25
4/9/2012		29.64	31.64	20.72	8.80	6.12
5/11/2012		29.38	31.37	19.84	5.92	5.20
6/8/2012		29.06	31.03	19.38	5.60	5.30
7/9/2012		28.29	30.17	18.95	6.01	5.31
8/10/2012		28.00	31.12	18.77	5.12	5.45
9/10/2012		28.02	30.19	18.24	6.26	5.14
10/11/2012		28.03	30.12	19.47	7.60	5.70
11/9/2012		27.95	30.11	19.66	9.31	5.71
12/6/2012		28.25	30.43	20.18	10.28	6.71
1/10/2013		28.86	31.05	21.21	11.93	8.14
2/8/2013		29.43	31.54	21.95	14.27	8.67

pipe above casing

3/8/2013	29.84	31.96	22.56	16.58	9.45	
4/8/2013	30.17	33.55	23.13	16.72	10.04	
5/7/2013	30.41	32.47	23.55	17.08	10.48	
6/7/2013	29.92	31.56	22.35	16.11	9.12	
7/8/2013	29.25	31.08	21.38	17.40	8.66	
8/9/2013	28.15	30.09	19.41	20.87	8.50	
9/9/2013	27.79	29.91	20.06	21.08	8.84	
10/9/2013	26.80	29.41	20.48	22.73	10.18	
11/8/2013	27.44	30.01	21.51	23.96	11.21	
12/10/2013	28.15	31.66	22.24	25.70	11.81	
1/9/2014	28.78	32.35	23.06	26.51	12.62	
2/7/2014	29.35	31.79	23.68	26.81	13.12	
3/7/2014	29.78	32.21	24.22	26.95	13.44	
4/10/2014	30.14	32.49	24.74	27.05	13.75	
5/7/2014	30.28	32.52	24.65	25.53	13.33	
6/9/2014	29.27	31.72	23.22	25.61	11.30	
7/8/2014	29.26	32.50	22.99	23.41	10.97	
8/7/2014	28.31	30.30	21.24	25.47	8.91	
9/9/2014	damaged	29.66	20.11	25.93	8.36	
10/7/2014	27.07	30.65	20.39	27.45	8.77	
11/10/2014	27.37	30.14	21.12	29.19	10.02	
12/8/2014	27.90	30.72	21.81	29.74	11.05	
1/8/2015	28.55	31.36	22.54	30.32	12.16	
2/6/2015	29.16	31.95	23.33	30.67	13.01	
3/6/2015	29.68	32.50	24.18	31.35	13.77	
4/7/2015	30.05	32.80	24.95	31.48	14.38	
5/6/2015	30.17	32.83	24.88	31.19	13.32	
6/15/2015	29.85	32.58	24.89	31.07	13.68	
7/13/2015	29.51	33.28	22.87	25.48	9.48	
8/12/2015	28.34	30.60	21.09	26.03	8.20	
9/14/2015	27.72	30.30	20.69	26.83	9.40	
10/12/2015	27.73	31.45	21.21	29.71	10.37	
11/10/2015	27.88	30.56	21.89	32.19	11.75	
12/10/2015	28.32	31.09	22.65	33.50	12.82	
1/11/2016	28.92	32.78	23.51	34.47	13.73	
2/11/2016	29.47	32.24	24.51	35.46	14.27	
3/10/2016	29.82	32.57	25.00	37.64	14.83	
4/11/2016	30.09	34.20	25.83	38.11	14.72	
5/10/2016	30.13	32.83	25.46	37.74	16.63	
6/10/2016	29.97	32.57	25.17	35.28	13.40	
7/11/2016	29.43	33.11	23.23	26.21	10.15	
8/11/2016	28.58	31.23	22.55	22.86	11.09	
9/12/2016	27.94	30.77	22.26	28.19	11.94	
10/11/2016	27.45	30.21	22.21	30.59	12.23	
11/10/2016	27.47	30.39	22.66	32.11	13.16	
12/9/2016	27.93	31.03	23.27	30.25	14.73	pipe broken
1/12/2017	29.34	31.96	25.09	31.37	17.14	
2/9/2017	29.35	32.53	25.71	31.82	17.22	
3/9/2017	30.41	33.60	26.00	32.27	14.84	
4/10/2017	30.78	34.03	26.25	32.38	14.84	

5/11/2017	30.09	33.01	25.81	29.56	14.97	
6/8/2017	29.71	32.74	25.78	26.87	16.70	
7/12/2017	29.03	31.68	24.72	15.52	20.77	
8/10/2017	28.22	30.81	23.26	13.77	22.41	
9/11/2017	27.68	30.33	22.14	13.25	22.33	
10/12/2017	27.76	30.74	22.87	21.54	24.41	
11/9/2017	28.28	31.49	23.81	24.62	25.49	
12/7/2017	28.91	32.15	24.67	26.45	broken	
1/11/2018	29.61	32.87	25.47	27.60	26.18	
2/8/2018	30.07	33.42	26.34	28.14	22.44	
3/8/2018	30.37	33.74	26.61	28.03	22.37	
4/11/2018	30.59	34.19	26.91	27.81	26.58	
5/9/2018	30.76	34.58	27.09	27.30	29.59	repaired H-4
6/5/2018	30.52	34.18	27.06	22.05	32.13	
7/9/2018	29.95	33.32	26.42	15.22	29.60	
8/9/2018	29.31	32.59	25.28	11.09	27.87	
9/6/2018	29.04	32.34	24.83	13.00	29.75	
10/11/2018	28.82	32.30	24.43	13.97	30.67	
11/8/2018	28.82	32.18	24.20	18.79	31.80	
12/6/2018	28.88	32.10	24.23	22.07	31.96	
1/9/2019	29.1	32.21	24.37	24.45	32.73	
2/11/2019	29.32	32.20	24.51	26.24	33.15	
3/7/2019	29.46	32.26	24.56	27.17	33.14	
4/9/2019	29.68	32.34	24.65	27.84	32.95	
5/9/2019	29.78	32.45	24.76	26.62	32.91	
6/6/2019	29.45	31.99	24.65	23.68	31.37	
7/8/2019	29	31.93	24.33	15.57	30.15	
8/8/2019	28.38	30.71	23.85	11.65	28.50	
9/5/2019	27.95	30.46	23.41	13.27	30.17	
10/8/2019	27.81	30.46	23.23	18.18	30.89	
11/7/2019	27.97	30.77	23.29	22.04	32.23	
12/5/2019	28.28	31.08	23.43	24.18	32.43	
1/9/2020	28.75	31.57	23.73	26.05	32.81	
2/6/2020	29.17	31.95	24.17	27.34	33.03	
3/10/2020	29.63	32.38	24.53	28.15	33.03	
4/8/2020	29.9	32.61	24.72	28.43	32.76	
5/8/2020	29.81	32.50	24.80	28.09	32.27	