



February 8, 2021

Kurt Blunt
Blue Mountain Energy, Inc.
3607 County Rd. 65
Rangely, CO 81648

**RE: Deserado Mine, Permit No. C-1981-018
4th Quarter 2020 Discharge Monitoring Reports Review**

Dear Kurt,

The Colorado Division of Reclamation, Mining and Safety (the Division) has finished reviewing the 2020 4th Quarter Discharge Monitoring Reports (DMR). The reports were received on February 4 2021. The Division finds the reports to be in compliance with the following Rules:

- **Rule 4.05.13(2)(i)** – Samples are measured accurately and record the quality and quantity of the water discharged from the permit area.
- **Rule 4.05.13(2)(ii)** – Discharges occurred from DP-1 (Outfall 001-A/MN-01), SDH-3/5 (Outfall 026-A/MN-26), the B-Seam Dewatering System No. 1 (Outfall 029-A/029-W/ MN-29) and the Sewage Treatment Plant (Outfall 045-A) during the 4th quarter of 2020. The samples collected from 001-A, 026-A, 029-A and 045-A were below the maximum allowable values or within acceptable value ranges. 026-W did not receive enough flow to conduct WET Testing during the 4th Quarter.
- **Rule 4.05.13(2)(iii)** – Discharge Monitoring Reports are received on a quarterly basis and filed with the Division within 90 days of the sample collection.

This concludes the Division's review of the 2020 4th Quarter Discharge Monitoring Reports. If you have any questions, please contact me at (303)-866-3567 x8144.

Sincerely,

Clayton Wein
Environmental Protection Specialist

