## **DRMS Coal New Revision Application**



Login

### **General Information**

Revision Application Form Selection \*

Permit Number \*

MR (Minor Revision Application)

C1981018

**Operation Name** 

Deserado Mine

The following pages will show the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information. Indicating that it is inaccurate will send an email to notify your administrator to make the appropriate changes.

## **Contact Information**

### **Permittee Contact Information**

**Permittee Name** 

Blue Mountain Energy, Inc

**Permittee Contact** 

Lynn Mitten

**Permittee Address 1** 

10714 South Jordon Gateway, Suite 300

**Permittee Address 2** 

Permittee City Permittee State Permittee Zip Code

South Jordon UT 840950000

**Permittee Contact Email Address** 

**Permittee Contact Phone Number** 

# **Permitting Contact Info**

**Permitting Name** 

Blue Mountain Energy, Inc

**Permitting Contact** 

Kurtis Blunt

**Permitting Address 1** 

3607 County Road 65

**Permitting Address 2** 

Permitting City Permitting State Permitting Zip Code

Rangely, CO 816480000

**Permitting Contact Email Address** 

kblunt@deserado.com

**Permitting Contact Phone Number** 

# **Inspection Contact Info**

**Inspection Name** 

Blue Mountain Energy, Inc

**Inspection Contact** 

Kurtis Blunt

**Inspection Address 1** 

3607 County Road 65

Inspection Address 2		
Inspection City Rangely, CO	Inspection State	Inspection Zip Code 816480000
Inspection Contact Email Address kblunt@deserado.com		
Inspection Contact Phone Number		
Is the contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *		
○ Yes ● No		
Once this form is submitted you will see a link to update contact information, which you may do if you're an admin.		

# Surface Area Changes

### **Revision**

Revision Title \* (?)

Longwall Advancement Core Drillilng

Short description

Narrative Description of Revision \* (?)

Deserado Mine is requesting permission to drill seven core drill holes to gain information regarding longwall advancement..

Detailed description used for notifications

Bond Amount Change? \*

Yes
No

Additional Surface Disturbance? \*

Yes
No

# **Proposed Acreage Revisions**

#### Permit Area

Current Value Proposed Change Value \* (?) Calculated Revised Total

13645.01 0.00 13645.01

This value must equal the total of all Surface and Mineral Acreage changes

Affected Area

Current Value Proposed Change Value \* (?) Calculated Revised Total

8215.75 0.00 8215.75

Disturbed Area

Current Value Proposed Change Value \* (?) Calculated Revised Total

645.61 1.16 646.77

# Attachments & Maps

## Do you have attachments? \*

● Yes ○ No

## **Attachments**

Standard Uploads

#### **Document, NOT Confidential**

II.F-18A MR-181.pdf 297.02KB **Map, NOT Confidential** 

MR-181 Page V-24 2-2021.pdf 123.58KB Map147 - Version 47.pdf 26.01MB

#### **Confidential Uploads**

CONFIDENTIAL Document CONFIDENTIAL Map

## **Document / Map List**

### New or Revised Documents / Pages \*

If none exist, enter NONE in the comment box below.

Page II.F-18A MR-181

Page V-24 2-2021 MR-181

#### New or Revised Maps \*

If none exist, enter NONE in the comment box below.

Map 147 - Version 47

### Deleted Documents / Pages \*

If none exist, enter NONE in the comment box below.

Page II.F-18A MR-180

Page V-24 2-2021 MR-180

#### **Deleted Maps**\*

If none exist, enter NONE in the comment box below.

Map 147 - Version 46

## **Signature**

#### **Date**

02/26/21

By checking this box you have thoroughly reviewed this Coal Revision form and are ready to submit this form to DRMS.

I Agree