



**COLORADO**  
**Division of Reclamation,  
Mining and Safety**  
Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

March 1, 2021

Jim Doody  
Elam Construction, Inc.  
556 Struthers Ave  
Grand Junction, CO 81501

**23 ¼ West Pit, Permit No. M-2020-035, Inspection Problem Abated**

Dear Mr. Doody:

On December 17, 2020 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs and markers was cited as a problem for failure to post a mine sign at the entrance to the site. Corrective actions required you to submit photo documentation that a sign had been posted by the corrective action date.

On February 26, 2021 the Division received a photo of the corrected mine sign posted at the permit entrance. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me.

Sincerely,

**Amy C Yeldell**  
Environmental Protection Specialist

EC: Travis Marshall, Senior EPS, DRMS

