

PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: None
Operator Representative Signature: (Field Issuance Only)	

INSPECTION INFORMATION

Inspection Start Date: March 2, 2021 Inspection Start Time: 12:30 Inspection End Date: March 2, 2021 Inspection End Time: 12:45	Inspection Type: Aerial Inspection Inspection Reason: Normal I&E Program Weather: Clear
Joint Inspection Agency: None	Joint Inspection Contacts:
Post Inspection Agency: None	Post Inspection Contacts:
Inspector(s): Tabetha Lynch Brock Bowles	Inspector's Signature:  Signature Date: 3/5/2021

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection
N - Availability of Records
N - Backfill & Grading
N - Excess Spoil and Dev. Waste
N - Explosives
N - Fish & Wildlife
Y - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
NA - Processing Waste

Y - Roads
Y - Reclamation Success
N - Revegetation
N - Subsidence
N - Slides and Other Damage
N - Support Facilities On-site
N - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was an aerial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. Photos were taken by Brock Bowles on 3/2 and photos were observed by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 3/5. The weather was patchy clouds and site was snow covered during the inspection.

Permit Revision No. 2 (PR-2) and Bond Release No.2 (SL-2) are currently under review by the Division. PR-2 proposes to modify the approved reclamation plan and post-mining land use for the major portion of the Hayden Gulch Loadout, consistent with the transfer of former rail spur areas to the Town of Hayden (Hayden) for recreational use. The former rail spur area has been converted to a recreational trail for the use of residents and visitors to Hayden under a locally managed "Tracks-to-Trails" program. The Division provided adequacy comments for PR-2 to the operator on November 25th, 2020. Decision date for PR-2 is currently 3/12/2021. Permit Revision No. 2 (PR-2) must be Issued by the Division before a proposed decision will be made by Division for Bond Release SL-2.

GENERAL MINE PLAN COMPLIANCE:

Train Loop shown below looking east. Ponds appear snow covered and not likely holding additional water as vegetation is visible. The loop is currently being used by public as a walking trail. It appears the former haul road are being plowed and maintained.



County Road 37 is shown in photo below looking south. The rail bed trail is to the left of the road in the lower portion of the photo, crosses the road and loadout loop is visible in the top right. Dry creek does not appear to be holding water.



Highway 40 is pictured below looking east. The parking lot appears to be plowed. Remaining permit area appears snow covered and undisturbed. No issues are noted as a result of this inspection.



DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.