



July 6, 2020

Rob Zuber
Division of Reclamation, Mining & Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Quarterly Pond Inspection
Keenesburg Mine, Permit C-1981-028

Dear Rob Zuber:

Attached is a copy of the Quarterly Pond Inspection report for the third Quarter of 2020. Coors Energy Company has prepared and is submitting this copy in compliance with revised Division Regulation 4.05.9(17). The original of this report has been placed in the inspection reference volume at the site.

Should there be questions about the report, or a need for additional information, please contact me at (303 944-8166).

Sincerely,
Danny Kipp

Danny Kipp
Chief Reclamation Specialist

Enclosure

ANNUAL & QUARTERLY POND INSPECTION

COORS ENERGY COMPANY

KEENESBURG MINE SITE

Date of Inspection 7/6/20

Pond Identification:		Sediment Pond #2		Dugout
Type of Pond		Sediment		Permanent
Capacities		15.6 acre ft. 5097,925 gals.		19.7 acre ft. 6,437,760 gals.
Approx. water level - (% of capacity)		trace		trace
Sediment level - (% of capacity)		0		0
Out flow				
Erosional Features		yes - no		yes - no
Rills / Gullies		no		no
Inadequate Vegetation		no		no
Outlet Channel				
Erosion		no		no
Burrows		no		no
Other				
Structural Issues				
Settlement		no		no
Cracks/Slides		no		no
Seepage				
Spillways (cond.)		good		good
Other				

Signature (P.E. or Authorized Inspector): Danny Kipp