



November 11, 2020

Rob Zuber
Division of Reclamation, Mining & Safety
Department of Natural Resources
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Quarterly Pond Inspection
Keenesburg Mine, Permit C-1981-028

Dear Rob Zuber:

Attached is a copy of the Quarterly Pond Inspection report for the Fourth Quarter of 2020. Coors Energy Company has prepared and is submitting this copy in compliance with revised Division Regulation 4.05.9(17). The original of this report has been placed in the inspection reference volume at the site.

Should there be questions about the report, or a need for additional information, please contact me at (3030-810-4231

Sincerely,

Ben Moline, PE
General Manager

Enclosure

ANNUAL & QUARTERLY POND INSPECTION

COORS ENERGY COMPANY

KEENESBURG MINE SITE

Date of Inspection 11/11/20

Pond Identification:		Sediment Pond #2		Dugout	
Type of Pond		Sediment		Permanent	
Capacities		15.6 acre ft. 5097,925 gals.		19.7 acre ft. 6,437,760 gals.	
Approx. water level - (% of capacity)		Trace		Trace	
Sediment level - (% of capacity)		0		0	
Out flow					
Erosional Features		yes - no		yes - no	
Rills / Gullies		No		No	
Inadequate Vegetation		No		No	
Outlet Channel Erosion		No		No	
Burrows		No		No	
Other		NA		NA	
Structural Issues					
Settlement		No		No	
Cracks/Slides		No		No	
Seepage		None		None	
Spillways (cond.)		Good		Good	
Other		NA		NA	

Signature (P.E. or Authorized Inspector): Ben Moline, PE

B Moline
CE 40876
10/31/21