

Property	Martin Marietta - D&S			Martin Marietta - D&S			Martin Marietta - D&S		
Area	CR 23 & 10			CR 23 & 10			CR 23 & 10		
Well Name	DS03-MW01			DS03-MW02			DS03-MW03		
Ground Elevation	4902.0			4908.9			4914.1		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	14.1	3.6	10.5	16.0	3.4	12.6	21.9	4.1	17.8
02/24/17	15.9	3.6	12.3	16.3	3.4	12.9	21.9	4.1	17.8
03/24/17	14.6	3.6	11.0	16.3	3.4	12.9	22.0	4.1	17.9
04/28/17	12.4	3.6	8.8	14.1	3.4	10.7	21.9	4.1	17.8
05/30/17	12.3	3.6	8.7	15.6	3.4	12.2	21.7	4.1	17.6
06/23/17	10.0	3.6	6.4	14.5	3.4	11.1	21.1	4.1	17.0
07/28/17	10.4	3.6	6.8	11.7	3.4	8.3	20.7	4.1	16.6
08/22/17	10.0	3.6	6.4	11.6	3.4	8.2	19.5	4.1	15.4
09/18/17	11.3	3.6	7.7	11.5	3.4	8.1	19.6	4.1	15.5
10/27/17	12.6	3.6	9.0	13.2	3.4	9.8	20.0	4.1	15.9
11/28/17	15.0	3.6	11.4	15.4	3.4	12.0	21.1	4.1	17.0
12/18/17	16.0	3.6	12.4	16.2	3.4	12.8	21.7	4.1	17.6
01/26/18	17.5	3.6	13.9	16.1	3.4	12.7	22.0	4.1	17.9
02/23/18	18.0	3.6	14.4	16.6	3.4	13.2	22.0	4.1	17.9
03/21/18	18.4	3.6	14.8	16.2	3.4	12.8	21.9	4.1	17.8
04/26/18	14.4	3.6	10.8	16.2	3.4	12.8	22.0	4.1	17.9
05/29/18	11.9	3.6	8.3	13.0	3.4	9.6	21.8	4.1	17.7
06/22/18	12.3	3.6	8.7	14.4	3.4	11.0	21.7	4.1	17.6
09/28/18	12.8	3.6	9.2	13.6	3.4	10.2	21.2	4.1	17.1
10/23/18	12.0	3.6	8.4	14.0	3.4	10.6	20.8	4.1	16.7
11/30/18	15.3	3.6	11.7	15.9	3.4	12.5	21.3	4.1	17.2
12/19/18	16.4	3.6	12.8	16.2	3.4	12.8	21.7	4.1	17.6
01/31/19	17.6	3.6	14.0	16.6	3.4	13.2	21.6	4.1	17.5
02/28/19	17.8	3.6	14.2	16.3	3.4	12.9	21.5	4.1	17.4
03/29/19	17.7	3.6	14.1	16.3	3.4	12.9	21.5	4.1	17.4
04/26/19	14.3	3.6	10.7	16.2	3.4	12.8	21.4	4.1	17.3
05/29/19	10.3	3.6	6.7	13.7	3.4	10.3	20.4	4.1	16.3
07/09/19	9.2	3.6	5.6	12.2	3.4	8.8	19.1	4.1	15.0
08/30/19	8.6	3.6	5.0	9.7	3.4	6.3	16.9	4.1	12.8
09/30/19	8.9	3.6	5.3	10.4	3.4	7.0	17.0	4.1	12.9
10/31/19	9.7	3.6	6.1	10.4	3.4	7.0	17.2	4.1	13.1
11/22/19	10.3	3.6	6.7	11.8	3.4	8.4	17.9	4.1	13.8
12/20/19	10.7	3.6	7.1	12.6	3.4	9.2	18.7	4.1	14.6
01/29/20	11.3	3.6	7.7	13.3	3.4	9.9	19.4	4.1	15.3
02/28/20	11.3	3.6	7.7	13.4	3.4	10.0	19.5	4.1	15.4

Property	Martin Marietta - D&S			Martin Marietta - MF			Martin Marietta - MF		
Area	CR 23 & 10			CR 23 & 10			CR 23 & 10		
Well Name	DS03-MW04			MF03-MW01			MF03-MW02		
Ground Elevation	4911.4			4922.2			4909.1		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	21.1	3.9	17.2	27.1	4.2	22.9	21.3	3.8	17.5
02/24/17	22.1	3.9	18.2	28.0	4.2	23.8	21.7	3.8	17.9
03/24/17	22.6	3.9	18.7	28.4	4.2	24.2	22.1	3.8	18.3
04/28/17	22.0	3.9	18.1	28.2	4.2	24.0	22.0	3.8	18.2
05/30/17	20.9	3.9	17.0	27.4	4.2	23.2	20.4	3.8	16.6
06/23/17	19.1	3.9	15.2	25.4	4.2	21.2	19.7	3.8	15.9
07/28/17	18.5	3.9	14.6	25.1	4.2	20.9	19.5	3.8	15.7
08/22/17	17.6	3.9	13.7	24.8	4.2	20.6	19.0	3.8	15.2
09/18/17	17.5	3.9	13.6	24.3	4.2	20.1	19.0	3.8	15.2
10/27/17	18.3	3.9	14.4	25.0	4.2	20.8	19.4	3.8	15.6
11/28/17	19.3	3.9	15.4	27.8	4.2	23.6	18.8	3.8	15.0
12/18/17	19.9	3.9	16.0	26.2	4.2	22.0	19.0	3.8	15.2
01/26/18	20.3	3.9	16.4	26.8	4.2	22.6	19.4	3.8	15.6
02/23/18	20.5	3.9	16.6	27.0	4.2	22.8	19.5	3.8	15.7
03/21/18	20.7	3.9	16.8	27.3	4.2	23.1	19.7	3.8	15.9
04/26/18	22.5	3.9	18.6	27.5	4.2	23.3	19.9	3.8	16.1
05/29/18	21.9	3.9	18.0	26.9	4.2	22.7	19.6	3.8	15.8
06/22/18	21.8	3.9	17.9	26.3	4.2	22.1	19.0	3.8	15.2
09/28/18	19.6	3.9	15.7	25.5	4.2	21.3	18.2	3.8	14.4
10/23/18	18.7	3.9	14.8	25.2	4.2	21.0	17.8	3.8	14.0
11/30/18	19.5	3.9	15.6	25.7	4.2	21.5	18.1	3.8	14.3
12/19/18	19.8	3.9	15.9	25.7	4.2	21.5	17.1	3.8	13.3
01/31/19	19.1	3.9	15.2	25.3	4.2	21.1	16.8	3.8	13.0
02/28/19	19.1	3.9	15.2	25.3	4.2	21.1	16.7	3.8	12.9
03/29/19	19.0	3.9	15.1	25.3	4.2	21.1	16.6	3.8	12.8
04/26/19	18.6	3.9	14.7	25.2	4.2	21.0	16.5	3.8	12.7
05/29/19	17.5	3.9	13.6	24.7	4.2	20.5	16.4	3.8	12.6
07/09/19	16.2	3.9	12.3	23.7	4.2	19.5	15.4	3.8	11.6
08/30/19	14.4	3.9	10.5	21.8	4.2	17.6	14.1	3.8	10.3
09/30/19	14.6	3.9	10.7	21.6	4.2	17.4	14.1	3.8	10.3
10/31/19	14.8	3.9	10.9	22.2	4.2	18.0	14.6	3.8	10.8
11/22/19	15.2	3.9	11.3	22.8	4.2	18.6	15.2	3.8	11.4
12/20/19	15.9	3.9	12.0	23.6	4.2	19.4	15.8	3.8	12.0
01/29/20	16.3	3.9	12.4	25.4	4.2	21.2	16.3	3.8	12.5
02/28/20	16.4	3.9	12.5	25.4	4.2	21.2	15.5	3.8	11.7

Property	Martin Marietta - MY			Aurora - D&S Thornton			Aurora - D&S Thornton		
Area	CR 23 & 10			CR 6 & 8			CR 6 & 8		
Well Name	MY03-MW01			DS03-MW05			DS03-MW06		
Ground Elevation	4923.0			4905.1			4906.7		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	17.3	4.2	13.1	10.3	3.4	6.9	10.5	3.6	6.9
02/24/17	17.8	4.2	13.6	10.3	3.4	6.9	10.6	3.6	7.0
03/24/17	18.1	4.2	13.9	10.1	3.4	6.7	11.0	3.6	7.4
04/28/17	17.8	4.2	13.6	9.6	3.4	6.2	10.4	3.6	6.8
05/30/17	16.7	4.2	12.5	7.4	3.4	4.0	9.0	3.6	5.4
06/23/17	16.0	4.2	11.8	7.7	3.4	4.3	9.8	3.6	6.2
07/28/17	15.1	4.2	10.9	7.0	3.4	3.6	9.1	3.6	5.5
08/22/17	14.6	4.2	10.4	7.8	3.4	4.4	9.9	3.6	6.3
09/18/17	14.2	4.2	10.0	8.1	3.4	4.7	10.3	3.6	6.7
10/27/17	15.1	4.2	10.9	8.2	3.4	4.8	10.2	3.6	6.6
11/28/17	16.0	4.2	11.8	8.5	3.4	5.1	10.4	3.6	6.8
12/18/17	16.4	4.2	12.2	8.4	3.4	5.0	10.3	3.6	6.7
01/26/18	17.0	4.2	12.8	8.9	3.4	5.5	10.4	3.6	6.8
02/23/18	17.4	4.2	13.2	9.0	3.4	5.6	10.6	3.6	7.0
03/21/18	17.7	4.2	13.5	8.8	3.4	5.4	10.2	3.6	6.6
04/26/18	17.7	4.2	13.5	8.4	3.4	5.0	10.3	3.6	6.7
05/29/18	16.7	4.2	12.5	8.5	3.4	5.1	10.0	3.6	6.4
06/22/18	15.2	4.2	11.0	8.2	3.4	4.8	10.2	3.6	6.6
09/28/18	15.2	4.2	11.0	9.4	3.4	6.0	11.0	3.6	7.4
10/23/18	15.7	4.2	11.5	9.3	3.4	5.9	10.9	3.6	7.3
11/30/18	16.2	4.2	12.0	9.6	3.4	6.2	10.6	3.6	7.0
12/19/18	16.5	4.2	12.3	9.8	3.4	6.4	10.6	3.6	7.0
01/31/19	16.9	4.2	12.7	9.9	3.4	6.5	10.9	3.6	7.3
02/28/19	17.0	4.2	12.8	9.9	3.4	6.5	10.8	3.6	7.2
03/29/19	17.2	4.2	13.0	9.6	3.4	6.2	10.8	3.6	7.2
04/26/19	17.2	4.2	13.0	9.2	3.4	5.8	11.0	3.6	7.4
05/29/19	16.9	4.2	12.7	8.5	3.4	5.1	9.8	3.6	6.2
07/09/19	14.9	4.2	10.7	7.0	3.4	3.6	8.0	3.6	4.4
08/30/19	13.9	4.2	9.7	8.5	3.4	5.1	10.4	3.6	6.8
09/30/19	14.5	4.2	10.3	8.9	3.4	5.5	10.7	3.6	7.1
10/31/19	15.3	4.2	11.1	9.1	3.4	5.7	10.3	3.6	6.7
11/22/19	15.7	4.2	11.5	9.4	3.4	6.0	10.1	3.6	6.5
12/20/19	16.2	4.2	12.0	9.8	3.4	6.4	10.4	3.6	6.8
01/29/20	17.1	4.2	12.9	10.0	3.4	6.6	10.5	3.6	6.9
02/28/20	17.2	4.2	13.0	9.9	3.4	6.5	10.3	3.6	6.7

Property	Aurora - D&S Thornton			Aurora - D&S Thornton			Aurora - D&S Thornton		
Area	CR 6 & 8			CR 6 & 8			CR 6 & 8		
Well Name	DS03-MW07			DS03-MW08			DS03-MW09		
Ground Elevation	4912.2			4910.3			4912.3		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	12.9	4.3	8.6	10.2	3.6	6.6	8.9	4.0	4.9
02/24/17	13.3	4.3	9.0	10.3	3.6	6.7	9.1	4.0	5.1
03/24/17	13.5	4.3	9.2	10.0	3.6	6.4	8.6	4.0	4.6
04/28/17	12.9	4.3	8.6	9.3	3.6	5.7	7.6	4.0	3.6
05/30/17	11.6	4.3	7.3	7.9	3.6	4.3	6.5	4.0	2.5
06/23/17	12.3	4.3	8.0	8.6	3.6	5.0	7.1	4.0	3.1
07/28/17	11.7	4.3	7.4	8.1	3.6	4.5	6.7	4.0	2.7
08/22/17	12.6	4.3	8.3	8.6	3.6	5.0	6.8	4.0	2.8
09/18/17	11.6	4.3	7.3	9.0	3.6	5.4	7.3	4.0	3.3
10/27/17	11.6	4.3	7.3	9.2	3.6	5.6	7.6	4.0	3.6
11/28/17	11.6	4.3	7.3	9.6	3.6	6.0	7.9	4.0	3.9
12/18/17	12.9	4.3	8.6	9.7	3.6	6.1	8.2	4.0	4.2
01/26/18	13.1	4.3	8.8	9.9	3.6	6.3	8.6	4.0	4.6
02/23/18	13.4	4.3	9.1	10.0	3.6	6.4	8.8	4.0	4.8
03/21/18	13.1	4.3	8.8	9.8	3.6	6.2	8.8	4.0	4.8
04/26/18	11.8	4.3	7.5	9.4	3.6	5.8	8.3	4.0	4.3
05/29/18	12.6	4.3	8.3	9.2	3.6	5.6	7.5	4.0	3.5
06/22/18	12.6	4.3	8.3	8.9	3.6	5.3	7.3	4.0	3.3
09/28/18	11.9	4.3	7.6	9.8	3.6	6.2	8.2	4.0	4.2
10/23/18	11.9	4.3	7.6	9.8	3.6	6.2	8.0	4.0	4.0
11/30/18	13.1	4.3	8.8	10.1	3.6	6.5	8.6	4.0	4.6
12/19/18	12.4	4.3	8.1	10.2	3.6	6.6	8.6	4.0	4.6
01/31/19	12.3	4.3	8.0	10.4	3.6	6.8	8.6	4.0	4.6
02/28/19	12.0	4.3	7.7	10.3	3.6	6.7	8.6	4.0	4.6
03/29/19	13.1	4.3	8.8	10.2	3.6	6.6	8.6	4.0	4.6
04/26/19	13.3	4.3	9.0	9.8	3.6	6.2	8.2	4.0	4.2
05/29/19	12.2	4.3	7.9	9.3	3.6	5.7	7.4	4.0	3.4
07/09/19	10.6	4.3	6.3	7.7	3.6	4.1	5.8	4.0	1.8
08/30/19	13.5	4.3	9.2	9.4	3.6	5.8	7.4	4.0	3.4
09/30/19	13.7	4.3	9.4	9.8	3.6	6.2	7.8	4.0	3.8
10/31/19	11.9	4.3	7.6	10.0	3.6	6.4	8.0	4.0	4.0
11/22/19	11.6	4.3	7.3	10.2	3.6	6.6	8.2	4.0	4.2
12/20/19	13.3	4.3	9.0	10.7	3.6	7.1	8.9	4.0	4.9
01/29/20	14.6	4.3	10.3	11.0	3.6	7.4	9.5	4.0	5.5
02/28/20	14.4	4.3	10.1	10.5	3.6	6.9	9.5	4.0	5.5

Property	MM-Chikuma			MM-Chikuma			MM-Chikuma		
Area	CR 6 & 8			CR 6 & 8			CR 6 & 8		
Well Name	CH03-MW01			CH03-MW02			CH03-MW03		
Ground Elevation	4914.2			4912.9			4910.9		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	7.3	3.5	3.8	9.2	3.9	5.3	(1)	NA	NA
02/24/17	7.8	3.5	4.3	9.7	3.9	5.8	(1)	NA	NA
03/24/17	6.0	3.5	2.5	9.7	3.9	5.8	(1)	NA	NA
04/28/17	5.3	3.5	1.8	8.4	3.9	4.5	(1)	NA	NA
05/30/17	5.6	3.5	2.1	7.2	3.9	3.3	(1)	NA	NA
06/23/17	5.2	3.5	1.7	7.7	3.9	3.8	(1)	NA	NA
07/28/17	4.5	3.5	1.0	7.3	3.9	3.4	(1)	NA	NA
08/22/17	4.5	3.5	1.0	8.1	3.9	4.2	(1)	NA	NA
09/18/17	5.3	3.5	1.8	7.7	3.9	3.8	(1)	NA	NA
10/27/17	6.2	3.5	2.7	8.1	3.9	4.2	(1)	NA	NA
11/28/17	6.3	3.5	2.8	8.1	3.9	4.2	(1)	NA	NA
12/18/17	6.5	3.5	3.0	8.7	3.9	4.8	(1)	NA	NA
01/26/18	6.4	3.5	2.9	9.2	3.9	5.3	(1)	NA	NA
02/23/18	7.4	3.5	3.9	9.5	3.9	5.6	(1)	NA	NA
03/21/18	7.2	3.5	3.7	9.8	3.9	5.9	(1)	NA	NA
04/26/18	7.3	3.5	3.8	9.5	3.9	5.6	(1)	NA	NA
05/29/18	5.5	3.5	2.0	8.5	3.9	4.6	(1)	NA	NA
06/22/18	5.3	3.5	1.8	8.0	3.9	4.1	(1)	NA	NA
09/28/18	6.0	3.5	2.5	8.0	3.9	4.1	(1)	NA	NA
10/23/18	6.3	3.5	2.8	8.3	3.9	4.4	(1)	NA	NA
11/30/18	6.7	3.5	3.2	9.0	3.9	5.1	(1)	NA	NA
12/19/18	6.6	3.5	3.1	9.1	3.9	5.2	(1)	NA	NA
01/31/19	6.4	3.5	2.9	9.2	3.9	5.3	(1)	NA	NA
02/28/19	6.5	3.5	3.0	9.2	3.9	5.3	(1)	NA	NA
03/29/19	6.5	3.5	3.0	9.2	3.9	5.3	(1)	NA	NA
04/26/19	6.3	3.5	2.8	9.1	3.9	5.2	(1)	NA	NA
05/29/19	5.4	3.5	1.9	8.6	3.9	4.7	(1)	NA	NA
07/09/19	4.8	3.5	1.3	7.0	3.9	3.1	(1)	NA	NA
08/30/19	4.9	3.5	1.4	(1)	NA	NA	(1)	NA	NA
09/30/19	5.5	3.5	2.0	(1)	NA	NA	(1)	NA	NA
10/31/19	6.1	3.5	2.6	(1)	NA	NA	(1)	NA	NA
11/22/19	6.4	3.5	2.9	(1)	NA	NA	(1)	NA	NA
12/20/19	7.1	3.5	3.6	(1)	NA	NA	(1)	NA	NA
01/29/20	8.1	3.5	4.6	(1)	NA	NA	(1)	NA	NA
02/28/20	8.3	3.5	4.8	(1)	NA	NA	(1)	NA	NA
				(1) Farmer hit and destroyed it, now buried			(1) Farmer hit and destroyed it, now buried		

Property	MM-Chikuma			MM-Chikuma			MM-Norden		
Area	CR 6 & 8			CR 6 & 8			CR 8 & 23		
Well Name	CH03-MW04			CH03-South Well			NO03-MW01		
Ground Elevation	4915.5			4918.4			4923.9		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	(1)	NA	NA	NA	NA	7.4	5.6	3.9	1.7
02/24/17	(1)	NA	NA	NA	NA	8.2	5.9	3.9	2.0
03/24/17	(1)	NA	NA	NA	NA	6.0	6.0	3.9	2.1
04/28/17	(1)	NA	NA	NA	NA	5.0	5.7	3.9	1.8
05/30/17	(1)	NA	NA	NA	NA	6.0	5.5	3.9	1.6
06/23/17	(1)	NA	NA	NA	NA	4.6	5.2	3.9	1.3
07/28/17	(1)	NA	NA	NA	NA	4.2	4.3	3.9	0.4
08/22/17	(1)	NA	NA	NA	NA	4.3	4.0	3.9	0.1
09/18/17	(1)	NA	NA	NA	NA	5.1	4.5	3.9	0.6
10/27/17	(1)	NA	NA	NA	NA	6.2	5.0	3.9	1.1
11/28/17	(1)	NA	NA	NA	NA	6.0	5.2	3.9	1.3
12/18/17	(1)	NA	NA	NA	NA	6.3	5.3	3.9	1.4
01/26/18	(1)	NA	NA	NA	NA	6.3	5.6	3.9	1.7
02/23/18	(1)	NA	NA	NA	NA	8.0	5.9	3.9	2.0
03/21/18	(1)	NA	NA	NA	NA	8.1	6.0	3.9	2.1
04/26/18	(1)	NA	NA	NA	NA	8.8	6.1	3.9	2.2
05/29/18	(1)	NA	NA	NA	NA	5.1	6.0	3.9	2.1
06/22/18	(1)	NA	NA	NA	NA	5.0	5.4	3.9	1.5
09/28/18	(1)	NA	NA	NA	NA	6.0	5.0	3.9	1.1
10/23/18	(1)	NA	NA	NA	NA	6.3	5.2	3.9	1.3
11/30/18	(1)	NA	NA	NA	NA	7.0	5.6	3.9	1.7
12/19/18	(1)	NA	NA	NA	NA	6.8	5.7	3.9	1.8
01/31/19	(1)	NA	NA	NA	NA	6.8	6.0	3.9	2.1
02/28/19	(1)	NA	NA	NA	NA	6.9	6.1	3.9	2.2
03/29/19	(1)	NA	NA	NA	NA	7.1	5.9	3.9	2.0
04/26/19	(1)	NA	NA	NA	NA	6.8	5.8	3.9	1.9
05/29/19	(1)	NA	NA	NA	NA	5.9	5.5	3.9	1.6
07/09/19	(1)	NA	NA	NA	NA	5.1	5.3	3.9	1.4
08/30/19	(1)	NA	NA	NA	NA	4.7	4.6	3.9	0.7
09/30/19	(1)	NA	NA	NA	NA	5.7	4.9	3.9	1.0
10/31/19	(1)	NA	NA	NA	NA	6.4	5.2	3.9	1.3
11/22/19	(1)	NA	NA	NA	NA	6.5	5.3	3.9	1.4
12/20/19	(1)	NA	NA	NA	NA	7.7	5.8	3.9	1.9
01/29/20	(1)	NA	NA	NA	NA	8.7	6.0	3.9	2.1
02/28/20	(1)	NA	NA	NA	NA	9.4	NA	3.9	NA
	(1) Farmer hit and destroyed it, now buried								

Property	MM-Norden			MM-Norden			MM-Rittenhouse		
Area	CR 8 & 23			CR 8 & 23			HWY 85 & CR 6		
Well Name	NO03-MW02			NO03-MW03			RI01-MW01		
Ground Elevation	4923.6			4922.9			4930.6		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
02/24/17	7.4	3.9	3.5	(1)	NA	NA	(1)	NA	NA
03/24/17	6.8	3.9	2.9	(1)	NA	NA	(1)	NA	NA
04/28/17	6.5	3.9	2.6	(1)	NA	NA	(1)	NA	NA
05/30/17	7.0	3.9	3.1	(1)	NA	NA	(1)	NA	NA
06/23/17	6.0	3.9	2.1	(1)	NA	NA	(1)	NA	NA
07/28/17	5.1	3.9	1.2	(1)	NA	NA	(1)	NA	NA
08/22/17	5.4	3.9	1.5	(1)	NA	NA	(1)	NA	NA
09/18/17	5.2	3.9	1.3	(1)	NA	NA	(1)	NA	NA
10/27/17	6.6	3.9	2.7	(1)	NA	NA	(1)	NA	NA
11/28/17	6.9	3.9	3.0	(1)	NA	NA	(1)	NA	NA
12/18/17	6.9	3.9	3.0	(1)	NA	NA	(1)	NA	NA
01/26/18	7.1	3.9	3.2	(1)	NA	NA	(1)	NA	NA
02/23/18	7.4	3.9	3.5	(1)	NA	NA	(1)	NA	NA
03/21/18	7.4	3.9	3.5	(1)	NA	NA	(1)	NA	NA
04/26/18	7.6	3.9	3.7	(1)	NA	NA	(1)	NA	NA
05/29/18	6.8	3.9	2.9	(1)	NA	NA	(1)	NA	NA
06/22/18	6.3	3.9	2.4	(1)	NA	NA	(1)	NA	NA
09/28/18	6.8	3.9	2.9	(1)	NA	NA	(1)	NA	NA
10/23/18	7.0	3.9	3.1	(1)	NA	NA	(1)	NA	NA
11/30/18	7.2	3.9	3.3	(1)	NA	NA	(1)	NA	NA
12/19/18	7.2	3.9	3.3	(1)	NA	NA	(1)	NA	NA
01/31/19	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
02/28/19	7.4	3.9	3.5	(1)	NA	NA	(1)	NA	NA
03/29/19	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
04/26/19	7.2	3.9	3.3	(1)	NA	NA	(1)	NA	NA
05/29/19	6.7	3.9	2.8	(1)	NA	NA	(1)	NA	NA
07/09/19	6.2	3.9	2.3	(1)	NA	NA	(1)	NA	NA
08/30/19	6.0	3.9	2.1	(1)	NA	NA	(1)	NA	NA
09/30/19	6.4	3.9	2.5	(1)	NA	NA	(1)	NA	NA
10/31/19	6.9	3.9	3.0	(1)	NA	NA	(1)	NA	NA
11/22/19	7.0	3.9	3.1	(1)	NA	NA	(1)	NA	NA
12/20/19	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
01/29/20	7.5	3.9	3.6	(1)	NA	NA	(1)	NA	NA
02/28/20	NA	3.9	NA	(1)	NA	NA	(1)	NA	NA
				(1) Farmer hit and destroyed it, now buried			(1) Farmer hit and destroyed it, now buried		

Property	MM-Rittenhouse			MM-Rittenhouse			MM-Rittenhouse		
Area	HWY 85 & CR 6			HWY 85 & CR 6			HWY 85 & CR 6		
Well Name	RI01-MW02			RI01-MW03			RI01-MW04		
Ground Elevation	4931.4			4930.2			4927.3		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	9.9	3.9	6.0	(2)	NA	NA	(1)	NA	NA
02/24/17	10.0	3.9	6.1	(2)	NA	NA	(1)	NA	NA
03/24/17	10.2	3.9	6.3	(2)	NA	NA	(1)	NA	NA
04/28/17	9.9	3.9	6.0	(2)	NA	NA	(1)	NA	NA
05/30/17	9.0	3.9	5.1	(2)	NA	NA	(1)	NA	NA
06/23/17	9.5	3.9	5.6	(2)	NA	NA	(1)	NA	NA
07/28/17	9.3	3.9	5.4	(2)	NA	NA	(1)	NA	NA
08/22/17	9.7	3.9	5.8	(2)	NA	NA	(1)	NA	NA
09/18/17	9.8	3.9	5.9	(2)	NA	NA	(1)	NA	NA
10/27/17	9.8	3.9	5.9	(2)	NA	NA	(1)	NA	NA
11/28/17	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/18/17	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/26/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/23/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
03/21/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
04/26/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
05/29/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
06/22/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
09/28/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
10/23/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
11/30/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/19/18	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/31/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/28/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
03/29/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
04/26/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
05/29/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
07/09/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
08/30/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
09/30/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
10/31/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
11/22/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/20/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/29/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/28/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
	(2) Plugged in pipe			(2) Plugged in pipe			(1) Farmer hit and destroyed it, now buried		

Property	Aurora - McWilliams			Aurora - McWilliams			Aurora - McWilliams		
Area	CR 8 & 23			CR 8 & 23			CR 8 & 23		
Well Name	RI01-MW05			RI01-MW06			RI01-MW07		
Ground Elevation	4922.3			4917.0			4924.9		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	12.0	4.5	7.5	(1)	NA	NA	12.8	3.7	9.1
02/24/17	12.1	4.5	7.6	(1)	NA	NA	12.9	3.7	9.2
03/24/17	12.5	4.5	8.0	(1)	NA	NA	13.2	3.7	9.5
04/28/17	12.2	4.5	7.7	(1)	NA	NA	13.0	3.7	9.3
05/30/17	11.4	4.5	6.9	(1)	NA	NA	11.6	3.7	7.9
06/23/17	11.9	4.5	7.4	(1)	NA	NA	12.0	3.7	8.3
07/28/17	11.0	4.5	6.5	(1)	NA	NA	11.6	3.7	7.9
08/22/17	11.7	4.5	7.2	(1)	NA	NA	12.5	3.7	8.8
09/18/17	11.7	4.5	7.2	(1)	NA	NA	12.6	3.7	8.9
10/27/17	11.7	4.5	7.2	(1)	NA	NA	12.5	3.7	8.8
11/28/17	11.6	4.5	7.1	(1)	NA	NA	12.4	3.7	8.7
12/18/17	12.4	4.5	7.9	(1)	NA	NA	12.7	3.7	9.0
01/26/18	12.5	4.5	8.0	(1)	NA	NA	12.8	3.7	9.1
02/23/18	12.5	4.5	8.0	(1)	NA	NA	12.6	3.7	8.9
03/21/18	12.1	4.5	7.6	(1)	NA	NA	12.3	3.7	8.6
04/26/18	12.6	4.5	8.1	(1)	NA	NA	13.0	3.7	9.3
05/29/18	12.2	4.5	7.7	(1)	NA	NA	12.5	3.7	8.8
06/22/18	12.2	4.5	7.7	(1)	NA	NA	12.9	3.7	9.2
09/28/18	12.0	4.5	7.5	(1)	NA	NA	12.6	3.7	8.9
10/23/18	12.0	4.5	7.5	(1)	NA	NA	12.6	3.7	8.9
11/30/18	12.4	4.5	7.9	(1)	NA	NA	12.5	3.7	8.8
12/19/18	12.6	4.5	8.1	(1)	NA	NA	12.6	3.7	8.9
01/31/19	12.4	4.5	7.9	(1)	NA	NA	12.8	3.7	9.1
02/28/19	12.4	4.5	7.9	(1)	NA	NA	12.7	3.7	9.0
03/29/19	12.6	4.5	8.1	(1)	NA	NA	12.7	3.7	9.0
04/26/19	12.7	4.5	8.2	(1)	NA	NA	12.9	3.7	9.2
05/29/19	11.7	4.5	7.2	(1)	NA	NA	12.0	3.7	8.3
07/09/19	9.9	4.5	5.4	(1)	NA	NA	10.4	3.7	6.7
08/30/19	12.6	4.5	8.1	(1)	NA	NA	13.4	3.7	9.7
09/30/19	12.5	4.5	8.0	(1)	NA	NA	13.2	3.7	9.5
10/31/19	12.0	4.5	7.5	(1)	NA	NA	12.7	3.7	9.0
11/22/19	11.6	4.5	7.1	(1)	NA	NA	12.2	3.7	8.5
12/20/19	11.9	4.5	7.4	(1)	NA	NA	12.6	3.7	8.9
01/29/20	12.0	4.5	7.5	(1)	NA	NA	13.0	3.7	9.3
02/28/20	12.1	4.5	7.6	(1)	NA	NA	12.7	3.7	9.0
				(1) Farmer hit and destroyed it, now buried					

Property	Aurora - McWilliams		
Area	CR 8 & 23		
Well Name	RI01-MW08		
Ground Elevation	4923.7		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
01/17/17	11.1	4.9	6.2
02/24/17	11.1	4.9	6.2
03/24/17	9.4	4.9	4.5
04/28/17	9.1	4.9	4.2
05/30/17	9.7	4.9	4.8
06/23/17	8.8	4.9	3.9
07/28/17	8.3	4.9	3.4
08/22/17	8.9	4.9	4.0
09/18/17	9.3	4.9	4.4
10/27/17	9.9	4.9	5.0
11/28/17	9.7	4.9	4.8
12/18/17	10.1	4.9	5.2
01/26/18	10.3	4.9	5.4
02/23/18	10.9	4.9	6.0
03/21/18	10.2	4.9	5.3
04/26/18	11.0	4.9	6.1
05/29/18	9.7	4.9	4.8
06/22/18	9.3	4.9	4.4
09/28/18	10.0	4.9	5.1
10/23/18	10.4	4.9	5.5
11/30/18	10.7	4.9	5.8
12/19/18	10.8	4.9	5.9
01/31/19	11.1	4.9	6.2
02/28/19	11.0	4.9	6.1
03/29/19	10.8	4.9	5.9
04/26/19	10.7	4.9	5.8
05/29/19	9.8	4.9	4.9
07/09/19	8.5	4.9	3.6
08/30/19	9.7	4.9	4.8
09/30/19	10.0	4.9	5.1
10/31/19	10.1	4.9	5.2
11/22/19	9.9	4.9	5.0
12/20/19	10.8	4.9	5.9
01/29/20	11.0	4.9	6.1
02/28/20	10.7	4.9	5.8