



Legend

- | | | | |
|--|---|--|-------------------------------------|
| | Piezometers | | Marsh Area |
| | Colorado Discharge Permit System Compliance Point | | Clay Stockpile |
| | Facility Areas | | Drainage Improvement |
| | Buildings | | Underground Workings |
| | Clay-Fabric-Rock Lined Channel | | Sediment Pond Embankment |
| | Riprap Lined Channel | | Disposal Cell Tie Camp |
| | Approximate Permit Boundary | | Road |
| | Areas of Earth Structure Repair | | Treatment Residuals Management Area |
| | Areas Revegetated | | Completed in 2020 |
| | Engineered Treatment Cell Area | | |



Notes:

1. Base topography provided by Homestake Mining Company established in 1994.
2. Revegetated areas prior to 1998 provided by Golder Associates.
3. For illustrative purposes.



2020 RECLAMATION AREAS



FIGURE
2