



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

Operation Type: 🛛 Competitive/Negotiated Contract 🗌 Free Use Permit (FUP) 🔲 Common Use Area (CUA)

Date: 4/22/2021	Operation Name: Red Canyon			
Time: 9:30	Operator: Martin Marietta			
Weather: Sunny, windy	Case Number: COC-077898			
	CDRMS #: M-1985-043			
Attendees	General			
	Operation(s) are in-compliance with documentation on file			
BLM: S. Carter	\Box Yes \Box No \Box N/A			
	Operation(s) and disturbance onsite coincide with the			
	operations and access on file			
Operator(s): P. Courtney, W. Stoughton, D. Bieber	\Box Yes \Box No \Box N/A			
	Current scale certification on file			
	\Box Yes \Box No \Box N/A			
Other(s):	Annual copies of scale tickets on file			
	\Box Yes \Box No \Box N/A			

Inspection	Purpose:
------------	----------

□ Pre-Operations

 \boxtimes General \square Final

 \Box Trespass \Box Complaint

	Inspection Items	Compliant	Non- Compliant	N/A
	d of Operations Quarry, Pit, Other			
	ardrock Quarry			
i.	Operations Equipment	\boxtimes		
ii.	Processing Equipment	\boxtimes		
iii.	Blasting	\boxtimes		
	\Box Internal \boxtimes External			
iv.	Interim Benches	\boxtimes		
v.	Final Benches	\boxtimes		
vi.	Working Floor	\boxtimes		
b. Pi	t			\boxtimes
i.	Operations Equipment			
ii.	Processing Equipment			
iii.	Slopes			
c. 0	ther			\boxtimes
i.	Area of Disturbance/Excavation			
ii.	Operations Equipment			
iii.	Processing Equipment			

Inspection Items	Compliant	Non- Compliant	N/A			
2. Site Conditions						
a. Material/Waste Rock Management	\boxtimes					
b. Erosion & Stormwater Control			\boxtimes			
c. Man-made Structures			\boxtimes			
d. Weed Management			\boxtimes			
e. Safety Hazards			\boxtimes			
f. Interim Reclamation			\boxtimes			
g. Interim Management Plan			\boxtimes			
3. Housekeeping						
a. Container Management			\boxtimes			
b. Spills/Leaks Observed	\boxtimes					
c. Hazardous Substances/POL Management			Ø			
d. General Housekeeping	\boxtimes					
4. Access	-					
a. Road Management	\boxtimes					
b. Berms	\boxtimes					
c. Security	\boxtimes					
d. Signage	\boxtimes					
e. Surface Water Controls			Ø			
5. Quality Assurance/Quality Control						
a. Routine Site Conditions Monitoring			\boxtimes			
b. Air, Water, Noise, Other Monitoring			\boxtimes			
c. Monitoring Reporting			\boxtimes			
d. Regulatory Submittals			Ø			
e. Other Agency/Entity Permits			Ø			
6. Final Reclamation						
a. Exploration/Sampling Location			\boxtimes			
b. Access Roads/Trails			\boxtimes			
c. Grading			\boxtimes			
d. Revegetation						
e. Removal of Structures			\boxtimes			
f. Free of Trash			\boxtimes			
g. RGFO Solid Minerals Reclamation Standards met						

Additional Actions Necessary To be addressed by Operator

NONE

Final Notes

General:

- N/A noted in Sections because these items were not reviewed during the inspection.
- 1. Method of Operation
 - Next blast is planned for bench 6 on 4/29/21
 - In 2023, plan to start opening up bench 3, which will involve private and BLM minerals production.

2. Site Conditions

- Material from benches 8-5 going into the rock buffer.
- On bench 5, the buffer zone is on the State side and the spoils on the BLM side.
- 4. Access
 - Future action moving the disturbance line on the west to accommodate a new road, but still within the current boundary. This area will involve private surface/federal minerals. BLM will provide additional information on land status and use of split-estate mineral materials.

Date inspection shared with CDRMS: 4/26/2021 Date inspection shared with Operator: 4/23/2021







