



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

April 27, 2021

Louis Head
New Elk Coal Company, LLC
12250 Highway 12
Weston, Co 81091

**RE: Lorencito Canyon Mine, Permit C-1996-084
1st Quarter 2021 – Lorencito Canyon Mine Quarterly Sediment Pond Inspections**

Dear Ms. Head,

The Colorado Division of Reclamation, Mining and Safety (Division) has reviewed the above referenced report. The first quarter sediment pond inspection reports and the pond capacity data were received by the Division on March 29th, 2021. Sediment pond inspections were conducted by New Elk Coal Company on March 17 2021 by a qualified impoundment inspector according to the report and the report was stamped by you a Colorado Licensed Professional Engineer. This report appears to be in compliance with the applicable sections of Rule 4.05.9(14), (15) and (17).

No issues were noted on the report.

Thank you for submitting this report and for conducting the maintenance on the sediment ponds.

Sincerely,

Daniel Cunningham
Environmental Protection Specialist, DRMS

