DRMS Coal Revision Application Modification



COLORADO Division of Reclamation, Mining and Safety

Department of Natural Resources

Login

General Information

Permit Number *

C1981008

Select Revision *

If there are no options available it's because there are no open revisions of the selected type for the selected permit number

TR-104 SP Inlet Structure

Revision Application Form Selection *

TR (Technical Revision Application)

Revision Sequence *

If this does not populate, please contact your specialist to determine which sequence number to use.

104

Operation Name

New Horizon Mine

The following pages will show the contact information we have on file for this permit. If any of it is inaccurate, you will have the opportunity to correct it after this form has been submitted.

- 1. Upon submission of this form you will be presented with a link to the contact information update form.
- 2. There is a question asking about the accuracy of this information. Indicating that it is inaccurate will send an email to notify your administrator to make the appropriate changes.

Permittee Contact Information

Permittee Name

Elk Ridge Mining and Reclamation, LLC

Permittee Contact Barbara Waltz

Permittee Address 1 PO Box 33695

Permittee Address 2

Permittee City	Permittee State
Denver	СО

Permittee Zip Code 802330695

Permittee Contact Email Address

Permittee Contact Phone Number

Permitting Contact Info

Permitting Name

Tri-State Generation and Transmission Assoc., Inc

Permitting Contact Chris Gilbreath

Permitting Address 1 P.O. Box 33695

Permitting Address 2

Permitting CityPermitting StateDenverCO

Permitting Zip Code 802330695

Permitting Contact Email Address cgilbreath@tristategt.org

Permitting Contact Phone Number

3032543291

Inspection Contact Info

Inspection Name Elk Ridge Mining and Reclamation, LLC

Inspection Contact Tony Tennyson

Inspection Address 1 P.O. Box 628

Inspection Address 2

27646 West 5th Avenue

Inspection City

Nucla

Inspection State CO Inspection Zip Code 81424

Inspection Contact Email Address

ttennyson@tristategt.org

Inspection Contact Phone Number 9708241232

Is the contact information listed above correct? If it is not correct your organization's Administrator will receive an email notification. *

🖲 Yes 🔵 No

Once this form is submitted you will see a link to update contact information, which you may do if you're an admin.

Surface Area Changes

Revision

Revision Title * (?)

TR-104 SP Inlet Structure Short description

Narrative Description of Revision * (?)

TR-104 proposes a small rock lined inlet structure into the SP2 stock pond. Detailed description used for notifications

Bond Amount Change? *

🔍 Yes 💿 No

Additional Surface Disturbance? *

🔵 Yes 💿 No

Proposed Acreage Revisions

Permit Area		
Current Value	Proposed Change Value * (?)	Calculated Revised Total
402.45	0.00	402.45 This value must equal the total of all Surface and Mineral Acreage changes
Affected Area		
Current Value	Proposed Change Value * (?)	Calculated Revised Total
459.28	0.00	459.28
Disturbed Area		
Current Value	Proposed Change Value * (?)	Calculated Revised Total
360.66		

Attachments & Maps

Proposed Public Notice Attachment

Do you have attachments? *

🖲 Yes 🔵 No

Attachments				
Standard Uploads				
Document, NOT Confidential 210510 NHM TR-104 Gilbreath to Binns.pdf	243.05KB	Map, NOT Confidential		
Proof of Publication				
Confidential Uploads				
CONFIDENTIAL Document		CONFIDENTIAL Map		
Document / Map List				
New or Revised Documents / Pages * If none exist, enter NONE in the comment box below. None				
New or Revised Maps * If none exist, enter NONE in the comment None	t box below.			
Deleted Documents / Pages * If none exist, enter NONE in the comment None	t box below.			
Deleted Maps * If none exist, enter NONE in the comment None	t box below.			
Signature				

Date

Г

05/10/21

By checking this box you have thoroughly reviewed this Coal Revision form and are ready to submit this form to DRMS. I Agree