

## WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME: 3/26/2019

INSPECTOR SIGNATURE: Miranda Kawiak

INSPECTOR TITLE: Environmental Engineer

This inspection was conducted to comply with DMG Rule 4.09.1(11).

This inspection was conducted to evaluate:

☒ A. Stability of fill (quarterly inspection)

☐ B. Critical construction periods:

☐ 1. Removal of all organic material/topsoil

☐ 2. Placement of underdrainage system

☐ 3. Installation of surface drainage system

☒ 4. Placement and compaction of fill materials

☐ 5. Revegetation

NOTES:

All cover material has been piled on  
pile, ready to be dispersed across the  
refuse for at least a 2 foot coverage  
before the top soil.