



**PERMIT INFORMATION**

<b>Permit Number:</b> C-1981-037 <b>Mine Name:</b> GEC Strip Mine <b>Operator:</b> GEC Minerals, Inc. <b>Operator Address:</b> Dr W Corley 2605 Constellation Drive Colorado Springs, CO 80906	<b>County:</b> Fremont <b>Operation Type:</b> Surface <b>Permit Status:</b> Revoked <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature: (Field Issuance Only)</b>	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> June 29, 2021 <b>Inspection Start Time:</b> 08:00 <b>Inspection End Date:</b> June 29, 2021 <b>Inspection End Time:</b> 08:10	<b>Inspection Type:</b> Coal Complete Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Cloudy
<b>Joint Inspection Agency:</b>  None	<b>Joint Inspection Contacts:</b>  None
<b>Post Inspection Agency:</b>  None	<b>Post Inspection Contacts:</b>  None
<b>Inspector(s):</b>  Zach Trujillo	<b>Inspector's Signature:</b>  <b>Signature Date:</b>  7/2/21

**Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection	N - Roads
N - Availability of Records	N - Reclamation Success
N - Backfill & Grading	N - Revegetation
N - Excess Spoil and Dev. Waste	N - Subsidence
N - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	N - Support Facilities On-site
N - Hydrologic Balance	N - Signs and Markers
N - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
N - Processing Waste	N - Topsoil

**COMMENTS**

This was a complete inspection of the GEC Mine conducted by Zach Trujillo of Colorado Division of Reclamation, Mining and Safety (DRMS) on June 29, 2021. The GEC Mine was a surface mine which the Division has revoked the bond and terminated the permit. Therefore, no mine operator remains. All bond monies available to the Division were utilized by the Division for reclamation activities and no reclamation bond money remains to conduct maintenance activities. The weather was cloudy and ground conditions were dry. Temperatures during the inspection were around seventy degrees fahrenheit.

On November 13, 2018, a meeting was held between the Division and The Corley Company in regards to the Division's intentions of releasing jurisdiction to the GEC Mine Site. During this meeting, Dr. Corely, president of The Corley Company, informed the Division that it was best that the Division no longer access the site on the lands owned by The Corely Company. Based upon that meeting, this inspection was done from a limited public access point at the gated county road. The lock code that the Division once had to this gate no longer works.

The inspection for the GEC Mine was done at the locked gate along the county road to the site. A portion of Chen's Hill was visible from this location. From the gate along the county road no rills or gullies could be observed however, as documented in previous reports, the slope has multiple gullies. Overall, the northern face of Chen's Hill shows good vegetative growth due to recent precipitation. Pond A was also inspected from the county road. The pond has been previously reported as filled with sediment.

Number of Partial Inspection this Fiscal Year: 0Number of Complete Inspections this Fiscal Year: 2



Number of Partial Inspection this Fiscal Year: 0  
Number of Complete Inspections this Fiscal Year: 2