

QUARTERLY POND INSPECTION REPORT

Operator:

Bowie Resources LLC

Quarter:

Second 2021

Mine:

Bowie No. 2 Mine - C-1996-083

Inspection Date:

29-Jun-21

Pond Identification

Type of Pond

B	C	D - Gob Pile	F - New Gob	J UTL East	K UTL West
Sediment	Sediment	Sediment	Sediment	Sediment	Sediment

Status During Inspection:

Approximate Water Level

Dry	Puddle	Puddle	5945'	5848	Damp
-----	--------	--------	-------	------	------

Sediment (% remaining)

90%	90%	85%	100%	90%	80%
-----	-----	-----	------	-----	-----

Outflow (cfs)

0	0	0	0	0	0
---	---	---	---	---	---

Features

Problem	Problem	Problem	Problem	Problem	Problem
Yes/No	Yes/No	Yes/No	Yes/No	Yes/No	Yes/No

Erosional

Rills & Gulleys

No	No	No	No	No	No
----	----	----	----	----	----

Inadequate Vegetation

No	No	No	No	No	No
----	----	----	----	----	----

Outlet Channel Erosion

No	No	No	No	No	No
----	----	----	----	----	----

Burrows

No	No	No	No	No	No
----	----	----	----	----	----

Other

No	No	No	No	No	No
----	----	----	----	----	----

Structural

Differential Settling

No	No	No	No	No	No
----	----	----	----	----	----

Cracks or Slides

No	No	No	No	No	No
----	----	----	----	----	----

Seepage

No	No	No	No	No	No
----	----	----	----	----	----

Other

No	No	No	No	No	No
----	----	----	----	----	----

Appurtenant Structures

Defective Spillways

No	No	No	No	No	No
----	----	----	----	----	----

Dewatering Devices Clogged

No	No	No	No	No	No
----	----	----	----	----	----

Faulty Gates, Etc.

No	No	No	No	No	No
----	----	----	----	----	----

Other

No	No	No	No	No	No
----	----	----	----	----	----

Additional Comments

Design depth measured from pond bottom to invert of emergency spillway:

Pond B=10, C=10, D=10, J=10, K=3, F=10' TD

Pond Bottom Elevations B=5942, C=5990, D=5970, J=5846, F=5944, K=5819

Pond C was damp.

Pond B was dry.

Pond D was damp.


Pond J held between 1-2' of water.

Pond K was damp

Pond F held a puddle to as much as 1' of water.

SWMP components were inspected and found to be in good condition. No corrections necessary at this time

Name of Inspector: Tamme Bishop



Date