



STATE OF
COLORADO

Lennberg - DNR, Patrick <patrick.lennberg@state.co.us>

M-2000-080 Pioneer Farm Inspection Response

1 message

Angela Bellantoni <angela.bellantoni@pioneerco.com>

Tue, Jul 20, 2021 at 8:42 AM

To: "Lennberg - DNR, Patrick" <patrick.lennberg@state.co.us>

Cc: Russ Bartz <russ.bartz@pioneerco.com>, Dave Sawyers <dave.sawyers@pioneerco.com>

Good morning Mr. Lennberg,

Please find the attached response to the inspection report.

Feel free to contact me directly with any questions.

Angela Bellantoni Ph.D.

Permits and Licenses Specialist

angela.bellantoni@pioneerco.com

C. 719-429-8950



www.pioneerco.com

630 Plaza Dr., Ste. 150, Highlands Ranch, CO 80129



M-2000-080 Pioneer Farm Response to Inspection.pdf

1958K



July 20, 2021

Patrick Lennberg
CO Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

RE: M-2000-080 Pioneer Farm
Response to May 13, 2021 Inspection


Dear Mr. Lennberg,

Pioneer secured the services of John Kratz of Red Rock Surveying to locate and stake the corners of the permit area and affected area of the Pioneer Farm. The corner coordinates and photos of the new corner stakes are presented in Table 1.

The Technical Revision application is in progress. Exhibit C is being revised. Submission is intended for August 2021.


Please feel free to contact me directly with any questions at (719) 429-8950 or angela.bellantoni@pioneerco.com.

Respectfully submitted,


Angela M. Bellantoni, Ph.D.

Cc: Russ Bartz and Dave Sawyers, Pioneer

Table 1: Affected area corner coordinates and photos of stakes

Corner Description	Coordinates	Picture
Northeast corner	39.658830, -104.531419	 A photograph of a survey stake at the northeast corner. The stake is a black metal rod with a bright orange flag attached near the top. It is positioned in a field of dry, yellowish grass. In the background, a dirt road and a line of trees are visible under a clear blue sky.
Southeast corner	39.651508, -104.529219	 A photograph of a survey stake at the southeast corner. The stake is a black metal rod with a bright orange flag attached near the top. It is positioned in a field of dry, yellowish grass. In the background, a dirt road and a line of trees are visible under a clear blue sky.
Southwest corner	39.651854, -104.543348	 A photograph of a survey stake at the southwest corner. The stake is a black metal rod with a bright orange flag attached near the top. It is positioned in a field of green grass. In the background, a line of trees is visible under a clear blue sky.
Northwest corner	39.65912, -104.546867	 A photograph of a survey stake at the northwest corner. The stake is a black metal rod with a bright orange flag attached near the top. It is positioned in a field of green grass. In the background, a line of trees is visible under a clear blue sky.