



The BLM has conducted an inspection of your operations, which concludes whether the documented operations on file with BLM are compliant or noncompliant. Any non-compliance issues are reported in the Additional Actions Necessary section of this inspection.

Competitive/Negotiated Contract Free Use Permit (FUP) Common

Operation Type: Use Area (CUA)

| Date: June 9, 2021 | Operation Name: THE Aggregate Source | | |
|--------------------------------|--|--|--|
| Time: 08:49 | Case Number: COC- 74982 | | |
| Weather: Sunny | CDRMS #: M-1977-193 | | |
| Attendees | General | | |
| BLM:S. Carter | Operation(s) are in compliance with documentation on file | | |
| | \checkmark Yes \Box No \Box N/A | | |
| | Operation(s) and disturbance on-site coincide with the | | |
| Operator(s): Lu Toxvard | operations and access on file | | |
| | \checkmark Yes \Box No \Box N/A | | |
| Other(s): | Current scale certification on file | | |
| | \checkmark Yes \Box No \Box N/A | | |
| | Annual copies of scale tickets on file | | |
| | \checkmark Yes \Box No \Box N/A | | |
| | | | |

| Inspection | Purpose: |
|------------|----------|
|------------|----------|

□ Pre-Operations

🗹 General 🛛 Final

 \Box Complaint

□ Trespass

| Inspection Items | Compliant | Non- Compliant | N/A |
|-----------------------------------|-----------|-------------------|--------------|
| 1. Method of Operations | | | |
| Hardrock Quarry, Pit, Other | | | |
| a. Hardrock Quarry | | | |
| Operations Equipment | | | |
| Processing Equipment | | | |
| • Blasting 🔽 Internal 🗆 External | | | |
| • Interim Benches | | | |
| • Final Benches | | | |
| Working Floor | | | \checkmark |
| | | | |
| b. Pit | | | \checkmark |
| Operations Equipment | | | |
| Processing Equipment | | | |
| • Slopes | | | |
| | | | |
| c. Other | | | \checkmark |
| Area of Disturbance/Excavation | | | |
| Operations Equipment | | | |
| Processing Equipment | | | |
| 2. Site Conditions | | | |
| a. Material/Waste Rock Management | | | \checkmark |
| b. Erosion & Stormwater Control | | | \checkmark |
| c. Man-made Structures | | | |

| d. Weed Management | \checkmark | |
|----------------------------|--------------|--------------|
| e. Safety Hazards | | \checkmark |
| f. Interim Reclamation | | \checkmark |
| g. Interim Management Plan | | \checkmark |

| Inspection Items | Compliant | Non- Compliant | N/A | |
|--|--------------|-------------------|--------------|--|
| 3. Housekeeping | | | | |
| a. Container Management | | | \checkmark | |
| b. Spills/Leaks Observed | | | \checkmark | |
| c. Hazardous Substances/POL Management | | | \checkmark | |
| d. General Housekeeping | \checkmark | | | |
| 4. Access | | | | |
| a. Road Management | | | \checkmark | |
| b. Berms | | | \checkmark | |
| c. Security | | | \checkmark | |
| d. Signage | | | \checkmark | |
| e. Surface Water Controls | | | \checkmark | |
| 5. Quality Assurance/Quality Control | | | | |
| a. Routine Site Conditions Monitoring | | | \checkmark | |
| b. Air, Water, Noise, Other Monitoring | | | \checkmark | |
| c. Monitoring Reporting | | | \checkmark | |
| d. Regulatory Submittals | | | | |
| e. Other Agency/Entity Permits | | | \checkmark | |
| 6. Final Reclamation | | | | |
| a. Exploration/Sampling Location | | | \checkmark | |
| b. Access Roads/Trails | | | \checkmark | |
| c. Grading | | | \checkmark | |
| d. Revegetation | | | \checkmark | |
| e. Removal of Structures | | | \checkmark | |
| f. Free of Trash | | | \checkmark | |

Additional Actions Necessary

Non-Compliance Issues to be addressed by Operator

NONE

Additional Actions Needed

Follow-up Items to be addressed by Operator

- 1. Consider additional efforts to be more effective with weed management.
- 2. Send BLM a copy of the scale inspection, once conducted by the State of Colorado.
- 3. Send BLM the highwall inspection report from 5/2021, once received by THE Aggregate Source.
- 4. Work with BLM on bonding for Phase III.
- 5. Work with BLM regarding path forward, once out phases design is complete.

Final Notes

General Comments:

Weeds Management was the focus of this inspection, therefore if N/A is noted in Sections 2-5, it is because these items were not specifically addressed at this time.

Weeds

- All management is internal. The company purchases herbicide from Tractor Supply.
 - All treatments are applied in the manner that is required by the product label.
 - Applied once/year in the springtime.
 - Will apply for 2021 during the next couple of weeks.
 - Most common weed observed Russian Thistle turning to tumbleweeds.
 - Some Kochia observed.
 - Sent Lu a CPW link for additional weed information
 - Things to consider for more effective weed management:
 - Focus on better timing of spray, which may be more effective.
 - Consider seeding some of the areas that won't be disturbed for a few years
 - Coordinate with Fremont County for additional information

Other

- Paper scale certification paper copy shows it is good through 12/31/2021. The scales have still yet to be inspected by the State, due to the pandemic. When it does get inspected, a copy needs to be emailed to BLM.
- The highwall inspection was conducted by a 3rd party at the end of May. This report will be emailed to BLM, once THE Aggregate Source has received it.
- Bonding for Phase III is being worked on by a hired contractor of THE Aggregate Source. BLM will need to work with DRMS on this, once the contractor has completed their efforts.
- Engineering design for the out phases is about 95% completed. When complete design received, BLM, DRMS and THE Aggregate Source will meet to have a general discussion of path forward.

Date inspection shared with CDRMS:

Date inspection shared with Operator: 8/2/2021





