




MINERALS PROGRAM INSPECTION REPORT
PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Bonnie Earl Pit	MINE/PROSPECTING ID#: M-1985-014	MINERAL: Sand and gravel	COUNTY: Bent
INSPECTION TYPE: Surety-Related Inspection	INSPECTOR(S): Daniel Cunningham	INSP. DATE: August 16 2021	INSP. TIME: 16:00
OPERATOR: Leone Sand & Gravel LLC	OPERATOR REPRESENTATIVE: Mark Carrigan	TYPE OF OPERATION: 110c - Construction Regular Operation	
REASON FOR INSPECTION: Surety Related	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: \$14,000.00	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: August 26, 2021	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>N</u>	(FN) FINANCIAL WARRANTY----- <u>Y</u>	(RD) ROADS----- <u>Y</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>Y</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>Y</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>Y</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a request for release inspection conducted at the Bonnie Earl Pit site by DRMS representative DJ Cunningham. Mr. Mark Carrigan was present during the inspection to represent the Operator. This site is an active, 9.9 acre, 110c permit, currently in reclamation.

The site identification sign was posted at the mine entrance and the permit boundary were marked. The area was reclaimed at a gradient of 3H:1V or flatter in most parts. Natural vegetation has been established in 98% of the permit. There is a small area that has limited vegetation established however this accounts for less than 2% of the total permit. A Road that cuts through the permit is to be left on site.

No issues were seen on the site.

The Division is in agreement with the full release of the site.

PHOTOGRAPH



Facing West



Facing East



Small area without complete vegetation

Inspection Contact Address

Rudy Torres
Riverside Aggregates, LLC
1750 County Road HH
Lamar, CO 81052

Enclosure

CC: