

Gold Mining Company P.O. Box 191 100 North 3rd Street Victor, Colorado 80860 P 719.689.2977 F 719.689.3254 newmont.com

September 14, 2021

SENT VIA EMAIL

Mr. Patrick Lennberg Environmental Protection Specialist Colorado Department of Natural Resources Division of Reclamation, Mining, and Safety Office of Mined Land Reclamation 1313 Sherman Street, Room 215 Denver, Colorado 80203

Re: <u>Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson</u> <u>Project – Notification of Water Quality Analysis Parameter Exceedance September 14, 2021</u>

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provide the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected third quarter compliance groundwater samples from monitoring wells CRMW-5B and CRMW-5D on August 26, 2021. CC&V received analytical results for these monitoring well samples on September 10, 2021 and upon review, determined that monitoring wells CRMW-5B and CRMW-5D exceeded established numeric protection limits for fluoride. The table below lists the exceedance for the location and the associated parameter, and the attached graphs demonstrate the parameter trend for the collected data.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
CRMW-5B	8/26/2021	Fluoride	2.97	2	2
CRMW-5D	8/26/2021	Fluoride	3.51	2	2

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or <u>ronald.parratt@newmont.com</u> or myself at 719.689.4042 or <u>justin.raglin@newmont.com</u>

Sincerely, _____DocuSigned by:

Justin Kaglin

Justin Raglin Sustainability & External Relations Manager



