


**PERMIT INFORMATION**

<b>Permit Number:</b> C-1982-056 <b>Mine Name:</b> Foidel Creek Mine <b>Operator:</b> Twentymile Coal, LLC <b>Operator Address:</b> Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Active <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  Kevin Copeland
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> October 20, 2021 <b>Inspection Start Time:</b> 09:00 <b>Inspection End Date:</b> October 20, 2021 <b>Inspection End Time:</b> 12:00		<b>Inspection Type:</b> Coal Partial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  10/22/21

## Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection

R - Availability of Records

N - Backfill & Grading

N - Excess Spoil and Dev. Waste

N - Explosives

Y - Fish & Wildlife

Y - Hydrologic Balance

R - Gen. Compliance With Mine Plan

N - Other

N - Processing Waste

R - Roads

N - Reclamation Success

N - Revegetation

N - Subsidence

N - Slides and Other Damage

N - Support Facilities On-site

Y - Signs and Markers

N - Support Facilities Not On-site

N - Special Categories Of Mining

Y - Topsoil

## COMMENTS

This was a partial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division).

AVAILABILITY OF RECORDS – Rule 5.02.4(1):

Ponds inspection reports were reviewed during this inspection. No issues were noted.

GENERAL MINE PLAN COMPLIANCE:

Pads 13 and 15 are being reclaimed. The gravel has been removed and moved to new pad sites.

Pictured below is drilling at the 7E cement drop pad.



Below shows the reclamation work at pad 13 located out the 6MN road.



Below is pictured the constructed wetlands out the 6MN road. Vegetation appears to be doing well. Per the operator water quality testing has occurred above and below the ponds.



#### **ROADS – Rule 4.03**

Construction 4.03.1(3)/4.03.2(3), Drainage 4.03.1(4)/4.03.2(4), Surfacing and Maintenance 4.03.1(5) and (6)/4.03.2(5) and (6), Reclamation 4.03.1(7)/4.03.2(7):

The 7E access road has been complete. This is an improved two track. The 18 left access road to the dewatering pad will begin construction the week of the inspection per the operator.



#### **DOCUMENTS RECEIVED**

#### **OTHER (SPECIFY)**

#### **ENFORCEMENT ACTIONS/COMPLIANCE**

No enforcement actions were initiated as a result of this inspection, nor are any pending.