

October 19, 2021

ELECTRONIC DELIVERY

Mr. Elliott Russell
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

**RE: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company; Cresson Project;
Schist Island Backfill Weekly Report**

Mr. Russell,

In accordance with Amendment Thirteen Second Adequacy Review Response, comment number 73; Newmont Corporation's Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides a weekly report documenting backfilling activities completed in Schist Island during Week 6 of the project, covering the period from 9/30/21 to 10/6/21.

Please note in Section 4 of this submittal, photographic grain size analysis was submitted on the last day of September and submitted in the Week 5 report.

Should you require further information please do not hesitate to contact Katie Blake at 719-689-4048 or Katie.Blake@Newmont.com or myself at Justin.Raglin@Newmont.com.

Regards,

PT Katie Blake

Justin Raglin
Sustainability & External Relations Manager
Cripple Creek and Victor Gold Mining Company

EC: E. Russell – DRMS
M. Cunningham – DRMS
M. Crepeau – Teller County
L. Morgan – Teller County
J. Raglin – CC&V
K. Blake – CC&V

J. Ratcliff – CC&V
M. Bujenovic – CC&V
N. Townley – CC&V
J. Gillen - Geosyntec

Enc (1)
20211006 DRMS Weekly Report – Low Compaction Zone

File: S:\CrippleCreek\na.cc.admin\Environmental\New File Structure\2-
Correspondence\DNR\DRMS\2021\Outgoing

ATTACHMENT 1



Newmont CC&V


VLF 2 Phase 3 Low Compaction Zone DRMS Weekly Report

Document No: NA-CCV-SER-FORM-XX
 Function: S&ER
 Effective Date: 04/01/20
 Page No: Page 1 of XX

1. SHIFT REPORTS: .

Report Period: Thursday-Wednesday	Ambient Temperature		Weather Conditions
	High	Low	Precipitation
Date: 9/30/21 – 10/06/21	66	32	Yes, ~0.25 inch total
Observations & Comments	Progressed dumping on the 9905 elevation with a 20-foot lift. Good rock/fines mix from South Cresson, West Cresson, and Schist Island phase 2. Prepped the high compaction backfill test pads on the North end of the work area.		

2. AREA OF BACKFILL: Dump progression map with shading for the areas where backfill was placed.





Newmont CC&V

VLF 2 Phase 3 Low Compaction Zone DRMS Weekly Report

Document No: NA-CCV-SER-FORM-
XX
Function:
Effective S&ER
Date: 04/01/20
Page No: Page 2 of XX

3. ACTIVE BACKFILL AREA PHOTOGRAPH:



4. PHOTOGRAPHIC GRAIN SIZE ANALYSIS: Completed first week of each month for the month prior. For example: Completed first week of March for month of February.

N/A



Newmont CC&V

VLF 2 Phase 3 Low Compaction Zone DRMS Weekly Report

Document No: NA-CCV-SER-FORM-XX
 Function: S&ER
 Effective Date: 04/01/20
 Page No: Page 3 of XX




5. LIFT HEIGHT - NOT TO EXCEED 25FT IN LOW COMPACTION AREAS:

Lift height <= 25' ☒

Yes ☐

No

6. APPROVALS: Completed each week by assigned representative or designee.

Role	Name	Signature
Project Manager	Evan Fonger	DocuSigned by:  539D7BC87A5248E...
OR	Project Manager Designee: <u>Jeff Gaul</u>	
Tech Services/ CQA Monitor Manager	Brian Crawford	DocuSigned by:  0A16580526894D9...
OR	Tech Services Designee: <u>__ Vivek Galla __</u>	
S&ER Manager	Justin Raglin	
OR	S&ER Designee: <u>Katie Blake</u>	DocuSigned by:  5A3D013B629844B...



Schist Island Backfill Report Week 6

Norma Townley <Norma.Townley2@newmont.com>
To: "Russell - DNR, Elliott" <elliott.russell@state.co.us>

Thu, Oct 21, 2021 at 6:12 AM

Cc: "Michaela.Cunningham@state.co.us" <Michaela.Cunningham@state.co.us>, "Crepeau, Michael" <CrepeauM@co.teller.co.us>, "MorganL@co.teller.co.us" <MorganL@co.teller.co.us>, Justin Raglin <Justin.Raglin@newmont.com>, Katie Blake <Katie.Blake@newmont.com>, Jeana Ratcliff <Jeana.Ratcliff@newmont.com>, Maria Bujenovic <Maria.Bujenovic@newmont.com>, Norma Townley <Norma.Townley2@newmont.com>, Jonathan Gillen <JGillen@geosyntec.com>

Dear Mr. Russell,

Please see the attached Schist Island Backfill Report for week 6 (9/30- 10/6). If you have any questions please reach out to Justin.Raglin@newmont.com or Katie.Blake@newmont.com.

Thank you,



Norma Townley

Business Assistant | Newmont | T 719-689-4255

Newmont

Cripple Creek & Victor Gold Mine

PO Box 191

100 N.3rd Street

Victor CO 80860

www.newmont.com

T-719-689-4255

Email: Norma.Townley2@Newmont.com

Please consider the environment before printing this e-mail



20211020_SIBackfillReport_Week6.pdf
963K