


Penrose Pit

Existing Conditions

Exhibit C

Native Vegetation:
Bouteloua dactyloides,
Pascopyrum smithii,
Opuntia fragilis
Cylindropuntia imbricata

Scale
600'-0"



Legend

- Permit Boundaries (1021.4 Acres)
- 20' Existing Contours
- Existing Roadway
- Power Lines
- Unaffected Area (116 Acres)

Map By James Higgs
Fremont Paving and Redi Mix 5/17/21