## WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)
DATE/TIME: 9 26 19
INSPECTOR SIGNATURE: Manda Manseali
INSPECTOR TITLE: Enviro Manager
This inspection was conducted to comply with DMG Rule 4.09.1(11).
This inspection was conducted to evaluate:
A. Stability of fill (quarterly inspection)
B. Critical construction periods:
1. Removal of all organic material/topsoil
2. Placement of underdrainage system
3. Installation of surface drainage system
4. Placement and compaction of fill materials
5. Revegetation
NOTES: Reclamation continues Covermaterial to be spread out it top soil distributed fall 2019.

file:I:\EN\ENVIRONMENTAL\EMPIRE\INSPREP\WASTEPILEFORM.DOC