WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME:_	3/19/20
INSPECTOR S	SIGNATURE: M. Manual
	TITLE: Enviro Mage
This inspection	was conducted to comply with DMG Rule 4.09.1(11).
This inspection	was conducted to evaluate:
	A. Stability of fill (quarterly inspection)
I	3. Critical construction periods:
	1. Removal of all organic material/topsoil
	2. Placement of underdrainage system
	3. Installation of surface drainage system
	4. Placement and compaction of fill materials
	5. Revegetation
NOTES:	Pile is stabile. Pile was covered w/2' fill material in fall 2019. Reclamation to Continue in 2020.