

WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)

DATE/TIME: 9/16/21

INSPECTOR SIGNATURE: M Kawcak

INSPECTOR TITLE: Enviro Manager

This inspection was conducted to comply with DMG Rule 4.09.1(11).

This inspection was conducted to evaluate:

☒ A. Stability of fill (quarterly inspection)

☐ B. Critical construction periods:

- ☐ 1. Removal of all organic material/topsoil
- ☐ 2. Placement of underdrainage system
- ☐ 3. Installation of surface drainage system
- ☐ 4. Placement and compaction of fill materials
- ☐ 5. Revegetation

NOTES:

Pile is stable. Due to drought conditions
vegetation is struggling. Peabody may need to
inter seed some areas.