

Minerals Annual Report

Yr. 2021

MARTIN PIT 1-A

FILE NO. M-1990-140 DURAN & PEARCE CONTRACTORS

EXHIBIT C-2

S1/2 NW1/4 OF SECTION 13, T6N R9W, 6th P.M., MOFFAT CO., N.T.Y., COLORADO

- Permit Boundary
- Currently Affected (8)
- Newly Affected (9)
- Reclaim (10)
- Affected (11)
- Reclaims 2020 (12)
- Stockpile Top Soil



- NOTES:
1. THERE IS A 200 FOOT BUFFER ADJACENT TO THE OPENED POWER LINES ON THE SOUTH BOUNDARY.
 2. THERE IS A 200 FOOT BUFFER ADJACENT TO THE OPENED POWER LINE ON THE EAST BOUNDARY.
 3. THERE IS A 200 FOOT BUFFER ADJACENT TO THE SOUTH AND WEST PROPERTY LINES.
 4. THE FENCES ALONG THE EAST, WEST, AND SOUTH BOUNDARIES ARE COMBUSTIBLE FENCES.
 5. THERE ARE NO STRUCTURES OF VALUE WITHIN 200 FEET OF THE PROPERTY BOUNDARIES, OTHER THAN THOSE SHOWN.

NOTICE: ACCORDING TO COLORADO LAW, YOU MUST COME ANY LEGAL ACTION BASED ON ANY DEFECT ACTION BE COMPLETED MORE THAN TEN YEARS FROM THE DATE OF CERTIFICATION FROM HERE ON.

DURAN & PEARCE CONTRACTORS		MARTIN PIT 1-A	
FILE NO. M-1990-140		EXHIBIT C-2	
DATE	DATE	DATE	DATE
1/1/2021	1/1/2021	1/1/2021	1/1/2021
CUSTOMER: DURAN & PEARCE CONTRACTORS		LAND SURVEYORS	
HARTEN, CO. 81603		(870) 276-5013	
FAX: 276-5005			

Geospatial Imaging
Colorado Pit 1-A 2020