



**PERMIT INFORMATION**

<b>Permit Number:</b> C-1982-056 <b>Mine Name:</b> Foidel Creek Mine <b>Operator:</b> Twentymile Coal, LLC <b>Operator Address:</b> Ms Miranda Kawcak 29515 Routt County Road No. 27 Oak Creek, CO 80467	<b>County:</b> Routt <b>Operation Type:</b> Underground <b>Permit Status:</b> Active <b>Ownership:</b> Private
	<b>Operator Representative Present:</b>  None
<b>Operator Representative Signature: (Field Issuance Only)</b>  	

**INSPECTION INFORMATION**

<b>Inspection Start Date:</b> January 10, 2022 <b>Inspection Start Time:</b> 10:00 <b>Inspection End Date:</b> January 10, 2022 <b>Inspection End Time:</b> 10:30		<b>Inspection Type:</b> Aerial Inspection <b>Inspection Reason:</b> Normal I&E Program <b>Weather:</b> Clear	
<b>Joint Inspection Agency:</b>  None		<b>Joint Inspection Contacts:</b>  	
<b>Post Inspection Agency:</b>  None		<b>Post Inspection Contacts:</b>  	
<b>Inspector(s):</b>  Tabetha Lynch  Brock Bowles	<b>Inspector's Signature:</b> 		<b>Signature Date:</b>  1/19/2022

**Inspection Topic Summary**

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

N - Air Resource Protection	Y - Roads
N - Availability of Records	N - Reclamation Success
N - Backfill & Grading	N - Revegetation
N - Excess Spoil and Dev. Waste	N - Subsidence
N - Explosives	N - Slides and Other Damage
N - Fish & Wildlife	Y - Support Facilities On-site
R - Hydrologic Balance	N - Signs and Markers
R - Gen. Compliance With Mine Plan	N - Support Facilities Not On-site
N - Other	N - Special Categories Of Mining
N - Processing Waste	N - Topsoil

**COMMENTS**

This was an aerial inspection of the Foidel Creek Mine; DRMS Permit No. C-1982-056, operated by Twentymile Coal, LLC. (TC). The photos were taken by Brock Bowles on 1/10/22 and evaluated by Tabettha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division) on 1/19/22. The weather was mostly clear and the site was snow covered during the inspection.

**HYDROLOGIC BALANCE - Rule 4.05**

Drainage Control 4.05.1, 4.05.2, 4.05.3; Siltation Structures 4.05.5, 4.05.6; Discharge Structures 4.05.7, 4.05.10; Diversions 4.05.4; Effluent Limits 4.05.2; Ground Water Monitoring 4.05.13; Surface Water Monitoring 4.05.13; Drainage – Acid and Toxic Materials 4.05.8; Impoundments 4.05.6, 4.05.9; Stream Buffer Zones 4.05.18:

Ponds were mostly snow and ice covered.

**GENERAL MINE PLAN COMPLIANCE:**

As noted in the on ground December 20, 2021 inspection; multiple structures were noted by the Division at the 7E, cement drop pad, permitted by the Division under TR97. Per the operator these are temporary structures owned by the contractor for the required cement work required. However these structures are not currently accounted for within the Divisions reclamation cost estimate. Any mine related structures (include those utilized by mine contractors) regardless of the duration of use are required to be bonded. **Please address this issue within 10 days of this inspection report, dated 1/19/22.** Aerial photos of the 7E pad are provided below.

**DOCUMENTS RECEIVED****OTHER (SPECIFY)**

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2

**ENFORCEMENT ACTIONS/COMPLIANCE**

**Please address the issue at the 7E cement drop pad as noted above within 10 days of this inspection report, dated 1/19/22.**

**PHOTOGRAPHS**

7E cement drop pad, temporary structures, and fuel tanks.



7E cement drop pad, temporary structures, and fuel tanks.

Number of Partial Inspection this Fiscal Year: 5

Number of Complete Inspections this Fiscal Year: 2