

Colorado Division of Reclamation, Mining and Safety

Annual Reclamation Report for Calendar Year – 2021

West Elk Mine	C-1980-007	Mountain Coal Company, LLC
Mine Name	Permit Number	Permittee
5174 Highway 133, Somerset, CO 81434		

Address

This report, required by Rule 2.04.13, is due by February 15 of each year, or other date, as agreed upon by the Division. It should include text, discussion, and maps, at a minimum, in addition to any other reclamation monitoring data as required by the approved permit. The location of the acreage reported under each land status category and year of seeding (if applicable) should be clearly identified on a map included with the report.

Land Category	Last Year's Cumulative Total (from last year's ARR)	This Calendar Year			Cumulative Total
		Acres Added (+)	Acres Subtracted (-)		
Acreage in Active Mining Areas ¹	NA	NA	NA	=	NA

Land Category	Last Year's Cumulative Total (from last year's ARR)	This Calendar Year			Cumulative Total
		Acres Added (+)	Acres Subtracted (-)		
Acres Disturbed ²	542.99	0.00	0.00	=	542.99
Acres Backfilled and Graded	154.30	7.65	0.00	=	161.95
Acres Topsoiled	154.30	7.65	0.00	=	161.95

Acreage in Long-term Facilities ³	Last Year's Cumulative Total (from last year's ARR)	This Calendar Year			Cumulative Total
		Acres Added (+)	Acres Subtracted (-)		
Non-Permanent Facilities	388.69	7.65	0.00	=	396.34
Permanent Facilities (permitted)	0.00	0.00	0.00	=	0.00
Totals	388.69			=	396.34


Acres Seeded (permanent)	Last Year's Cumulative Total (from last year's ARR)	This Calendar Year			Cumulative Total
		Acres Added (+)	Acres Subtracted (-)		
9 Years and Less	90.89	7.65	0.00	=	98.54
10 Years and Greater	61.8	0.00	0.00	=	61.8
Totals	152.69			=	160.34

Bond Release	Last Year's Cumulative Total (from last year's ARR)	This Calendar Year			Cumulative Total
		Acres Added (+)	Acres Subtracted (-)		
Phase I Released	121.25	12.05	0.00	=	133.30
Phase II Released	67.60	50.04	0.00	=	117.64
Phase III Released	61.8	0.00	0.00	=	61.8

¹Includes pits, topsoil stripped areas in advance of pits, and spoil not backfilled and graded

²Surface Mine Acres Disturbed = B&G + Long-Term Facilities + Active Mining Areas; Underground Mine Acres Disturbed = B&G + Long-Term Facilities; Separately-permitted Loadouts = B&G + Long-Term Facilities

³Includes haul, access and light-use roads, temporary dams and impoundments; permanent dams and impoundments; diversion and collector ditches, water and air monitoring sites; topsoil stockpiles; overburden stockpiles; repair, storage and construction areas; office area, repair shops, and parking; coal stockpiles, loading, and processing areas; railroads; coal conveyors; refuse piles and coal mine waste impoundments; head-of-hollow fills; valley fills; ventilation shafts and entryways; and non-coal waste disposal area (garbage dumps and coal combustion by-products disposal areas).



LEGEND

- RECLAIMED 2021
- RECLAIMED 2020
- RECLAIMED 2019
- RECLAIMED 2018
- RECLAIMED 2017
- RECLAIMED 2016
- RECLAIMED 2015
- RECLAIMED 2014
- RECLAIMED 2013
- RECLAIMED 2012
- RECLAIMED 2011
- RECLAIMED 2010
- RECLAIMED 2009
- RECLAIMED 2008
- RECLAIMED 2007
- RECLAIMED 2005-2006
- RECLAIMED 2004
- RECLAIMED 2003
- RECLAIMED 2002
- RECLAIMED 2001
- RECLAIMED 2000
- RECLAIMED 1996

THIS DRAWING WAS PREPARED UNDER
MY DIRECT SUPERVISION & REPRESENTS
INFORMATION THAT IS ACCURATE TO
THE BEST OF MY KNOWLEDGE

FIGURE 1

MOUNTAIN COAL COMPANY, L.L.C. WEST ELK MINE
P.O. BOX 591, 5174 HWY. 133
SOMERSET, CO. 81434

MCC RECLAMATION 2021

DRAWN BY NP	SCALE 1"=1000'	DATE 1-24-2022
ACAD DWG NO. N20RP703.DWG(11x17)		

Missing Photos: E7-8&9. Due to winter weather conditions MCC was unable to get photos of the reclamation.



E7-6



E8-6



SS1-1



SS1-2



SS1-3



SS1-4



SS1-5



SS1-7



SS2-3



SS2-5



SS2-3&5 with reclaimed road