



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

February 9, 2022

Melissa Harmon
Cripple Creek & Victor Gold Mining Company
P.O. Box 191
Victor, CO 80860

**Re: Receipt of Fourth Quarter 2021 Groundwater and Surface Water Report,
Cresson Project, Permit No. M-1980-244**

Dear Melissa Harmon,

On January 28, 2022, the Division of Reclamation, Mining and Safety received the 4th Quarter 2021 Groundwater and Surface Water Report for the Cresson Project 112d-3 Hard Rock Reclamation Permit (M-1980-244), located in Teller County. A review of the submitted materials indicate the water quality concentrations within the monitoring wells are generally consistent with what has been previously reported. Monthly monitoring continues at GVMW-25 to monitor concentrations in this well.

The Division is evaluating and reviewing Technical Revision 129 concerning the establishment of points of compliance and applicable groundwater quality standards.

If you have any questions or need further information, please contact me at (303) 866-3567 x8114.

Sincerely,

Patrick Lennberg
Environmental Protection Specialist

ec: Justin Raglin, Cripple Creek & Victor Gold Mine
Michael Cunningham, DRMS
Elliott Russell, DRMS

