


Note 1: NAIP 2019 Satellite Imagery

TOTAL MINING ACRES CURRENTLY AFFECTED: 19.03±  
 MINING ACRES NEWLY AFFECTED: 0.97±  
 NUMBER OF ACRES RECLAIMED: 0.00±  
 APPROXIMATED NEW ACREAGE TO BE AFFECTED IN THE NEXT YEAR REPORT: 1.00±  
 APPROXIMATED NEW ACREAGE TO BE RECLAIMED IN THE NEXT YEAR REPORT: 0.00±  
 NO STRUCTURES WITHIN 25' OF PERMIT BOUNDARY



| DRAWING LEGEND |                                 |
|----------------|---------------------------------|
|                | Pit Tract Boundary              |
|                | Existing Permit Boundary        |
|                | Section Line                    |
|                | Edge of gravel roadway          |
|                | Fence line                      |
|                | Entry                           |
|                | Pin set by PLS 14840            |
|                | Section Monument (As Described) |



**SUMMIT ENGINEERING CO.**  
 ENGINEERS & LAND SURVEYORS  
 P: 719-589-6147 F: 719-589-6633  
 Loc: 1317 State Ave. Alamosa, CO 81101  
 Mail: P.O. Box 1897 Alamosa, CO 81101  
 www.summitengineering.co  
 summitengco@gmail.com

|  |            |              |     |
|--|------------|--------------|-----|
| <b>PROJECT</b>                         |            |              |     |
| 2021 Robins Consolidate Pit Annual Map |            |              |     |
| 5101 State Hwy. 285 Antonito, CO 81120 |            |              |     |
| Conejos County                         |            |              |     |
| Owner: Robins Construction, LLLP       |            |              |     |
| Job:                                   | 1707122CE  | Print Draft: | A   |
| Date:                                  | 04-23-2021 | Designed By: | ### |
| Drawn By:                              | KFA        | Checked By:  | SEJ |

|                   |
|-------------------|
| <b>SHEET NAME</b> |
| Annual Map        |
| <b>C-101</b>      |
| SHEET NO. 1 OF 1  |