




MINERALS PROGRAM INSPECTION REPORT

PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME: Arkansas Valley Slag (AVS)	MINE/PROSPECTING ID#: M-2021-058	MINERAL: Aggregate	COUNTY: Lake
INSPECTION TYPE: Preoperation Inspection	INSPECTOR(S): Dustin Czapla	INSP. DATE: April 7, 2022	INSP. TIME: 09:00
OPERATOR: CJK Milling Company, LLC	OPERATOR REPRESENTATIVE: Gary Slifka, Steve Craig	TYPE OF OPERATION: 112c - Construction Regular Operation	
REASON FOR INSPECTION: Pre-operation Inspection	BOND CALCULATION TYPE: Complete Bond	BOND AMOUNT: No Bond Held	
DATE OF COMPLAINT: NA	POST INSP. CONTACTS: None	JOINT INSP. AGENCY: None	
WEATHER: Clear	INSPECTOR'S SIGNATURE: 	SIGNATURE DATE: April 22, 2022	

GENERAL INSPECTION TOPICS

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>N</u>	(BG) BACKFILL & GRADING----- <u>N</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>N</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>N</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>N</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

OBSERVATIONS

This was a pre-operation inspection conducted as part of the Division of Reclamation, Mining and Safety's (Division) normal review process for a 112c application. Gary Slifka and Steve Craig, representing the Operator, were present during this inspection. Photographs are included with this report in order to document conditions observed.

The Arkansas Valley Slag (AVS) site is located approximately one mile southwest of Leadville and accessed from Hwy 24. The proposed permit area includes 56 acres of historically disturbed area. The site is largely covered by slag piles generated from past mining/smelting activities. The application proposes excavation of the slag piles down to native ground for use as construction material.

Site conditions observed during this inspection are consistent with those represented in the application.

No problems were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.

Inspection Contact Address

Gary Slifka
CJK Milling Company, LLC
PO Box 260490
Littleton, CO 80162



