

July 15, 2022

Leister Materials Limited dba Select Materials – M-1980-205

Photo description:

IMG 5523:

Proof the pond has been back filled 4' above the groundwater surface.

IMG 5534 and IMG 5543: Before and After

Proof the debris and unused fuel tank has been removed from the property.







