

Property	Martin Marietta - D&S			Martin Marietta - D&S			Martin Marietta - D&S		
Area	CR 23 & 10			CR 23 & 10			CR 23 & 10		
Well Name	DS03-MW01			DS03-MW02			DS03-MW03		
Ground Elevation	4902.0			4908.9			4914.1		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	17.7	3.6	14.1	16.3	3.4	12.9	21.5	4.1	17.4
04/26/19	14.3	3.6	10.7	16.2	3.4	12.8	21.4	4.1	17.3
05/29/19	10.3	3.6	6.7	13.7	3.4	10.3	20.4	4.1	16.3
07/09/19	9.2	3.6	5.6	12.2	3.4	8.8	19.1	4.1	15.0
08/30/19	8.6	3.6	5.0	9.7	3.4	6.3	16.9	4.1	12.8
09/30/19	8.9	3.6	5.3	10.4	3.4	7.0	17.0	4.1	12.9
10/31/19	9.7	3.6	6.1	10.4	3.4	7.0	17.2	4.1	13.1
11/22/19	10.3	3.6	6.7	11.8	3.4	8.4	17.9	4.1	13.8
12/20/19	10.7	3.6	7.1	12.6	3.4	9.2	18.7	4.1	14.6
01/29/20	11.3	3.6	7.7	13.3	3.4	9.9	19.4	4.1	15.3
02/28/20	11.3	3.6	7.7	13.4	3.4	10.0	19.5	4.1	15.4
03/18/20	11.0	3.6	7.4	13.1	3.4	9.7	19.4	4.1	15.3
04/10/20	10.4	3.6	6.8	12.2	3.4	8.8	19.1	4.1	15.0
05/14/20	9.8	3.6	6.2	10.9	3.4	7.5	18.1	4.1	14.0
06/18/20	9.0	3.6	5.4	10.7	3.4	7.3	17.6	4.1	13.5
07/29/20	10.4	3.6	6.8	10.0	3.4	6.6	17.2	4.1	13.1
08/20/20	10.7	3.6	7.1	10.4	3.4	7.0	17.5	4.1	13.4
09/30/20	8.6	3.6	5.0	10.2	3.4	6.8	16.3	4.1	12.2
10/16/20	8.7	3.6	5.1	10.2	3.4	6.8	16.2	4.1	12.1
11/30/20	10.4	3.6	6.8	12.1	3.4	8.7	18.0	4.1	13.9
12/17/20	10.4	3.6	6.8	12.1	3.4	8.7	18.1	4.1	14.0
01/15/21	11.0	3.6	7.4	12.9	3.4	9.5	18.7	4.1	14.6
02/09/21	11.1	3.6	7.5	13.0	3.4	9.6	19.2	4.1	15.1
03/04/21	11.2	3.6	7.6	13.2	3.4	9.8	19.1	4.1	15.0
04/07/21	10.3	3.6	6.7	13.0	3.4	9.6	19.0	4.1	14.9
05/21/21	8.6	3.6	5.0	12.3	3.4	8.9	18.6	4.1	14.5
06/23/21	9.2	3.6	5.6	12.0	3.4	8.6	18.1	4.1	14.0
07/29/21	8.0	3.6	4.4	10.5	3.4	7.1	17.3	4.1	13.2
08/27/21	8.6	3.6	5.0	9.3	3.4	5.9	16.3	4.1	12.2
09/22/21	9.4	3.6	5.8	9.3	3.4	5.9	16.5	4.1	12.4
10/29/21	10.3	3.6	6.7	10.7	3.4	7.3	16.3	4.1	12.2
11/17/21	10.7	3.6	7.1	11.0	3.4	7.6	16.9	4.1	12.8
12/08/21	11.0	3.6	7.4	11.7	3.4	8.3	17.5	4.1	13.4
01/27/22	11.5	3.6	7.9	12.6	3.4	9.2	18.3	4.1	14.2
02/28/22	11.3	3.6	7.7	12.9	3.4	9.5	18.7	4.1	14.6
03/21/22	11.2	3.6	7.6	13.0	3.4	9.6	18.7	4.1	14.6

Property	MM-Chikuma			MM-Chikuma			MM-Chikuma		
Area	CR 6 & 8			CR 6 & 8			CR 6 & 8		
Well Name	CH03-MW02			CH03-MW03			CH03-MW04		
Ground Elevation	4912.9			4910.9			4915.5		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	9.2	3.9	5.3	(1)	NA	NA	(1)	NA	NA
04/26/19	9.1	3.9	5.2	(1)	NA	NA	(1)	NA	NA
05/29/19	8.6	3.9	4.7	(1)	NA	NA	(1)	NA	NA
07/09/19	7.0	3.9	3.1	(1)	NA	NA	(1)	NA	NA
08/30/19	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
09/30/19	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
10/31/19	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
11/22/19	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
12/20/19	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
01/29/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
02/28/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/18/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
04/10/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
05/14/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
06/18/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
07/29/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
08/20/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
09/30/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
10/16/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
11/30/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
12/17/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
01/15/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
02/09/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/04/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
04/07/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
05/21/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
06/23/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
07/29/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
08/27/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
09/22/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
10/29/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
11/17/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
12/08/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
01/27/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
02/28/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/21/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
	(1) Farmer hit and destroyed it, now buried			(1) Farmer hit and destroyed it, now buried			(1) Farmer hit and destroyed it, now buried		

Property	Aurora - D&S Thornton			Aurora - D&S Thornton			Aurora - D&S Thornton		
Area	CR 6 & 8			CR 6 & 8			CR 6 & 8		
Well Name	DS03-MW05			DS03-MW06			DS03-MW07		
Ground Elevation	4905.1			4906.7			4912.2		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	9.6	3.4	6.2	10.8	3.6	7.2	13.1	4.3	8.8
04/26/19	9.2	3.4	5.8	11.0	3.6	7.4	13.3	4.3	9.0
05/29/19	8.5	3.4	5.1	9.8	3.6	6.2	12.2	4.3	7.9
07/09/19	7.0	3.4	3.6	8.0	3.6	4.4	10.6	4.3	6.3
08/30/19	8.5	3.4	5.1	10.4	3.6	6.8	13.5	4.3	9.2
09/30/19	8.9	3.4	5.5	10.7	3.6	7.1	13.7	4.3	9.4
10/31/19	9.1	3.4	5.7	10.3	3.6	6.7	11.9	4.3	7.6
11/22/19	9.4	3.4	6.0	10.1	3.6	6.5	11.6	4.3	7.3
12/20/19	9.8	3.4	6.4	10.4	3.6	6.8	13.3	4.3	9.0
01/29/20	10.0	3.4	6.6	10.5	3.6	6.9	14.6	4.3	10.3
02/28/20	9.9	3.4	6.5	10.3	3.6	6.7	14.4	4.3	10.1
03/18/20	9.4	3.4	6.0	10.4	3.6	6.8	14.1	4.3	9.8
04/10/20	8.1	3.4	4.7	10.4	3.6	6.8	13.6	4.3	9.3
05/14/20	9.0	3.4	5.6	9.6	3.6	6.0	13.4	4.3	9.1
06/18/20	11.0	3.4	7.6	8.8	3.6	5.2	12.7	4.3	8.4
07/29/20	12.5	3.4	9.1	9.7	3.6	6.1	11.8	4.3	7.5
08/20/20	12.2	3.4	8.8	9.9	3.6	6.3	11.9	4.3	7.6
09/30/20	13.4	3.4	10.0	10.3	3.6	6.7	13.4	4.3	9.1
10/16/20	13.3	3.4	9.9	10.6	3.6	7.0	13.4	4.3	9.1
11/30/20	(1)	NA	NA	10.0	3.6	6.4	12.0	4.3	7.7
12/17/20	(1)	NA	NA	10.1	3.6	6.5	12.1	4.3	7.8
01/15/21	(1)	NA	NA	10.0	3.6	6.4	12.0	4.3	7.7
02/09/21	(1)	NA	NA	9.9	3.6	6.3	12.3	4.3	8.0
03/04/21	(1)	NA	NA	10.0	3.6	6.4	12.6	4.3	8.3
04/07/21	(1)	NA	NA	9.7	3.6	6.1	13.3	4.3	9.0
05/21/21	(1)	NA	NA	9.6	3.6	6.0	12.6	4.3	8.3
06/23/21	(1)	NA	NA	9.2	3.6	5.6	12.7	4.3	8.4
07/29/21	(1)	NA	NA	9.2	3.6	5.6	12.7	4.3	8.4
08/27/21	(1)	NA	NA	10.1	3.6	6.5	13.1	4.3	8.8
09/22/21	(1)	NA	NA	10.3	3.6	6.7	13.3	4.3	9.0
10/29/21	(1)	NA	NA	9.8	3.6	6.2	11.9	4.3	7.6
11/17/21	(1)	NA	NA	10.0	3.6	6.4	12.4	4.3	8.1
12/08/21	(1)	NA	NA	10.0	3.6	6.4	13.2	4.3	8.9
01/27/22	(1)	NA	NA	9.9	3.6	6.3	13.6	4.3	9.3
02/28/22	(1)	NA	NA	9.8	3.6	6.2	13.6	4.3	9.3
03/21/22	(1)	NA	NA	9.9	3.6	6.3	13.7	4.3	9.4
	(1) Gone								

Property	Aurora - D&S Thornton			Aurora - D&S Thornton			MM-Norden		
Area	CR 6 & 8			CR 6 & 8			CR 8 & 23		
Well Name	DS03-MW08			DS03-MW09			NO03-MW01		
Ground Elevation	4910.3			4912.3			4923.9		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	10.2	3.6	6.6	8.6	4.0	4.6	5.9	3.9	2.0
04/26/19	9.8	3.6	6.2	8.2	4.0	4.2	5.8	3.9	1.9
05/29/19	9.3	3.6	5.7	7.4	4.0	3.4	5.5	3.9	1.6
07/09/19	7.7	3.6	4.1	5.8	4.0	1.8	5.3	3.9	1.4
08/30/19	9.4	3.6	5.8	7.4	4.0	3.4	4.6	3.9	0.7
09/30/19	9.8	3.6	6.2	7.8	4.0	3.8	4.9	3.9	1.0
10/31/19	10.0	3.6	6.4	8.0	4.0	4.0	5.2	3.9	1.3
11/22/19	10.2	3.6	6.6	8.2	4.0	4.2	5.3	3.9	1.4
12/20/19	10.7	3.6	7.1	8.9	4.0	4.9	5.8	3.9	1.9
01/29/20	11.0	3.6	7.4	9.5	4.0	5.5	6.0	3.9	2.1
02/28/20	10.5	3.6	6.9	9.5	4.0	5.5	(1)	NA	NA
03/18/20	10.1	3.6	6.5	8.8	4.0	4.8	(1)	NA	NA
04/10/20	9.6	3.6	6.0	8.3	4.0	4.3	(1)	NA	NA
05/14/20	9.2	3.6	5.6	8.4	4.0	4.4	(1)	NA	NA
06/18/20	9.0	3.6	5.4	7.6	4.0	3.6	(1)	NA	NA
07/29/20	8.8	3.6	5.2	7.4	4.0	3.4	(1)	NA	NA
08/20/20	8.9	3.6	5.3	7.1	4.0	3.1	(1)	NA	NA
09/30/20	9.3	3.6	5.7	8.1	4.0	4.1	(1)	NA	NA
10/16/20	9.5	3.6	5.9	8.1	4.0	4.1	(1)	NA	NA
11/30/20	9.3	3.6	5.7	8.6	4.0	4.6	(1)	NA	NA
12/17/20	9.4	3.6	5.8	8.8	4.0	4.8	(1)	NA	NA
01/15/21	9.4	3.6	5.8	9.0	4.0	5.0	(1)	NA	NA
02/09/21	9.4	3.6	5.8	8.9	4.0	4.9	(1)	NA	NA
03/04/21	9.4	3.6	5.8	8.8	4.0	4.8	(1)	NA	NA
04/07/21	9.2	3.6	5.6	8.6	4.0	4.6	(1)	NA	NA
05/21/21	7.5	3.6	3.9	5.6	4.0	1.6	(1)	NA	NA
06/23/21	8.2	3.6	4.6	7.1	4.0	3.1	(1)	NA	NA
07/29/21	8.0	3.6	4.4	7.0	4.0	3.0	(1)	NA	NA
08/27/21	8.4	3.6	4.8	7.2	4.0	3.2	(1)	NA	NA
09/22/21	8.8	3.6	5.2	7.5	4.0	3.5	(1)	NA	NA
10/29/21	9.0	3.6	5.4	7.9	4.0	3.9	(1)	NA	NA
11/17/21	9.1	3.6	5.5	8.0	4.0	4.0	(1)	NA	NA
12/08/21	9.2	3.6	5.6	8.2	4.0	4.2	(1)	NA	NA
01/27/22	9.5	3.6	5.9	8.6	4.0	4.6	(1)	NA	NA
02/28/22	9.5	3.6	5.9	8.8	4.0	4.8	(1)	NA	NA
03/21/22	9.4	3.6	5.8	8.8	4.0	4.8	(1)	NA	NA
							(1) Gone		

Property	MM-Norden			MM-Norden			MM-Rittenhouse		
Area	CR 8 & 23			CR 8 & 23			HWY 85 & CR 6		
Well Name	NO03-MW02			NO03-MW03			RI01-MW01		
Ground Elevation	4923.6			4922.9			4930.6		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
04/26/19	7.2	3.9	3.3	(1)	NA	NA	(1)	NA	NA
05/29/19	6.7	3.9	2.8	(1)	NA	NA	(1)	NA	NA
07/09/19	6.2	3.9	2.3	(1)	NA	NA	(1)	NA	NA
08/30/19	6.0	3.9	2.1	(1)	NA	NA	(1)	NA	NA
09/30/19	6.4	3.9	2.5	(1)	NA	NA	(1)	NA	NA
10/31/19	6.9	3.9	3.0	(1)	NA	NA	(1)	NA	NA
11/22/19	7.0	3.9	3.1	(1)	NA	NA	(1)	NA	NA
12/20/19	7.3	3.9	3.4	(1)	NA	NA	(1)	NA	NA
01/29/20	7.5	3.9	3.6	(1)	NA	NA	(1)	NA	NA
02/28/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/18/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
04/10/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
05/14/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
06/18/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
07/29/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
08/20/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
09/30/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
10/16/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
11/30/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
12/17/20	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
01/15/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
02/09/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/04/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
04/07/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
05/21/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
06/23/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
07/29/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
08/27/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
09/22/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
10/29/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
11/17/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
12/08/21	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
01/27/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
02/28/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
03/21/22	(1)	NA	NA	(1)	NA	NA	(1)	NA	NA
	(1) Gone			(1) Farmer hit and destroyed it, now buried			(1) Farmer hit and destroyed it, now buried		

Property	MM-Rittenhouse			MM-Rittenhouse			MM-Rittenhouse		
Area	HWY 85 & CR 6			HWY 85 & CR 6			HWY 85 & CR 6		
Well Name	RI01-MW02			RI01-MW03			RI01-MW04		
Ground Elevation	4931.4			4930.2			4927.3		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
04/26/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
05/29/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
07/09/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
08/30/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
09/30/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
10/31/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
11/22/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/20/19	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/29/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/28/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
03/18/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
04/10/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
05/14/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
06/18/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
07/29/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
08/20/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
09/30/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
10/16/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
11/30/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/17/20	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/15/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/09/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
03/04/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
04/07/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
05/21/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
06/23/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
07/29/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
08/27/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
09/22/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
10/29/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
11/17/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
12/08/21	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
01/27/22	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
02/28/22	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
03/21/22	(2)	NA	NA	(2)	NA	NA	(1)	NA	NA
	(2) Plugged in pipe			(2) Plugged in pipe			(1) Farmer hit and destroyed it, now buried		

Property	Aurora - McWilliams			Aurora - McWilliams			Aurora - McWilliams		
Area	CR 8 & 23			CR 8 & 23			CR 8 & 23		
Well Name	RI01-MW05			RI01-MW06			RI01-MW07		
Ground Elevation	4922.3			4917.0			4924.9		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	12.6	4.5	8.1	(1)	NA	NA	12.7	3.7	9.0
04/26/19	12.7	4.5	8.2	(1)	NA	NA	12.9	3.7	9.2
05/29/19	11.7	4.5	7.2	(1)	NA	NA	12.0	3.7	8.3
07/09/19	9.9	4.5	5.4	(1)	NA	NA	10.4	3.7	6.7
08/30/19	12.6	4.5	8.1	(1)	NA	NA	13.4	3.7	9.7
09/30/19	12.5	4.5	8.0	(1)	NA	NA	13.2	3.7	9.5
10/31/19	12.0	4.5	7.5	(1)	NA	NA	12.7	3.7	9.0
11/22/19	11.6	4.5	7.1	(1)	NA	NA	12.2	3.7	8.5
12/20/19	11.9	4.5	7.4	(1)	NA	NA	12.6	3.7	8.9
01/29/20	12.0	4.5	7.5	(1)	NA	NA	13.0	3.7	9.3
02/28/20	12.1	4.5	7.6	(1)	NA	NA	12.7	3.7	9.0
03/18/20	12.5	4.5	8.0	(1)	NA	NA	13.0	3.7	9.3
04/10/20	12.6	4.5	8.1	(1)	NA	NA	13.1	3.7	9.4
05/14/20	12.6	4.5	8.1	(1)	NA	NA	13.6	3.7	9.9
06/18/20	11.9	4.5	7.4	(1)	NA	NA	12.7	3.7	9.0
07/29/20	12.5	4.5	8.0	(1)	NA	NA	12.8	3.7	9.1
08/20/20	12.9	4.5	8.4	(1)	NA	NA	13.0	3.7	9.3
09/30/20	13.2	4.5	8.7	(1)	NA	NA	13.6	3.7	9.9
10/16/20	13.4	4.5	8.9	(1)	NA	NA	12.0	3.7	8.3
11/30/20	12.0	4.5	7.5	(1)	NA	NA	12.5	3.7	8.8
12/17/20	12.1	4.5	7.6	(1)	NA	NA	12.6	3.7	8.9
01/15/21	12.0	4.5	7.5	(1)	NA	NA	12.5	3.7	8.8
02/09/21	12.2	4.5	7.7	(1)	NA	NA	12.5	3.7	8.8
03/04/21	12.5	4.5	8.0	(1)	NA	NA	12.6	3.7	8.9
04/07/21	12.7	4.5	8.2	(1)	NA	NA	13.0	3.7	9.3
05/21/21	12.5	4.5	8.0	(1)	NA	NA	12.9	3.7	9.2
06/23/21	12.5	4.5	8.0	(1)	NA	NA	12.1	3.7	8.4
07/29/21	12.9	4.5	8.4	(1)	NA	NA	12.6	3.7	8.9
08/27/21	13.6	4.5	9.1	(1)	NA	NA	13.1	3.7	9.4
09/22/21	14.2	4.5	9.7	(1)	NA	NA	13.4	3.7	9.7
10/29/21	13.5	4.5	9.0	(1)	NA	NA	12.4	3.7	8.7
11/17/21	13.8	4.5	9.3	(1)	NA	NA	12.5	3.7	8.8
12/08/21	14.0	4.5	9.5	(1)	NA	NA	12.8	3.7	9.1
01/27/22	14.2	4.5	9.7	(1)	NA	NA	13.6	3.7	9.9
02/28/22	14.2	4.5	9.7	(1)	NA	NA	13.7	3.7	10.0
03/21/22	14.2	4.5	9.7	(1)	NA	NA	13.4	3.7	9.7
				(1) Farmer hit and destroyed it, now buried					

Property	Aurora - McWilliams		
Area	CR 8 & 23		
Well Name	RI01-MW08		
Ground Elevation	4923.7		
Date	Depth from PVC (ft)	Height of Pipe (ft)	Depth from ground (ft)
03/29/19	10.8	4.9	5.9
04/26/19	10.7	4.9	5.8
05/29/19	9.8	4.9	4.9
07/09/19	8.5	4.9	3.6
08/30/19	9.7	4.9	4.8
09/30/19	10.0	4.9	5.1
10/31/19	10.1	4.9	5.2
11/22/19	9.9	4.9	5.0
12/20/19	10.8	4.9	5.9
01/29/20	11.0	4.9	6.1
02/28/20	10.7	4.9	5.8
03/18/20	10.7	4.9	5.8
04/10/20	10.9	4.9	6.0
05/14/20	10.4	4.9	5.5
06/18/20	9.3	4.9	4.4
07/29/20	9.5	4.9	4.6
08/20/20	9.9	4.9	5.0
09/30/20	10.2	4.9	5.3
10/16/20	10.5	4.9	5.6
11/30/20	10.5	4.9	5.6
12/17/20	10.5	4.9	5.6
01/15/21	10.6	4.9	5.7
02/09/21	10.6	4.9	5.7
03/04/21	10.7	4.9	5.8
04/07/21	11.2	4.9	6.3
05/21/21	11.2	4.9	6.3
06/23/21	8.7	4.9	3.8
07/29/21	9.0	4.9	4.1
08/27/21	10.3	4.9	5.4
09/22/21	11.2	4.9	6.3
10/29/21	12.0	4.9	7.1
11/17/21	12.3	4.9	7.4
12/08/21	12.9	4.9	8.0
01/27/22	14.8	4.9	9.9
02/28/22	14.8	4.9	9.9
03/21/22	14.3	4.9	9.4