



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

August 4, 2022

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining, and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedance August 4, 2022

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected third quarter compliance groundwater samples from monitoring wells GVMW-25 on July 11, 2022, VIN-2A on July 12, 2022, CRMW-5A, CRMW-5B, CRMW-5C, CRMW-5D on July 13, 2022, WCMW-6 on July 19, 2022 and GVMW-22A on July 20, 2022. Upon review of received analytical reports, CC&V determined monitoring well GVMW-25 exceeded established numeric protection limits for cadmium, and exceeded established table value standards for sulfate. VIN-2A exceeded the established table value standards for sulfate. CRMW-5A exceeded the established table value standards and numeric protection limit for fluoride and the established table value standard for uranium. Wells CRMW-5B, CRMW-5C, CRMW-5D, WCMW-6 and GVMW-22A exceeded the established table value standard and numeric protection limit for fluoride. The table below lists these exceedances by the location and the associated parameter. The attached graphs demonstrate the parameter trend for the collected data.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
----------	-------------	-----------	--------------	------------	-----------------------------



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

GVMW-25	7-11-22	Cadmium	0.01	0.005	0.005
GVMW-25	7-11-22	Sulfate	585	---	250
VIN-2A	7-12-22	Sulfate	684	---	250
CRMW-5A	7-13-22	Fluoride	2.16	2	2
CRMW-5A	7-13-22	Uranium	0.0896	---	0.03
CRMW-5B	7-13-22	Fluoride	3.26	2	2
CRMW-5C	7-13-22	Fluoride	3.46	2	2
CRMW-5C	7-13-22	Fluoride	3.61	2	2
WCMW-6	7-19-22	Fluoride	2.10	2	2
GVMW-22A	7-20-22	Fluoride	2.10	2	2

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or ronald.parratt@newmont.com or myself at 719.851.4048 or katie.blake@newmont.com

Sincerely,

DocuSigned by:


Katie Blake

5A3D913B629844B...
Katie Blake

Sustainability & External Relations Manager


GVMW-25

—●— Cadmium — Cadmium - NPL/TVS




GVMW-25

—●— Sulfate — Sulfate - NPL/TVS




VIN-2A

Sulfate Sulfate - TVS




CRMW-5A

Fluoride Fluoride - TVS/NPL




CRMW-5A

Uranium Uranium - TVS




CRMW-5B




CRMW-5C


Fluoride Fluoride - TVS/NPL



CRMW-5D



WCMW-6



GVMW-22A

Fluoride Fluoride - TVS/NPL

