

## MINERALS PROGRAM INSPECTION REPORT PHONE: (303) 866-3567

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

MINE NAME:	MINE/PROSPECTING ID#:	MINERAL:	COUNTY:
Base Products Gravel Pit 2	M-2022-025	Aggregate	Montrose
<b>INSPECTION TYPE:</b>	INSPECTOR(S):	INSP. DATE:	INSP. TIME:
Preoperation Inspection	Dustin Czapla	August 18, 2022	15:30
OPERATOR:	<b>OPERATOR REPRESENTATIVE:</b>	<b>TYPE OF OPERATION:</b>	
BDF, LLC		112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b>	<b>BOND CALCULATION TYPE:</b>	BOND AMOUNT:	
Normal I&E Program	Complete Bond	No Bond Held	
DATE OF COMPLAINT:	POST INSP. CONTACTS:	JOINT INSP. AGENCY:	
NA	None	None	
WEATHER:	INSPECTOR'S SIGNATURE:	SIGNATURE DATE:	
Clear	Q/	August 22, 2022	
WEATHER:		SIGNATURE DATE:	

### **GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS <u>Y</u>	(FN) FINANCIAL WARRANTY <u>N</u>	(RD) ROADS <u>N</u>
(HB) HYDROLOGIC BALANCE <u>N</u>	(BG) BACKFILL & GRADING <u>N</u>	(EX) EXPLOSIVES <u>N</u>
(PW) PROCESSING WASTE/TAILING <u>N</u>	(SF) PROCESSING FACILITIES <u>N</u>	(TS) TOPSOIL <u>N</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE <u>N</u>	(RV) REVEGETATION <u>N</u>
(SM) SIGNS AND MARKERS <u>N</u>	(SP) STORM WATER MGT PLAN <u>N</u>	(RS) RECL PLAN/COMP <u>N</u>
(ES) OVERBURDEN/DEV. WASTE <u>N</u>	(SC) EROSION/SEDIMENTATION <u>N</u>	(ST) STIPULATIONS <u>N</u>
(AT) ACID OR TOXIC MATERIALS <u>N</u>	(OD) OFF-SITE DAMAGE <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

# **OBSERVATIONS**

This was a pre-operation inspection conducted as part of the Division's normal review process for 112c applications. A representative for the operator was not present. Photographs are included with this report in order to illustrate the conditions observed.

The Base Products Gravel Pit #2 is located approximately 3.25 miles northwest of Montrose and accessed from Lasalle Road. The application is for a 112c permit which proposes an affected area of 73.8 acres. The proposed permit area is currently included as part of the affected area of the Base Products Gravel Pit (M-1994-053). The area is currently undisturbed by mining operations.

The proposed area is currently utilized as irrigated farm land. The land will be reclaimed as irrigated pasture.

This inspection confirmed that conditions at the site are consistent with those presented in the application. No problems or violations were noted during this inspection.

Responses to this inspection report should be directed to Dustin Czapla at the Division of Reclamation, Mining and Safety, 1313 Sherman Street Room 215, Denver, Colorado, 80203, phone number (303) 866-3567, ext. 8188.

#### PERMIT #: M-2022-025 INSPECTOR'S INITIALS: DMC INSPECTION DATE: August 18, 2022







## **Inspection Contact Address**

Doug Flowers BDF, LLC 20965 Hwy 550 Montrose, CO 81403