




**MINERALS PROGRAM INSPECTION REPORT**  
**PHONE: (303) 866-3567**

The Division of Reclamation, Mining and Safety has conducted an inspection of the mining operation noted below. This report documents observations concerning compliance with the terms of the permit and applicable rules and regulations of the Mined Land Reclamation Board.

<b>MINE NAME:</b> Powderwash Pit No. 66	<b>MINE/PROSPECTING ID#:</b> M-2005-006	<b>MINERAL:</b> Sand and gravel	<b>COUNTY:</b> Moffat
<b>INSPECTION TYPE:</b> Monitoring	<b>INSPECTOR(S):</b> Zach Trujillo	<b>INSP. DATE:</b> September 1, 2022	<b>INSP. TIME:</b> 14:00
<b>OPERATOR:</b> Moffat County	<b>OPERATOR REPRESENTATIVE:</b> None	<b>TYPE OF OPERATION:</b> 112c - Construction Regular Operation	
<b>REASON FOR INSPECTION:</b> Normal I&E Program	<b>BOND CALCULATION TYPE:</b> None	<b>BOND AMOUNT:</b> \$0.00	
<b>DATE OF COMPLAINT:</b> NA	<b>POST INSP. CONTACTS:</b> None	<b>JOINT INSP. AGENCY:</b> None	
<b>WEATHER:</b> Clear	<b>INSPECTOR'S SIGNATURE:</b> 	<b>SIGNATURE DATE:</b> September 12, 2022	

**GENERAL INSPECTION TOPICS**

This list identifies the environmental and permit parameters inspected and gives a categorical evaluation of each. No problems or possible violations were noted during the inspection. The mine operation was found to be in full compliance with Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for the Extraction of Construction Materials and/or for Hard Rock, Metal and Designated Mining Operations. Any person engaged in any mining operation shall notify the office of any failure or imminent failure, as soon as reasonably practicable after such person has knowledge of such condition or of any impoundment, embankment, or slope that poses a reasonable potential for danger to any persons or property or to the environment; or any environmental protection facility designed to contain or control chemicals or waste which are acid or toxic-forming, as identified in the permit.

(AR) RECORDS----- <u>Y</u>	(FN) FINANCIAL WARRANTY----- <u>N</u>	(RD) ROADS----- <u>N</u>
(HB) HYDROLOGIC BALANCE----- <u>Y</u>	(BG) BACKFILL & GRADING----- <u>Y</u>	(EX) EXPLOSIVES----- <u>N</u>
(PW) PROCESSING WASTE/TAILING---- <u>N</u>	(SF) PROCESSING FACILITIES----- <u>N</u>	(TS) TOPSOIL----- <u>Y</u>
(MP) GENL MINE PLAN COMPLIANCE- <u>N</u>	(FW) FISH & WILDLIFE----- <u>N</u>	(RV) REVEGETATION---- <u>N</u>
(SM) SIGNS AND MARKERS----- <u>Y</u>	(SP) STORM WATER MGT PLAN---- <u>N</u>	(RS) RECL PLAN/COMP-- <u>Y</u>
(ES) OVERBURDEN/DEV. WASTE----- <u>N</u>	(SC) EROSION/SEDIMENTATION--- <u>Y</u>	(ST) STIPULATIONS----- <u>N</u>
(AT) ACID OR TOXIC MATERIALS----- <u>N</u>	(OD) OFF-SITE DAMAGE----- <u>N</u>	

Y = Inspected / N = Not inspected / NA = Not applicable to this operation / PB = Problem cited / PV = Possible violation cited

## **OBSERVATIONS**

This inspection was conducted by Zach Trujillo of the Colorado Division of Reclamation, Mining and Safety as part of the normal monitoring program. The Powderwash Pit No. 66 is a 112c permitted site that includes a total of 30.85 permitted acres. It is located approximately 45 miles northeast of Craig and is accessed from Moffat County Road 66. No representative of Moffat County accompanied the Division on the inspection.

The mine identification sign and affected area boundary markers are in place and in compliance with Rule 3.1.12. Topsoil and overburden piles located on site were marked with designation. Reclamation performed on site was also marked. T-posts were observed marking the perimeter boundary.



Mine ID sign.

The site as inactive at the time of the inspection. Most of mining zone No. 1 has been reclaimed. Slopes are gentle, blend smoothly and are well vegetated. The overburden and topsoil piles from mining zone No. 1 remain in place. Both stockpiles are stable and vegetated. Two basins exist in zone No. 1 on the north and south side of the topsoil pile. Both basins were dry. Zone No. 2 had large stockpiles staged within the area. No equipment or fuel was located on site.



Reclamation in zone 1.



Stockpile in zone 2.



Overburden stockpile.

Responses to this inspection report should be directed to: Zach Trujillo at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 303-866-3567 x. 8164 or via email at zach.trujillo@state.co.us.

**Inspection Contact Address**

None  
Moffat County  
P.O. Box 667  
Craig, CO 81626

Enclosure

CC: Jason Musick