



Cripple Creek & Victor
Gold Mining Company
P.O. Box 191
100 North 3rd Street
Victor, Colorado 80860

P 719.689.2977
F 719.689.3254
newmont.com

September 15, 2022

SENT VIA EMAIL

Mr. Patrick Lennberg
Environmental Protection Specialist
Colorado Department of Natural Resources
Division of Reclamation, Mining, and Safety
Office of Mined Land Reclamation
1313 Sherman Street, Room 215
Denver, Colorado 80203

Re: Permit No. M-1980-244; Cripple Creek & Victor Gold Mining Company ("CC&V"); Cresson Project – Notification of Water Quality Analysis Parameter Exceedance September 15, 2022

Dear Mr. Lennberg,

In accordance with Rule 3, Section 3.1.7 (9) of the Mineral Rules and Regulations of the Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations (Rules), the Cripple Creek and Victor Gold Mining Company (CC&V) hereby provides the Division of Reclamation, Mining, and Safety (Division) with a formal notification of water quality parameter exceedances.

CC&V collected third quarter compliance groundwater samples from monitoring well SGMW-6B on August 24, 2022. Upon review of received analytical reports, CC&V determined monitoring well SGMW-6B exceeded established the numeric protection limits and the table value standards for fluoride and manganese, and exceeded the table value standards for beryllium and sulfate. The table below lists these exceedances by the location and the associated parameter. The attached graphs demonstrate the parameter trend for the collected data.

Location	Sample Date	Parameter	Value (mg/L)	NPL (mg/L)	Table Value Standard (mg/L)
SGMW-6B	8-24-2022	Beryllium	.0546	---	.004
SGMW-6B	8-24-2022	Fluoride	7.07	2	2
SGMW-6B	8-24-2022	Manganese	7.42	3	.05
SGMW-6B	8-24-2022	Sulfate	1060	---	250

Should you require further information please do not hesitate to contact Ronald Parratt at 719.689.4019 or ronald.parratt@newmont.com or myself at 719.851.4048 or katie.blake@newmont.com

Signed by:

Katie Blake


5A3D013B629844B...
Katie Blake

Sustainability & External Relations Manager
Cripple Creek and Victor Gold Mining Company

EC: P. Lennberg
M. Cunningham
K. Blake
R. Parratt
B. Doering
N. Townley


SGMW-6B

—●— Beryllium — Beryllium - TVS




SGMW-6B

Fluoride Fluoride - TVS/NPL



SGMW-6B

—●— Manganese — Manganese - NPL — Manganese - TVS



SGMW-6B

Sulfate Sulfate - TVS

