List of Appendices

App.	Vol.	Description
2-1	1	South Lease Exploration Plan (TR04 - #85-03)
2-2	1	South Lease Exploration Plan (MR10 - #85-03)
3-1	1	List of Owners, Officers and Directors
3-2	1	Rule 2.03.4(4) Information
5-1	1	Antiquities inventory for GEX-C010
5-2	1	Colorado Historical Society File Search 11/30/81
5-3	1	Colorado Historical Society File Search 10/29/81
5-4	1	Cultural Resource Inventory Report CRDA 2 & 3, 10/30/84
5-5	1	Cultural Resource Inventory Report - 2 West Portals and power line, 5/5/92
5-6	1	Cultural Resource Inventory Report - 2 West Portals and power line, 6/25/92
5-7	1	Cultural Resource Inventory Report - Cameo Borrow Area No. 1, 8/28/93
6-1	2	Borehole Logs and Gradation Graphs
6-2	2	Chemical and Physical Characteristics of Coal Processing Waste
6-3	2	Drill Hole Logs
7-1	2	Hydrology of Roadside Mining Corporation Operations
7-2	2	Aquifer Characteristics of the Rollins Sandstone and the Cameo Coal Zone
7-3	2	Hydrologic Characterization of Rollins Sandstone
7-4	2	Compliance Order on Consent – Alternate Water Supply
9-1	2	Soils Analysis (SS1-SS12)
9-2	2	Soils Analysis (15-28)
9-3	2	Soils Analysis (Roadside North & South Portals)
9-4	2	Soils Analysis (CRDA 2 & CRDA 3)
9-5	2	Soils Analysis - Miscellaneous
9-6	2	NRCS Soil Information
9-7	2	Soils Analysis - 2002 Reclamation Project
10-1	3	Baseline Vegetation Survey
10-2	3	Threatened and Endangered Species
10-3	3	Threatened and Endangered Species - 1996
10-4	3	New Greasewood Reference Area, 1999
11-1	3	Biological Opinion and Recovery Agreement

12-1	3	General Mining Order No. 1	
12-2	3	1999 Resource Recovery and Protection Plan	
13-1	3	Roadway Drainage Cross-Drainage Culvert Calculations, and Dip Section Creek	ons-Coal
13-2	3	Sediment Control Calculations	
13-3	3	Alternate Drainage	
13-4	4	Geotechnical Investigations: Cameo & Roadside Mines Refuse Pile	
13-5	4	Coal Waste Stability Study Cameo Refuse Piles 2 & 3 and Rocky Moun Geotechnical Figures 4 & 5	tain
13-6	4	Geotechnical Investigation: Pond 12	
13-7	4	Public Service of Colorado - Drainage South of Haul Road 5	
14-1	5	BLM-Proposal for Revegetation Research Project	
14-2	5	Reclamation Plan Cost Estimate	
14-3	5	Reclamation Costs, Cameo Refuse Disposal Areas Nos. 2 and 3, and oth Areas	ıer
14-4	5	Other Reclamation Cost Estimates	
14-5	5	Affected Land Owners Reclamation Approval	
14-6	5	Final Reclamation Drainage Design	
14-7	5	Revegetation Evaluation - Diversity	
14-8	5	Slope Stability Analysis - Roadside South Portal	
14-9	5	Approximate Original Contour Variance	
14-10	5	Steep Rock Slope Retention	
14-11	5	Re-Evaluation of Revegetation Success Standards – 2010	
14-12	5	Soils Loss Comparison – South Portal & North Decline	
14-13	5	Soils Loss Comparison - North Portal, CRDAs & CBAs	
14-14	5	April 2016 ERT Investigation – Huddleston-Berry/Fugro Consultants R	eports
14-15	5	August 2016 ERT Investigation – Huddleston-Berry/Fugro Consultants	Reports
15-1	5	Mesa County Dept of Planning & Economic Development South Portal Minor Site Plan	
15-2	5	Alternative Land Use, Halliburton Documents & Approvals, UTL	
15-3	5	Alternative Land Use, Cameo Sports Shooting & Education Complex Documents and Approvals, North Portal Area	
16-1	5	Air Pollution Permits	
17-1	5	Material Safety Data Sheets	
17-2	5	Salinity Report	
RN7		viii	Rev 10/17