



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

October 18, 2022

Daniel Takami  
Grand Island Resources LLC  
12567 West Cedar Dr.  
Lakewood, CO 80228

**Re: Division Comment, Second (2<sup>nd</sup>) Quarter 2022 Groundwater and Surface Water Monitoring Report; Cross Gold Mine, Permit No. M-1977-410**

Dear Mr. Takami,

On October 6, 2022, the Division of Reclamation, Mining and Safety (Division/DRMS) received your responses to the Division's request for additional information, dated September 6, 2022, for the 2<sup>nd</sup> Quarter 2022 Groundwater and Surface Water Monitoring Report for the Cross Gold Mine. After review of the submission the Division has the following comment.

At this time the Division does not consider the 2<sup>nd</sup> Quarter 2022 monitoring data to qualify as one quarter of baseline monitoring because the data was not collected in a manner consistent with the approved methods described in TR-10.

If you have any questions or need further information, please contact me at (303) 866-3567 x8114, or by email at [patrick.lennberg@state.co.us](mailto:patrick.lennberg@state.co.us).

Sincerely,

Patrick Lennberg  
Environmental Protection Specialist

cc: Jared Ebert; DRMS

ec: Daniel Takami, Grand Island Resources LLC  
Richard Mittasch, Grand Island Resources LLC

