## WILLIAMS FORK MINE WASTE PILE INSPECTION FORM

PILE I.D. NO. 1211-CO-09-01370-01 (SURFACE WASTE PILE)

PILE I	.D. NO. 1211-CO-09-01370-02 (OLD NO. 9 EXCAVATION)
DATE/TIME:_	9/12/2022
INSPECTOR S	GIGNATURE: Mirarda Kawcak
INSPECTOR T	TITLE: <u>Minarda Kawcak</u> TITLE: <u>Enviro</u> , <u>Manager</u>
This inspection	was conducted to comply with DMG Rule 4.09.1(11).
This inspection	was conducted to evaluate:
<u> </u>	A. Stability of fill (quarterly inspection)
E	3. Critical construction periods:
	1. Removal of all organic material/topsoil
	2. Placement of underdrainage system
	3. Installation of surface drainage system
	4. Placement and compaction of fill materials
	5. Revegetation
NOTES:	Site vegetation is sporse, but stable.
	Site grading & soil is stable