



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

October 26, 2022

Ms. Alyson Boye
Cripple Creek & Victor Gold Mining Company
P.O. Box 191
Victor, CO 80860

**Re: Additional Information Required, Grassy Valley Surface and Groundwater Monitoring
Submission; Permit No. M-1980-244**

Dear Ms. Boye:

On October 24, 2022, the Division of Reclamation, Mining and Safety (Division/DRMS) received the sample results for surface water and groundwater samples collected in response to the Division's problem citation dated September 30, 2022. After review of the submission the Division has additional items that need to be addressed or clarified.

1. Please provide a map that clearly shows each sample location, as required in item 2c.
2. Please provide the field sheet(s) for each of the sample locations, as required in item 2c.
3. It does not appear the Operator collected any QA/QC samples as was requested in item 2c. Please provide the results of the QA/QC samples. If no QA/QC samples were collected, please provide an explanation.
4. Please compare the sample results for GV-06 to the water quality standards listed for the CDPHE stream classification for this segment of Grassy Creek, identifying any parameters that exceed the stream standards.

Please respond to these items within 30 days of the date on this letter, by **November 25, 2022**. The Division reserves the right to further supplement this document with additional items and details as necessary.

If you need additional information or have any questions, please contact me by telephone at 303-866-3567 x8114, or by email at patrick.lennberg@state.co.us.

Sincerely,

Patrick Lennberg
Environmental Protection Specialist



cc: Katie Blake, Cripple Creek & Victor Gold Mine
Ronald Parratt, Cripple Creek & Victor Gold Mine
Amy Eschberger, Division of Reclamation, Mining & Safety
Michael Cunningham, Division of Reclamation, Mining & Safety
Jared Ebert, Division of Reclamation, Mining & Safety