McAtee Construction Company Permit # M-1986-147 Harley Pit #1 2022 Annual Report

Notes:

Please refer to the 2022 Annual Report Map for location of the areas of disturbance in the mine. We continued to remove material from stockpiles and the mined area. No reclamation is required at this time. The markings and colors noted in this text references areas shown on the map.

(9) Mining continued on the south mine face in the stripped area this year on approximately 0.27 acres (cross hatched). But no new area was affected. There are 4.5 acres currently stripped (yellow), we may strip addition area, if needed, south of the current mining face. There is 17.8 acres of stockpile area in use (orange).

(10) No reclamation is required next year, the reclaimed area (green) continues to be monitored and is growing as expected.

(14) Weed control was done in June 2022 this year in accordance with the Weed Management Plan on the perimeter of the mine and spot work was done on the mine floor areas and roadways. Escort and 2-4-D was applied as needed. Weed control will continue in 2023.

(19) The current bond is \$117,150 and was found to be adequate in an August 25, 2021 normal inspection report.