

NOTES:
-The entire acreage of the site has been disturbed, with the exception of some native vegetation remaining along the fencelines and property boundaries
-Topsoil is in place along roads and banks, not stockpiled



South Platte River

Pump house
/ building structure.

Worthing property
16.37 acres
backfilled in 2017

(troll road)

Mining permit boundary

French Drain
(Underground)

Southern and eastern walls of the north cell
of the reservoir were graded in 2020

Reseeding occurred in dashed line
in 2020

South Cell
Reservoir

15 acres
seeded and
hydromulched
March 2016
and 2.2 acres
reseeded in 2020

Approximately
53.22 acres covered
in reservoir water

Approximately 68.22
acres total

85

E 126th Ave

E 124th Ave



TITLE Brannan Sand and Gravel Company, LLC Pit 29 2022 Mining Annual Report Colorado Division of Reclamation, Mining and Safety Permit M1980-183			
SIZE	CAGE CODE	DWG NO	REV
SCALE 1"=500'		SHEET 1 of 1	